

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24080084/ANP3E2**Date:** 27/09/2024REFERENCEInsured/Claimant: RODRIGUES GERARD WILLIAM
Date of Loss: 03/08/2024Policy No: 2070138876
Nature of Claim: OD Claim No: 2108922227SGDESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV1028U	Engine No:	CZDC00062
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF36L1122974
Reg. Date:	30/09/2020 (Man. Year: 2020)	Odometer:	72588 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$137,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,484.00	7,153.76	7,330.24	50.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,182.00	5,992.00	3,190.00	34.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,666.00	13,145.76	10,520.24	44.45
- Excess (S\$)	900.00	900.00	0.00	0.00
(S\$)	22,766.00	12,245.76	10,520.24	46.21
+ GST 9.00/9.00% (S\$)	2,048.94	1,102.12	946.82	46.21
Nett Amount (S\$)	24,814.94	13,347.88	11,467.06	46.21

INSPECTION

Date of Assignment: 06/08/2024

Date Inspected: 08/08/2024 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,960.00 FS	*- FS
2	2		*REAR BUMPER DAMPING - LH / RH	Not Necessary	48.00 FS	*- FS
3	1		*REAR BUMPER CROSS REINFORCEMENT - CENTER	Not Necessary	121.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	573.00 FS	*- FS
5	1		*REAR BUMPER GRILLE - RH	Not Necessary	191.00 FS	*- FS
6	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	80.00 FS	*- FS
7	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	1,278.00 FS	*1,022.40 FS
8	1		*REAR DOOR - RH	Dented	3,215.00 FS	*2,572.00 FS
9	1		*REAR DOOR OUTER SEAL - RH	Necessary	168.00 FS	*134.40 FS
10	1		*REAR DOOR CATCH - RH	Not Necessary	150.00 FS	*- FS
11	1		*REAR DOOR HINGE UPPER PART - RH UPPER	Not Necessary	23.00 FS	*- FS
12	1		*REAR DOOR HINGE LOWER PART - RH LOWER	Not Necessary	59.00 FS	*- FS
13	1		*REAR DOOR HINGE UPPER PART - RH LOWER	Not Necessary	55.00 FS	*- FS
14	1		*REAR DOOR HINGE LOWER PART - RH UPPER	Not Necessary	60.00 FS	*- FS
15	1		*REAR DOOR LOWER COVER - RH	Cut	413.00 FS	*330.00 FS
16	1		*FRONT DOOR - RH	Dented	3,215.00 FS	*2,572.00 FS
17	1		*FRONT DOOR OUTER SEAL - RH	Necessary	206.00 FS	*164.80 FS
18	1		*FRONT DOOR CATCH - RH	Not Necessary	150.00 FS	*- FS
19	1		*FRONT DOOR LOWER COVER - RH	Cut	438.00 FS	*350.40 FS
20	1		*REAR ALUMINIUM RIM - RH	Not Necessary	1,576.00 FS	*- FS
21	1		*REAR ALUMINIUM RIM RUBBER VALVE - RH	Not Necessary	5.00 FS	*- FS
22	1		*SUNDRIES	Necessary	500.00 FS	*7.76 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

14,484.00

7,153.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	560.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND RHS FRONT AND REAR DOORS. TO REPAIR RHS REAR FEBDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,150.00	1,500.00
4	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS FRONT AND REAR DOORS, BOTH REAR WHEEL ARCH TRIM AND RHS FRONT AND REAR DOOR LOWER COVERS	New	4,300.00	3,000.00
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$)			9,182.00	5,992.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >