



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI24080086/Anp3e2
(BUDGET DIRECT INSURANCE) Date: 10/12/2024
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE SINGAPORE 239924 Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 1208R	Veh. Inspected	SKZ 5103L
Policy No.	P10931243R00	Coverage	0
Claim No.	C10030927 / JK	Excess	\$0.00
Assign From	JANICE KOH	Assign Date	05/08/2024

2. Vehicle Details

Make & Model	TOYOTA HARRIER	C.C	1986
Engine No.	3ZRB688405	Year of Reg.	26/01/2016
Chassis No.	ZSU600066336	Colour	WHITE
Odometer	109112 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/65 R17	YOKOHAMA	6
L/H Front Tyre	225/65 R17	YOKOHAMA	6
R/H Rear Tyre	225/65 R17	YOKOHAMA	6
L/H Rear Tyre	225/65 R17	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/08/2024	Inspection Date	06/08/2024
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days