

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

_					
Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL	INSURANCE LTD	Ref:	CS3/FCI24080088/Kvp3e2	
	16 RAFFLES QUAY		Date:	16/08/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
1.	. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	SHD 4509H	Veh. Inspected	GBF 5398P	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24006822MFCT	Excess	\$0.00	
	Assign From	AINI	Assign Date	05/08/2024	
2. Vehicle Details					
	Make & Model	NISSAN NV200 (M)	C.C	1461	
	Engine No.	K9KC400D056001	Year of Reg.	10/12/2016	
	Chassis No.	VSKYBAM20Z0133467	Colour	SILVER	
	Odometer	108751 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	175/70 R14	YOKOHAMA	8	
	L/H Front Tyre	175/70 R14	YOKOHAMA	8	
	R/H Rear Tyre	175/70 R14	BRIDGESTONE	8	
	L/H Rear Tyre	175/70 R14	BRIDGESTONE	8	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	General Information				
	Accident Date	01/08/2024	Inspection Date	07/08/2024 (10:06)	
	Survey held at	AESOP AUTO-CARE PTE LTD BLK 5032 #01-299/301 ANG MO KIO IND PARK 2 SINGAPORE 569535			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$26,000.00 E)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000					
5b.	, ,				
EST	IMATED NORMAL PI	ERIOD FOR REPAIR: 6 Working Days		_	

KSC

KENNETH KONG SENG CHEONG