



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080090/Dqh3
75 BRAS BASAH ROAD	Date:	22/08/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBM 4306A	Veh. Inspected	GBG 4857H
Policy No.	-	Coverage	0
Claim No.	MT/1287690-002	Excess	\$0.00
Assign From	ASTER QUEK	Assign Date	06/08/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KD2651364	Year of Reg.	22/08/2017
Chassis No.	KDH2010206263	Colour	WHITE
Odometer	63080 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	FALKEN	5
L/H Front Tyre	195 R15C	FALKEN	5
R/H Rear Tyre	195 R15C	FALKEN	5
L/H Rear Tyre	195 R15C	FALKEN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/07/2024	Inspection Date	07/08/2024 (10:30)
Survey held at	OUTCARS AUTO - 5035 ANG MO KIO INDUSTRIAL PARK 2, #01-371 SINGAPORE 569538		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days