8/28/24, 9:09 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24080091/KVP3E2

F083K699B48B20A

Date: 28/08/2024

REFERENCE

No .

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1000659019 **Claimant Vehicle** SGJ58Z Insured Vehicle No: SKE9166P

Date of Loss: 02/08/2024 Nature of Claim: TP Claim No: 369194

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGJ58Z

BMW X3, 2.0 SDRIVE 20I ADAPTIVE HL LED FL Make & Model: Engine No:

Reg. Date: 24/06/2021 (Man. Year: 2021) Chassis No: WBATS720109G42624

Colour: White Odometer: 51852 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

245/50 R19 245/50 R19 Front Tyre Size: Rear Tyre Size: Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,232.54	3,916.14	2,316.40	37.17
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,800.00	740.00	1,060.00	58.89
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,032.54	4,656.14	3,376.40	42.03
	Approved Total (Overridden) (S\$)		3,700.00		
	Nett Amount (S\$)	8,032.54	3,700.00	4,332.54	53.94

INSPECTION

Date of Assignment: 06/08/2024

Colour Vibe Pte. Ltd (HQ)

Date Inspected: 07/08/2024 Inspected At: 176 Sin Ming Drive #05-16 Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

8/28/24, 9:09 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Aug 2024)

Parts: M1-SUV BMW X3 2.0 SDRIVE 20I ADAPTIVE HL LED FL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGJ58Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	2,165.40 F	*1,562.95 FL
2	1		*REAR BUMPER LOWER TRIM	Mtg Cracked	473.15 F	*473.15 FL
3	1		*REAR, RIGHT BUMPER MOUNTING BRACKET	Cracked	275.25 F	*275.25 FL
4	1		*REINFORCE BUMPER REAR LOWER PART	Serviceable	224.55 F	*- FL
5	1		*REAR RADAR SENSOR RH	Mtg Cracked	1,565.45 F	*1,280.00 FL
6	1		*REAR TAIL LAMP, BODY	Serviceable	680.40 F	*- FL
7	1		*REAR FENDER TRIM	Distorted	345.00 F	*205.50 FL
8	1		*REAR SENSOR	Cut	473.34 F	*325.40 FL
9 E-Era	6	nart S-SncA	*FENDER RIVET ett. L=ListItemDisc.	Not Necessary	30.00 FS	*- FS
1 -110	111011136	part. 0-opciv	ett. E-Eistitembise.	Sub Total (S\$)	6,232.54	4,122.25
			- List Item Discount	on L Items 0.00/5.00% (S\$)	0.00	206.11
				Total Parts (S\$)	6,232.54	3,916.14
			Report was unsubmitted durin	g this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE, REPLACED DAMAGE LAMPS & CHECK WIRIN	I G New	200.00	20.00
2	TO REMOVE & REFIT PDC SENSOR	New	200.00	60.00
3	TO PANEL BEAT / RE-ALIGNMENT	New	800.00	300.00
4	TO SPRAY PAINTING	New	400.00	360.00
5	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	200.00	0.00
		Gross Labour Cost (S\$)	1,800.00	740.00
	Report was unsubmitte	d during this print-out.		

< END OF ESTIMATES >