8/27/24, 4:34 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24080094/ENP3M4

27/08/2024 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MAB00158 **Claimant Vehicle** SHB2003Z **Insured Vehicle No:** SMF4922C

No:

Date of Loss: 03/08/2024 Nature of Claim: ΤP Claim No: M2404378

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB2003Z

G4LLPS265118 Make & Model: HYUNDAI SX2 KONA, 1.6 GDI HEV (A) Engine No:

Reg. Date: 29/12/2023 (Man. Year: 2023) Chassis No: KMHHB811VRU037148

Colour: Yellow Odometer: 76994 km

Engine Capacity: 1580 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Good Yes **Engine Modification:** Pre-accident Condition: Good Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 205/65R16 Rear Tyre Size: 205/65R16 Front Left Side: Rear Left Side: Kumho 6 mm Kumho 6 mm Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,291.06	1,346.34	2,944.72	68.62
Miscellaneous Items		12.00	12.00	0.00	0.00
Labour		2,165.00	1,465.00	700.00	32.33
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	6,468.06	2,823.34	3,644.72	56.35
	+ GST 9.00/9.00% (S\$)	582.13	254.10	328.03	56.35
	Nett Amount (S\$)	7,050.19	3,077.44	3,972.75	56.35

INSPECTION

ComfortDelGro Engineering Pte Ltd (Loyang) Date of Assignment: 05/08/2024 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 06/08/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

CHEN TSUE YEE Manager: **HUEY YON** Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$2,823.33

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Aug 2024)

Parts: 192 HYUNDAI SX2 KONA 1.6 GDI HEV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB2003Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ASSY BUMPER UPPER	Crushed	375.30 FL	*375.30 FL
2	1		*COVER ASSY BUMPER LOWER	Crushed	188.14 FL	*188.14 FL
3	1		*SKID PLATE ASSY BUMPER REAR	Crushed	537.48 FL	*537.48 FL
4	1		*BEAM- BUMPER REAR	Deformed	582.00 FL	*582.00 FL
5	1		*PANEL ASSY TAIL GATE	Repair	2,164.00 FL	*- FL
6	1		*TAIL LAMP LH	Not Necessary	935.40 FL	*- FL
7	1		*EMBLEM- KONA	Not Necessary	97.00 FL	*- FL
8	1		*EMBLEM- H	Not Necessary	47.00 FL	*- FL
9	1		*TAIL GATE ZIG STICKER	Not Necessary	40.00 FS	*- FS
10	1		*TAIL GATE COMFORTDELGRO & TE NUMBER STICKER	Not Necessary	80.00 FS	*- FS
11	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
12	1		*REAR REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	5,276.32	1,682.92
			- List Item Discount on L Items	s 20.00/20.00% (S\$)	985.26	336.58
				Total Parts (S\$)	4,291.06	1,346.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount		
Mis	Miscellaneous Items						
1	1	OD/TP Case (Insurer)		12.00	12.00		
			Sub Total (S\$)	12.00	12.00		

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,150.00	760.00
2	SPRAY PAINTING	New	800.00	560.00
3	CHECK LIGHTING AND WIRING	New	60.00	30.00
4	REMOVE.REFIX REVERSE SENSOR	New	60.00	20.00
5	TOWING FEE	New	95.00	95.00
		Gross Labour Cost (S\$)	2,165.00	1,465.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >