

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24080095/RNP3E2**Date:** 04/10/2024REFERENCE

Insured/Claimant: TOH HUANG MENG (ZHUO HANMING)

Policy No: MPC24A00131100

Date of Loss: 02/08/2024

Nature of Claim: OD

Claim No: DMPC2401011H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMY533T**

Make & Model: LEXUS UX200, 2.0 (A)

Engine No: M20AN257274

Reg. Date: 10/02/2021 (Man. Year: 2020)

Chassis No: JTHY35BH802035124

Colour: Grey

Odometer: 50021 km

Engine Capacity: 1987 cc

Market Value/New Car Price: S\$143,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size: 225/50 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,830.58	3,227.35	2,603.23	44.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,896.00	4,019.60	2,876.40	41.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,726.58	7,246.95	5,479.63	43.06
+ GST 9.00/9.00% (S\$)	1,145.39	652.23	493.16	43.06
Nett Amount (S\$)	13,871.97	7,899.18	5,972.79	43.06

INSPECTION

Date of Assignment: 06/08/2024 Present Location: Borneo Motors (S) Pte Ltd (Pandan)

Date Inspected: 07/08/2024 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent

Estimated Period of Repair: 5.0 days Singapore 128462

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2024)
Parts:	M1-SUV	LEXUS UX200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY533T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	L42611-76310	*WHEEL DISC	Scratched	4,002.80 FL	*4,002.80 FL
2	1	L52113-76902	*EXTENSION FR	Repair	527.90 FL	*- FL
3	1	L89348-12140 B5	*RETAINER ULTRASONIC	Not Necessary	57.90 FL	*- FL
4	2	L75895-53010	*TAPE MOULDING NO.1	Not Necessary	111.00 FL	*- FL
5	1	L16563-24020	*SEAL RADIATOR TO	Not Necessary	55.60 FL	*- FL
6	1	L52126-76050	*BRACKET FOG LAMP	Not Necessary	84.10 FL	*- FL
7	1	L81482-76070	*COVER FOG LAMP LH	Not Necessary	189.20 FL	*- FL
8	1	L52411-76010	*GUARD FR BUMPER	Not Necessary	537.10 FL	*- FL
9	1	L52116-76020	*SUPPORT FR BUMPER	Not Necessary	120.60 FL	*- FL
10	4	L75392-35220	*RETAINER OUTSIDE	Necessary	22.40 FL	*22.40 FL
11	1	L53802-76030	*FENDER SUB-ASSY FR	Not Necessary	2,035.50 FL	*- FL
12	1	L75602-76010	*MOULDING SUB-ASSY	Scratched	506.50 FL	*506.50 FL
13	8	T90467-07215	*CLIP	Necessary	28.80 FL	*28.80 FL
14	10	L90269-04051	*RIVET	Necessary	22.00 FL	*22.00 FL
15	10	T90269-06013	*RIVET	Necessary	28.00 FL	*28.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	8,329.40	4,610.50
- List Item Discount on L Items 30.00/30.00% (S\$)	2,498.82	1,383.15
Total Parts (S\$)	5,830.58	3,227.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUNDRIES (Necessary)	New	100.00	50.00
2	TO CHECK WIRING AND CONDUCT WATER L	New	192.00	192.00
3	TO REMOVE AND REINSTALL FRONT BUMPE	New	192.00	192.00
4	TO RESET ECU & REPROGRAMME	New	192.00	192.00
5	TO CONDUCT ADJUSTMENT ON FRONT PRE-	New	192.00	192.00
6	TO REPLACE TYRE RIM AND CONDUCT WHE	New	192.00	192.00
7	TO CONDUCT ADJUATMENT ON WHEEL ALIG	New	168.00	168.00
8	TO REPLACE AND REPAIR ON FRONT ACCI	New	2,304.00	1,536.00
9	TO SPRAY PAINTING ON FRONT ACCIDENT	New	3,264.00	1,305.60
10	SUPPLY SEALANT (NETT) (Not necessary)	New	100.00	0.00

Gross Labour Cost (\$)**6,896.00****4,019.60**

Report was unsubmitted during this print-out.

< END OF ESTIMATES >