



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLX 6990J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BONNET	TO REPAIR SEE LABOUR	\$1,575.00	\$0.00
1	FRONT BUMPER	DISTORTED	\$1,400.00	\$1,400.00
1	FRONT BUMPER SPONGE	TORN	\$175.00	\$175.00
1	FRONT GRILLE	SERVICEABLE	\$450.00	\$0.00
1	FRONT GRILLE LOGO	NOT NECESSARY	\$143.75	\$0.00
1	FRONT BUMPER LOWER TRIM GARNISH	DENTED	\$1,212.50	\$1,100.00
1	FRONT BUMPER LOWER TRIM GRILLE	TORN	\$193.75	\$193.75
1	FRONT BUMPER LH COVER	TWISTED	\$118.75	\$118.75
1	FRONT LH BUMPER SIDE BRACKET (NPA)	NO SUCH PARTS	\$0.00	\$0.00
1	FRONT REINFORCEMENT BEAM	TO REPAIR SEE LABOUR	\$350.00	\$0.00
1	FRONT NUMBER PLATE HOLDER	NOT NECESSARY	\$150.00	\$0.00
1	FRONT LH HEADLAMP ASSY	CRACKED	\$2,812.50	\$2,812.50
1	FRONT LH HEADLAMP BRACKET (NPA)	NO SUCH PARTS	\$0.00	\$0.00
1	FRONT LH SENSOR	SERVICEABLE	\$212.50	\$0.00
1	FRONT LH SENSOR CORNER	SERVICEABLE	\$175.00	\$0.00
1	FRONT LH FENDER TRIM	NOT NECESSARY	\$281.25	\$0.00
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	\$912.50	\$0.00
1	FRONT LH HORN	NOT NECESSARY	\$262.50	\$0.00
1	FRONT LH AIR FLOW SERRATION (ADDITIONAL)	TORN	\$189.00	\$189.00
1	BUMPER FRONT UPPER SUPPORT LH (ADDITIONAL)	CRACKED	\$53.00	\$53.00
1	BUMPER FRONT UNDERCOVER (ADDITIONAL)	TORN	\$365.00	\$365.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$640.70)
			\$11,032.00	\$5,766.30

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$62.50	\$30.00
1	SET RIVETS (SN)	NECESSARY	\$62.50	\$30.00
			\$175.00	\$60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REPLACE FRONT BUMPER, FRONT REINFORCEMENT, LH FENDER, LH HEADLAMP & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT REINFORCEMENT BEAM AND FRONT LH FENDER		\$1,000.00	\$480.00
	TO RESPRAY FRONT BUMPER, FRONT LH FENDER, BLENDING FOR FRONT RH FENDER AND FRONT LH DOOR		\$800.00	\$600.00
	TO CARRY OUT BODY CAVITY PRESERVATION	NOT NECESSARY	\$150.00	\$0.00
	TO CARRY INSPECTION/CHECKS & TEST ON HANDBRAKE AND REAR BRAKE SYSTEM FOR DAMAGE	NOT NECESSARY	\$200.00	\$0.00
	TO TRANSFER THE FRONT BUMPER SENSORS		\$200.00	\$30.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING		\$250.00	\$20.00
	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS		\$350.00	\$100.00
			\$2,950.00	\$1,230.00
GRAND TOTAL			\$14,157.00	\$7,056.30
	RECOMMENDED COST OF REPAIR SUM			\$6,300.00
Report Ref No: CS/SPF24080096/Uvp3				

NOTES : NO SECOND HAND PARTS AND NEW PARTS REPLACEMENT

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$6,300-\$7,500

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.