



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBW 2280A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FRONT FORK TUBE ASSY	BENT	\$880.00	\$528.00
1	FORK UNDER BRACKET	BENT	\$280.00	\$220.00
1	FRONT RIM SHAFT	BENT	\$150.00	\$88.00
1	SET FRONT SIGNALS	BROKEN	\$260.00	\$120.00
1	HANDLE BAR	BENT	\$280.00	\$180.00
1	SET HANDLE BAR BALANCER	N/S CUT	\$155.00	\$80.00
1	SET HAND GRID	NOT NECESSARY	\$88.00	\$0.00
1	SET MIRROR	N/S CUT	\$330.00	\$90.00
1	BRAKE LEVER	CUT	\$160.00	\$70.00
1	HEADLAMP ASSY (LED)	BROKEN	\$1,080.00	\$650.00
1	HEADLAMP PROTECTOR	BROKEN	\$175.00	\$130.00
1	FRONT LOWER COVER	BROKEN	\$285.00	\$200.00
1	FOOT STEP PANEL - L/H	BROKEN	\$180.00	\$150.00
1	FOOT STEP LOWER PANEL - L/H	BROKEN	\$280.00	\$210.00
1	SET FAIRING ASSY	BROKEN	\$1,430.00	\$650.00
1	SIDE STAND	NOT NECESSARY	\$165.00	\$0.00
1	MAIN STAND	BENT	\$225.00	\$170.00
1	BELT HOUSING	CUT	\$780.00	\$250.00
1	BELT HOUSING PROTECTOR	CUT	\$160.00	\$80.00
1	AIR FILTER COVER	NOT NECESSARY	\$185.00	\$0.00
1	REAR FOOTREST	NOT NECESSARY	\$280.00	\$0.00
	LESS 10.00% DISCOUNT		(\$780.80)	(\$386.60)
			\$7,027.20	\$3,479.40

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	NOT NECESSARY	\$38.00	\$0.00
2	FORK OILS (SN)	NECESSARY	\$30.00	\$30.00
2	FORK OIL SEALS (SN)	NECESSARY	\$56.00	\$40.00
1	BEARING CONE (SN)	NECESSARY	\$95.00	\$80.00
1	LOGO (SN)	NECESSARY	\$120.00	\$100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOX (SN)	NOT NECESSARY	\$580.00	\$0.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	\$180.00	\$0.00
1	HAND PHONE HOLDER (SN)	NOT NECESSARY	\$120.00	\$0.00
			\$1,219.00	\$250.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING		\$80.00	\$30.00
	TO REPAIR BODY FRAME		\$420.00	\$100.00
	TO PROVIDE LABOUR		\$480.00	\$300.00
			\$980.00	\$430.00
GRAND TOTAL			\$9,226.20	\$4,159.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,350.00
Report Ref No: CS/LPC24080101/Evp3m4				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.