



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CD/CTI24080108/Dua3q2(N)	
			Date: 20/02/2025	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLE 527D	Veh. Inspected	SHA 3868T
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	08/08/2024
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	KMHC851CVKU165182	Colour	BLUE
	Odometer	702005 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/08/2024	Inspection Date	08/08/2024
	Survey held at	59 LOYANG DRIVE LEVEL 4 ROOM 7 SINGAPORE 508969		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3868T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED	2,253.80	2,253.80
2	BONNET HINGE (LH/RH) @\$118.70	BENT	237.40	237.40
1	BONNET MOULDING	NOT NECESSARY	41.40	-
1	BONNET LOCK	BENT	127.30	127.30
1	BONNET INSULATOR	NOT NECESSARY	230.10	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	15.00	-
1	RADIATOR GRILLE EMBLEM	CUT	88.00	88.00
1	RADIATOR GRILLE	BROKEN	1,409.10	1,409.10
2	FLAP ASSY ACTIVE AIR UPPER (LH/RH) @\$824.60	BROKEN	1,649.20	1,649.20
1	SPEKER ASSY-VESS	NOT NECESSARY	554.40	-
1	UNIT ASSY SMART CRU (RADAR SENSOR)	NOT NECESSARY	3,061.40	-
1	FLAP ASSY ACTIVE WIRE	NOT NECESSARY	765.30	-
1	FRONT NUMBER PLATE GARNISH	BROKEN	188.00	188.00
1	FRONT BUMPER COVER	BROKEN	481.10	481.10
1	FRONT BUMPER TOP COVER	NOT NECESSARY	476.30	-
1	FRONT BUMPER SPONGE	TORN	186.90	186.90
1	FRONT BUMPER REINFORCEMENT	DENTED	1,136.70	1,136.70
2	FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH) @\$186.50	SERVICEABLE	373.00	-
1	FRONT BUMPER TOWING COVER	TO REPAIR SEE LABOUR	29.00	-
1	FRONT BUMPER MOULDING CENTRE UPPER	BROKEN	368.50	368.50
1	FRONT BUMPER MOULDING	NOT NECESSARY	93.60	-
1	FRONT BUMPER LOWER STIFFNER	NOT NECESSARY	285.10	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	365.30	-
1	FRONT BUMPER LOWER GRILLE MOULDING	NOT NECESSARY	127.60	-
1	FRONT BUMPER LIP	NOT NECESSARY	35.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00	NOT NECESSARY	70.00	-
2	FRONT BUMPER BRACKET (LH/RH) @\$28.00	NOT NECESSARY	56.00	-
2	FRONT BUMPER RETAINER MOUNTING (LH/RH) @\$65.30	NOT NECESSARY	130.60	-
10	FRONT BUMPER CLIPS	NECESSARY	25.00	25.00
2	FRONT BUMPER GRILLE (LH/RH) @\$186.90	O/S CUT / N/S NOT NECESSARY	373.80	186.90
2	FRONT BUMPER AIR DUCT (LH/RH) @\$153.80	NOT NECESSARY	307.60	-
1	DAY LIGHT ,LH	NOT NECESSARY	642.50	-

Report Ref No. CD/CTI24080108/Dua3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DAY LIGHT RH	NOT NECESSARY	642.50	-
1	DAY LIGHT WIRE	NOT NECESSARY	585.50	-
1	BUZZER ASSY -PIEZO (LH)	NOT NECESSARY	388.00	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,139.30	1,139.30
2	HEADLAMP (LH/RH) @ \$997.50 \$2,110.30	BROKEN	7,974.60	4,220.60
2	HORN UNIT (LH/RH) @\$72.80	NOT NECESSARY	145.60	-
1	RADIATOR INVERTER	BENT	884.80	884.80
1	RADIATOR	BENT	710.50	710.50
1	RADIATOR FAN BLOWER MOTOR ASSY	NOT NECESSARY	1,459.60	-
2	RADIATOR AIR GUARD (LH/RH) @\$76.40	NOT NECESSARY	152.80	-
2	RADIATOR AIR GUARD ,UPR (LH/RH) @\$127.50	NOT NECESSARY	255.00	-
2	FRT PILLAR UPPER COVER -OUTER (LH/RH) @\$89.60	O/S NOT NECESSARY / N/S DISLODGE	179.20	89.60
2	FRONT FENDER (LH/RH) @\$490.70	O/S TO REPAIR SEE LABOUR / N/S DENTED	981.40	490.70
2	FRONT FENDER APRON PANEL (LH/RH) @\$756.20	NOT NECESSARY	1,512.40	-
2	FRONT FENDER APRON PANEL UPPER (LH/RH) @ \$329.00	NOT NECESSARY	658.00	-
2	FRONT FENDER SHIELD (LH/RH) @\$164.70	NOT NECESSARY	329.40	-
1	AIRCON CONDENSER	BENT	663.60	663.60
	LESS 20% DISCOUNT		-6,969.26	-3,307.40
			27,877.04	13,229.60
2	EMBLEM -BLUE DRIVE (LH/RH) @\$26.60	O/S NOT NECESSARY / N/S NECESSARY	53.20	26.60
	LESS 20% DISCOUNT		-	-5.32
			53.20	21.28
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BROKEN	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	BROKEN	30.00	20.00
2	FRONT FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00(SN)	O/S NOT NECESSARY / N/S NECESSARY	200.00	100.00
1	COOLANT (SN)	NOT NECESSARY	45.00	-
			300.00	145.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER TOWING COVER AND FRONT FENDER RH.		1,800.00	800.00
	SPRAY PAINTING CHARGE.		1,600.00	800.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	20.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX RADIATOR .		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	-
	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR .	NOT NECESSARY	550.00	-
			5,000.00	1,780.00
GRAND TOTAL			33,230.24	15,175.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,100.00

Report Ref No. CD/CTI24080108/Dua3q2(N)

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 1 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 6 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 7 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 9 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 10 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 11 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 12 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 13 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 3 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 5 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 6 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 7 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 8 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 9 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 10 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 11 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 12 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 13 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 14 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 15 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 16 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 17 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 18 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 19 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 20 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 21 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SHA 3868T

