

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**Tax Invoice**

MS FIRST CAPITAL INSURANCE LTD  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING  
  
SINGAPORE 048581

INV No. : SAC2401465  
INV Date : 20-11-2024

Reference CD/FCI24080109/Rua3q2  
Code FCI2

**PROFESSIONAL SERVICE FEE**

Vehicle No. SMW 2386Z  
Insured Veh. SHC 8656U  
Claim No. D24006639MFCT/TPD2/KT  
Policy No. D-24101861MFCT  
Accident Date 28/07/2024  
Inspection Date 27/08/2024

| Description                    | Amount |
|--------------------------------|--------|
| Third Party Express Settlement | 350.00 |
| Sub-Total                      | 350.00 |
| GST (9%)                       | 31.50  |
| Grand Total                    | 381.50 |

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

**LKK Auto Consultants Pte Ltd**

***LKM***

---



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

|                                   |       |                       |
|-----------------------------------|-------|-----------------------|
| MS MS FIRST CAPITAL INSURANCE LTD | Ref:  | CD/FCI24080109/Rua3q2 |
| 16 RAFFLES QUAY                   | Date: | 20/11/2024            |
| #42-01 HONG LEONG BUILDING        | Code: | FCI2                  |
| SINGAPORE 048581                  |       |                       |

### 1. Policy Particulars :- DIRECT SETTLEMENT

|              |                       |                |            |
|--------------|-----------------------|----------------|------------|
| Insured Veh. | SHC 8656U             | Veh. Inspected | SMW 2386Z  |
| Policy No.   | D-24101861MFCT        | Coverage       | 0          |
| Claim No.    | D24006639MFCT/TPD2/KT | Excess         | \$0.00     |
| Assign From  | KAREN TAN             | Assign Date    | 07/08/2024 |

### 2. Vehicle Details

|                 |                             |              |            |
|-----------------|-----------------------------|--------------|------------|
| Make & Model    | MAZDA 3 4DR 1.5 AT M-HYBRID | C.C          | 1496       |
| Engine No.      | P520624766                  | Year of Reg. | 10/11/2020 |
| Chassis No.     | JM6BP2SAAK1101483           | Colour       | GREY       |
| Odometer        | 86479 KM                    | Steering     | IN ORDER   |
| Brakes          | IN ORDER                    | General      | FAIR       |
| Modification(s) | RIMS: SPORTS RIM            |              |            |

### 3. Conditions of Tyres

|                | Size       | Make        | Balance (mm) |
|----------------|------------|-------------|--------------|
| R/H Front Tyre | 205/60 R16 | CONTINENTAL | 6            |
| L/H Front Tyre | 205/60 R16 | CONTINENTAL | 6            |
| R/H Rear Tyre  | 205/60 R16 | CONTINENTAL | 6            |
| L/H Rear Tyre  | 205/60 R16 | CONTINENTAL | 6            |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

|                |                                                                                           |                 |            |
|----------------|-------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 28/07/2024                                                                                | Inspection Date | 27/08/2024 |
| Survey held at | MOVA AUTOMOTIVE PTE LTD<br>BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 .<br>SINGAPORE 159722 |                 |            |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMW 2386Z

| REPLACEMENT OF PARTS |                                    |               |                        |                   |
|----------------------|------------------------------------|---------------|------------------------|-------------------|
| Qty                  | Description of Parts               | Condition     | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1                    | HEADLAMP ASSY LH                   | SCRATCHED     | \$2,266.25             | \$2,266.25        |
| 1                    | HEADLAMP PANEL LH (NPA)            | NOT NECESSARY | \$0.00                 | \$0.00            |
| 1                    | HEADLAMP LOWER BRACKER LH          | CRACKED       | \$67.70                | \$67.70           |
| 1                    | RADIATOR GRILLE MOULDING LH        | CRACKED       | \$341.95               | \$341.95          |
| 1                    | FRONT BUMPER                       | SCRATCHED     | \$867.30               | \$867.30          |
| 1                    | FRONT BUMPER RETAINER LH           | CRACKED       | \$23.60                | \$23.60           |
| 10                   | FRONT BUMPER CLIPS @\$5.00         | NECESSARY     | \$50.00                | \$50.00           |
| 1                    | FRONT FENDER LH                    | BENT          | \$476.80               | \$476.80          |
| 1                    | FRONT FENDER COWLING LH            | DEFORMED      | \$202.95               | \$202.95          |
| 10                   | FRONT FENDER COWLING CLIPS @\$5.00 | NECESSARY     | \$50.00                | \$50.00           |
| 1                    | FRONT SPORT RIM LH                 | SCRATCHED     | \$1,320.00             | \$1,320.00        |
| 1                    | FRONT WHEEL HUB C/W BEARING LH     | SERVICEABLE   | \$611.75               | \$0.00            |
| 1                    | FRONT KNUCKLE ARM LH               | SERVICEABLE   | \$452.75               | \$0.00            |
| 1                    | FRONT LOWER ARM LH                 | SERVICEABLE   | \$520.90               | \$0.00            |
| 1                    | FRONT SHOCK ABSORBER LH            | SERVICEABLE   | \$378.80               | \$0.00            |
| 1                    | FRONT BUMPER TOP BRACKET LH        | CRACKED       | \$21.50                | \$21.50           |
|                      | <b>LESS 20.00% DISCOUNT</b>        |               | (\$1,530.45)           | (\$1,137.61)      |
|                      |                                    |               | <b>\$6,121.80</b>      | <b>\$4,550.44</b> |

| Labour             |                                                                                                         |           |                        |                   |
|--------------------|---------------------------------------------------------------------------------------------------------|-----------|------------------------|-------------------|
|                    | Description of Parts                                                                                    | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
|                    | TO KNOCK & STRAIGHTEN FRONT BODY MEMBER ,REMOVE & REPLACE ACCIDENT DAMAGED PARTS.REALIGN ALL CONNECTION |           | \$500.00               | \$400.00          |
|                    | SPRAY PAINT FRONT BUMPER ,BONNET ,FRONT FENDER LH                                                       |           | \$600.00               | \$600.00          |
|                    | REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION LH                                                     |           | \$250.00               | \$80.00           |
|                    | COMPUTER WHEEL ALIGNMENT                                                                                |           | \$60.00                | \$60.00           |
|                    | RUST PROOF AFFECTED AREAS                                                                               |           | \$30.00                | \$30.00           |
|                    |                                                                                                         |           | <b>\$1,440.00</b>      | <b>\$1,170.00</b> |
| <b>GRAND TOTAL</b> |                                                                                                         |           | <b>\$7,561.80</b>      | <b>\$5,720.44</b> |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

|                                             |                                                                                 |  |                   |
|---------------------------------------------|---------------------------------------------------------------------------------|--|-------------------|
|                                             | <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  | <b>\$4,550.00</b> |
| <b>Report Ref No: CD/FCI24080109/Rua3q2</b> |                                                                                 |  |                   |

## ***MRB***

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**




**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**




**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**





**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**



**PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**REINSPECTION PHOTOS (Page 2 of 2)**

### PHOTOGRAPHS FOR VEHICLE NO. : SMW 2386Z

