

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080116/UMA3Q2**Date:** 14/10/2024REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900117674
Claimant Vehicle No : SGV1509U **Insured Vehicle No :** SMN2988J
 Date of Loss: 03/08/2024 Nature of Claim: TP Claim No: 3712230481SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV1509U**
 Make & Model: TOYOTA WISH, 1.8 X (A) Engine No: 1ZZ2927261
 Reg. Date: 05/06/2007 (Man. Year: 2007) Chassis No: ZNE100370344
 Colour: White Odometer: 424550 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,100.80	11,932.82	14,167.98	54.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,380.00	3,700.00	2,680.00	42.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,480.80	15,632.82	16,847.98	51.87
Approved Total (Overridden) (S\$)		12,500.00		
(S\$)	32,480.80	12,500.00	19,980.80	61.52
+ GST 9.00/9.00% (S\$)	2,923.27	1,125.00	1,798.27	61.52
Nett Amount (S\$)	35,404.07	13,625.00	21,779.07	61.52
+ Car Rental (14.0 x S\$120.00/day) (S\$)		1,680.00		
+ Doc/Search Fee (S\$)		2.18		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		15,367.18		
Global Sum Settlement (S\$)		15,300.00		

INSPECTION

Date of Assignment: 07/08/2024
 Date Inspected: 07/08/2024 Inspected At: Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883
 Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	1,488.10 F	*1,085.20 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	188.30 F	*188.30 FL
3	1		*TAILGATE	Badly Dented	2,685.10 F	*2,108.10 FL
4	1		*TAILGATE OUTER HANDLE CHROME	Cracked	544.80 F	*399.80 FL
5	1		*TAILGATE REAR LOGO	Necessary	68.50 F	*68.50 FL
6	1		*TAILGATE REAR WIPER ARM	Serviceable	188.90 F	*- FL
7	1		*TAILGATE REAR WIPER MOTOR	Bent / Jammed	620.00 F	*588.90 FL
8	1		*TAILGATE WEATHERSTRIP	Twisted	488.90 F	*398.50 FL
9	1		*TAILGATE INNER LOCK	Damaged / Jammed	641.90 F	*641.90 FL
10	1		*TAILGATE LOCK STRIKER	Not Necessary	60.00 F	*- FL
11	1		*TAILGATE INNER TRIM	Cracked	811.60 F	*641.10 FL
12	1		*TAILGATE INNER HOLDER GARNISH	Not Necessary	58.00 F	*- FL
13	1		*REAR BUMPER	Distorted	915.10 F	*701.20 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	170.00 F	*- FL
15	1		*REAR BUMPER SIDE RETAINERS	N/S Cracked / O/S Not Necessary	130.00 F	*65.00 FL
16	1		*REAR BUMPER DAMPERS	N/S Bent / O/S Not Necessary	570.00 F	*180.50 FL
17	1		*REAR END PANEL OUTER	Badly Dented	899.10 F	*899.10 FL
18	1		*REAR END PANEL LOCK SENSOR	Not fitted	350.00 F	*- FL
19	1		*REAR END PANEL TOP GARNISH	Distorted	468.90 F	*322.20 FL
20	2		*TAILLAMPS	N/S Broken / O/S Cracked	2,101.00 F	*970.20 FL
21	1		*TAILLAMP HOUSING PANELS	N/S Dented / O/S Repair	1,300.60 F	*520.50 FL
22	1		*REAR FENDER N/S	Badly Dented / Buckled	1,205.10 F	*1,205.10 FL
23	2		*REAR FENDER INNER TRIM BOARDS	Torn	1,370.20 F	*1,370.20 FL
24	1		*REAR FENDER UNDER CLOTH N/S	Not Necessary	281.20 F	*- FL
25	1		*REAR FENDER GLASS N/S	Shattered	1,099.10 F	*688.50 FL
26	1		*REAR FLOOR PANEL	Crumpled / Buckled	1,415.10 F	*1,125.20 FL
27	1		*REAR FLOOR PANEL TOP BOARD	Warped	622.30 F	*482.90 FL
28	1		*REAR FLOOR PANEL INNER GARNISH	Cracked	588.10 F	*366.20 FL
29	1		*REAR EXHAUST	Not Necessary	885.10 F	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	188.30 F	*- FL
31	1		*REAR DOOR N/S	Repair	2,012.30 F	*- FL
32	1		*REAR DOOR INNER LOCK N/S	Serviceable	455.20 F	*- FL
33	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
35	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*20.00 FS
36	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
37	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
38	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	450.00 FS	*120.00 FS
39	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR REVERSE CAMERA	Malfunction	380.00 FS	*300.00 FS
41	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
42	1		*REAR FENDER GLASS SEALANT N/S	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,100.80	15,687.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	3,754.28
Total Parts (\$\$)	26,100.80	11,932.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REAR REVERSE CAMERA	New	80.00	30.00
3	TO DISMANTLE & REPLACED REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REPLACED REAR FENDER GLASS N/S	New	120.00	100.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	100.00	0.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
8	TO TRANSFER TAILGATE MECHANISM	New	100.00	50.00
9	TO SPRAY PROOFING	New	180.00	100.00
10	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
11	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	3,000.00	1,800.00
12	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,400.00
Gross Labour Cost (\$\$)			6,380.00	3,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >