



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080117/Kqp3e2
16 RAFFLES QUAY	Date:	27/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 608L	Veh. Inspected	WC 6336D
Policy No.	-	Coverage	0
Claim No.	D24007068MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	07/08/2024

2. Vehicle Details

Make & Model	ISUZU CYH52S	C.C	15681
Engine No.	6WG1419241	Year of Reg.	28/08/2013
Chassis No.	JALCYH52SD7000323	Colour	MULTI COLOUR
Odometer	401937 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	295/80 R22.5	KPATOS	9
L/H Front Tyre	295/80 R22.5	KPATOS	9
R/H Rear Tyre	295/80 R22.5 (D/D)	KPATOS	8
L/H Rear Tyre	295/80 R22.5 (D/D)	KPATOS	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/08/2024	Inspection Date	08/08/2024
Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days