



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080118/Kvp3e2
16 RAFFLES QUAY	Date:	07/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3084H	Veh. Inspected	FBV 3294J
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24006627MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	07/08/2024

### 2. Vehicle Details

Make & Model	YAMAHA NMAX	C.C	155
Engine No.	G3L8E1646462	Year of Reg.	24/07/2023
Chassis No.	MH3SG5680PK177677	Colour	BLACK
Odometer	18769 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110/70 R13	PIRELLI	4
L/H Front Tyre			
R/H Rear Tyre	130/70 R13	PIRELLI	5
L/H Rear Tyre			

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	25/07/2024	Inspection Date	07/08/2024
Survey held at	PROJECT 8 MOTORWORKS 61 WOODLANDS INDUSTRIAL PARK E9, #01-03, E9 PREMIUM, SINGAPORE 757047		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days