



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLF 2870T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	GRAZED	\$654.20	\$654.20
1	REAR BUMPER SIDE O/S	CUT/TORN	\$285.60	\$285.60
1	REAR BUMPER REFLECTOR O/S	NOT NECESSARY	\$151.00	\$0.00
1	TAILLAMP O/S	NOT NECESSARY	\$520.80	\$0.00
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	\$971.20	\$0.00
1	REAR FENDER OUTER PROTECTOR O/S	GRAZED	\$288.60	\$288.60
1	REAR FENDER UNDER CLOTH O/S	TORN	\$241.50	\$241.50
1	REAR SHOCK ABSORBER O/S	NOT NECESSARY	\$299.80	\$0.00
1	REAR WHEEL HUB BEARING O/S	NOT NECESSARY	\$520.00	\$0.00
	LESS 20.00% DISCOUNT		(\$786.54)	(\$293.98)
			\$3,146.16	\$1,175.92

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	SET REAR FENDER UNDER CLOTH CLIPS O/S (SN)	NECESSARY	\$50.00	\$50.00
1	REAR SPORT RIM O/S (SN)	TO REPAIR SEE LABOUR	\$600.00	\$0.00
			\$700.00	\$100.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING		\$50.00	\$20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR		\$80.00	\$30.00
	TO DISMANTLE & REFIX REAR WINDSCREEN	NOT NECESSARY	\$150.00	\$0.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	NOT NECESSARY	\$120.00	\$0.00
	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	NOT NECESSARY	\$180.00	\$0.00
	TO SPRAY RUST PROOFING	NOT NECESSARY	\$50.00	\$0.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER O/S AND REAR SPORT RIM O/S		\$800.00	\$300.00
	TO PUTTY & SPRAY PAINTING		\$800.00	\$400.00
			\$2,230.00	\$750.00

GRAND TOTAL			\$6,076.16	\$2,025.92
--------------------	--	--	-------------------	-------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,600.00
Report Ref No: CS/AGI24080121/Uvp3			

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.