



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24080123/Aqp3m4
(BUDGET DIRECT INSURANCE)	Date:	11/12/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNL 4248Y	Veh. Inspected	SLA 4595B
Policy No.	-	Coverage	0
Claim No.	C10030946/JK	Excess	\$0.00
Assign From	JANICE KOH	Assign Date	07/08/2024

2. Vehicle Details

Make & Model	HONDA SHUTTLE	C.C	1496
Engine No.	L15B3530245	Year of Reg.	01/03/2016
Chassis No.	GK81000175	Colour	GREY
Odometer	182851 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	MICHELIN	6
L/H Front Tyre	185/60R15	MICHELIN	6
R/H Rear Tyre	185/60R15	MICHELIN	6
L/H Rear Tyre	185/60R15	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2024	Inspection Date	07/08/2024
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days