

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24080130/RUA3Q2
Date: 28/05/2025

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210157129
Claimant Vehicle No : SLZ7328E **Insured Vehicle No :** SMU2149C
Date of Loss: 05/08/2024 Nature of Claim: TP Claim No: 6987176735SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ7328E**
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A) Engine No: G4FGJU185592
Reg. Date: 17/05/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU685879
Colour: Grey Odometer: 108166 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
Front Left Side: Tourador 5 mm Rear Left Side: Tourador 6 mm
Front Right Side: Tourador 5 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,393.40	100.00	2,293.40	95.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	760.00	360.00	32.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,513.40	860.00	2,653.40	75.52
+ GST 9.00/9.00% (S\$)	316.21	77.40	238.81	75.52
Nett Amount (S\$)	3,829.61	937.40	2,892.21	75.52
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		1,119.58		

INSPECTION

Date of Assignment: 14/10/2024
Date Inspected: 14/10/2024 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Estimated Period of Repair: 3.0 days Blk 3 Pioneer Road North, #01-18 Singapore 628457

Adjuster: NA MENG YAN**Manager:** MOHD RASUL

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	500.00 F	*- F
2	6		*FRT BUMPER CLIP	Not Necessary	29.40 F	*- F
3	1		*FRT HEADLAMP LH	Not Necessary	1,199.00 F	*- F
4	1		*FRT HEADLAMP BRACKET LH	Not Necessary	35.00 F	*- F
5	1		*FRT TYRE RIM	Scratched	350.00 FS	*100.00 FS
6	1		*FRT TYRE	Not Necessary	280.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,393.40	100.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK FRT FENDER ,WELD ,REMOVE & REFIX ABOVE PARTS	New	500.00	300.00
2	TO SPRAY PAINTING ON AFFECTED AREAS	New	500.00	400.00
3	TO DO WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$\$)			1,120.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >