

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080132/AMA3Q2**Date:** 28/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100484867
Claimant Vehicle No : SMG7633L **Insured Vehicle No :** SLG5263X
 Date of Loss: 05/08/2024 Nature of Claim: TP Claim No: 2546629468SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG7633L**
 Make & Model: TOYOTA VIOS, 1.5 G (A) Engine No: 2NRX403584
 Reg. Date: 31/12/2018 (Man. Year: 2018) Chassis No: MR2B23F3901160273
 Colour: Bronze Odometer: 88356 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,440.45	735.75	2,704.70	78.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	650.00	2,810.00	81.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,900.45	1,385.75	5,514.70	79.92
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	6,900.45	1,100.00	5,800.45	84.06
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		1,247.25		
Global Sum Settlement (S\$)		1,240.00		

INSPECTION

Date of Assignment: 05/08/2024
 Date Inspected: 05/08/2024 Inspected At: Kt Motorwerk (HQ)
 Estimated Period of Repair: 2.0 days Blk 3012 Bedok Industrial Park E, #01-2020
 Singapore 489978

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	686.70 FL	*686.70 FL
2	1		*REAR BUMPER SIDE RETAINERS	Cracked	85.80 FL	*85.80 FL
3	2		*REAR BUMPER ATTACHMENT RETAINERS	Not Necessary	138.60 FL	*- FL
4	2		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	184.20 FL	*- FL
5	1		*REAR BUMPER REFLECTORS	Cracked	168.50 FL	*168.50 FL
6	1		*END PANEL	Not Necessary	645.30 FL	*- FL
7	1		*END PANEL TOP TRIM	Not Necessary	186.90 FL	*- FL
8	1		*REAR AIR VENT LH	Not Necessary	86.20 FL	*- FL
9	2		*REAR FENDER INNER TRIM	Not Necessary	286.30 FL	*- FL
10	2		*REAR FENDER INNER SHIELD	Not Necessary	125.80 FL	*- FL
11	2		*BOOTLID LAMP	Not Necessary	408.20 FL	*- FL
12	1		*TAILLAMPS	Not Necessary	468.60 FL	*- FL
13	1		*TAILLAMPS INNER SEALER	Not Necessary	38.00 FL	*- FL
14	1		*TAILLAMPS PANELS	Not Necessary	131.50 FL	*- FL
15	1		*SET END PANEL JOINT SEALANT	Not Necessary	150.00 FS	*- FS
16	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	50.00 FS	*- FS
17	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
18	1		*SET END PANEL TOP TRIM CLIPS	Not Necessary	30.00 FS	*- FS
19	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
20	2		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
21	2		*SET TAILLAMPS CLIPS	Not Necessary	60.00 FS	*- FS
22	1		*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,350.60	971.00
- List Item Discount on L Items 25.00/25.00% (\$)	910.15	235.25
Total Parts (\$)	3,440.45	735.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	200.00
2	SPRAY PAINTING	New	1,200.00	400.00
3	CHECK WIRING ON TAILAMP	New	120.00	0.00
4	ANTI RUST	New	180.00	0.00
5	REMOVE AND INSTALL INTERIOR UPHOLSTERY	New	120.00	0.00
6	REMOVE AND INSTALL REVERSE SENSOR	New	120.00	50.00
7	REMOVE AND INSTALL REVERSE CAMERA	New	150.00	0.00
8	TO CONDUCT RESET AND MANAGEMENT UNIT CALIBRATION	New	250.00	0.00
9	TO FOUR WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			3,460.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >