



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 2888S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLEBAR	BENT	590.00	590.00
1	HANDLE GRIP LH	NOT NECESSARY	85.00	-
1	HANDLE GRIP RH	CUT	85.00	85.00
1	HANDLE BALANCER LH	NOT NECESSARY	115.00	-
1	HANDLE BALANCER RH	SCRATCHED	115.00	115.00
1	HANDLE BALANCER COVER LH	NOT NECESSARY	70.00	-
1	HANDLE BALANCER COVER RH	SCRATCHED	70.00	70.00
1	BRAKE LEVER LH	NOT NECESSARY	155.00	-
1	BRAKE LEVER RH	SCRATCHED	155.00	155.00
1	MIRROR LH	NOT NECESSARY	190.00	-
1	MIRROR RH	SCRATCHED	190.00	190.00
1	UP HANDLE COVER	SCRATCHED	180.00	180.00
1	DOWN HANDLE COVER	SCRATCHED	240.00	240.00
1	HANDLE TOP COVER LH	NOT NECESSARY	210.00	-
1	HANDLE LOWER COVER LH	NOT NECESSARY	211.00	-
1	HANDLE TOP COVER RH	SCRATCHED	210.00	210.00
1	HANDLE LOWER COVER RH	SCRATCHED	210.00	210.00
1	HEADLAMP	BROKEN	1,250.00	1,250.00
1	HEADLAMP RIM	BENT	150.00	150.00
1	FRONT FORK UNDER BRACKET	BENT	720.00	720.00
1	FRONT FORK SET LH	BENT	690.00	690.00
1	FRONT FORK SET RH	BENT	690.00	690.00
1	STEERING CONE	NECESSARY	290.00	290.00
1	FRONT FENDER	SCRATCHED	390.00	390.00
2	FRONT NUMBER PLATE	NECESSARY	50.00	50.00
1	FRONT SPORTS RIM	CUT	980.00	980.00
1	TOP BEARING RH	NECESSARY	210.00	210.00
1	LOWER BEARING RH	NECESSARY	210.00	210.00
1	REAR FOOTREST COVER RH	CRACKED	170.00	170.00
1	REAR FOOTREST BRACKET RH	BENT	170.00	170.00
1	EXHAUST PIPE PROTECTOR	SCRATCHED	250.00	250.00

Report Ref No. CS/FCI24080134/Rvh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CRASH BAR LESS 10% DISCOUNT	SCRATCHED	560.00 -	560.00 -882.50
			9,861.00	7,942.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOX (SN)	SCRATCHED	280.00	150.00
			280.00	150.00
	<u>LABOUR</u>			
	PAINTWORK (UP & DOWN HANDLE COVER, FRONT FENDER).		390.00	250.00
	TOWING 2 WAY.		150.00	75.00
	LABOUR.		500.00	300.00
			1,040.00	625.00
GRAND TOTAL			11,181.00	8,717.50

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,950.00
---	--	--	-----------------

Report Ref No. CS/FCI24080134/Rvh3m4(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.