



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 9027H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SIDE MIRROR RH	DENTED/JAMMED	1,258.00	1,258.00
1	SIDE MIRROR COVER RH	TO REPAIR SEE LABOUR	356.00	-
1	SIDE MIRROR BRACKET RH	SERVICEABLE	152.00	-
1	SIDE MIRROR GLASS RH	CRACKED	345.00	345.00
	LESS 5% DISCOUNT		-	-80.15
			2,111.00	1,522.85
	<b><u>LABOUR</u></b>			
	TO SPRAY PAINT ON AFFECTED AREAS.		800.00	80.00
	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING.	NOT NECESSARY	800.00	-
	TO PANEL BEAT ON AFFECTED AREA. INCLUSIVE OF THE REPAIR OF SIDE MIRROR COVER RH.		800.00	80.00
			2,400.00	160.00
	<b>GRAND TOTAL</b>		<b>4,511.00</b>	<b>1,682.85</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,350.00</b>

Report Ref No. CS/SPF24080135/Kqh3m4(N)

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,350-\$1,400**

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.