



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE

Ref: CS/INC24080137/Anh3m4(N)

Date: 05/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 4865H	Veh. Inspected	SMS 7052A
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1289648-002	Excess (\$)	0.00
Assign From	ANNA YEO	Assign Date	07/08/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	MR2B23F3001193890	Colour	WHITE
Odometer	62782 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/08/2024	Inspect Date / Time	08/08/2024 (11:00 AM)
Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**