



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBC 2562S

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER (N)	BUCKLED/DENTED	\$524.80	\$524.80
1	REAR LAMP (N)	BROKEN	\$299.30	\$299.30
1	REAR BUMPER RETAINER (N)	DISTORTED	\$35.00	\$35.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$85.91)
			\$859.10	\$773.19
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	LOWER LID (SN)	CRACKED	\$350.00	\$350.00
			\$350.00	\$350.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REPAIR		\$400.00	\$350.00
	SPRAY PAINTING		\$800.00	\$550.00
			\$1,200.00	\$900.00
GRAND TOTAL			\$2,409.10	\$2,023.19
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,600.00
Report Ref No: CS/FCI24080138/Knh3m4				

**KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.