



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24080141/Rqh3e2
16 RAFFLES QUAY	Date:	08/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 8574S	Veh. Inspected	SMG 9565L
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24006835MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	08/08/2024

### 2. Vehicle Details

Make & Model	HYUNDAI AVANTE 1.6 GLS (A)	C.C	1591
Engine No.	G4FGJU044796	Year of Reg.	05/01/2019
Chassis No.	KMHD841CMKU815946	Colour	WHITE
Odometer	77283 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	CONTINENTAL	6
L/H Front Tyre	195/65 R15	CONTINENTAL	6
R/H Rear Tyre	195/65 R15	CONTINENTAL	6
L/H Rear Tyre	195/65 R15	CONTINENTAL	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	03/08/2024	Inspection Date	13/08/2024
Survey held at	KOMOCO MOTORS PTE LTD 253 ALEXANDRA ROAD #01-01 SINGAPORE 159936.		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days