IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-47 Synergy@KB, Singapore 417800 HP: 97489940 Shawn Tan

Email: shawn7530@hotmail.com

Not Androlad norms 1918/24 19 4 6870.83 Hays.

Vehicel No: PD1343T

Model:

TOYOTA HI-ACE BUS

OTY	DECRIPTION			AMT S\$		
	<u>List Items</u>					
1	Rear windscreen moulding			\$ NS	120.80 🗶	
1	Rear tailgate			\$ Ballo?	2,649.00	
2	Rear tailgate dampers			\$ 17	694.20 X	
1	Rear tailgate inner trim board			\$ 17	289.60 X	
1	Rear tailgate lock			\$ Dayl	450.00	
1	Rear tailgate lock catch			\$ in	55.00 ×	
1	Rear tailgate lock remote			\$ 17	850.00 🗶	
1	Rear tailgate logo			\$ nu	80.50 —	
1	Rer tailgate rubber			\$ 111	379.80	
2	Rear tailgate lower side stoppers			\$ 17	96.50 X	
1	Rear tailgate "HIACE" emblem			\$ 111	59.60	
1	Rear tailgate "GL" emblem			\$ ru	72.40	
2	Rear taillamps	396.50	MSnn	\$ akone	850.00 17	
2	Rear taillamp lower garnishes	396.50 180.60	MSnn	\$ OK TWI	568.40 C	
1	Rear end panel			\$ 50	569.10 —	
1	Rear end panel inner member			\$ R	624.50 X	
1	Rear end panel top moulding			\$ 11	259.30 ⊀	
1	Rear bumper			\$ 30	738.00	
2	Rear bumper top brackets			\$ 11	130.00 ⊀	
4	Rear bumper lower brackets			\$ Bert	212.00	
1	Rear bumper reinforcement			\$ NS	458.00 ×	
2 /sef				\$ me		
2	Rear bumper side retainers			\$ 11	112.40 X	
1	Rear floor panel			\$ R	1,880.80 X	
1	Rear spare tyre carriage			\$ 41	486.95 X	
1	Rear spare tyre lock catch			\$ 11	88.20 X	
1	Rear exhaust silencer			\$ R	716.95 X	
2	Rear exhaust mountings			\$ 11	97.20 X	
1	Rear side panel - RH			\$ 11	1,879.70 🗶	
1	Rear side panel air vent			\$ 17	68.00 X	
				\$	15,630.50	
			Less 25%	 3,907.63		
				\$	11,722.88	

Special Nett Items		7.7
	\$	ALL 80.00 40
	\$	nec 25.00 10
	\$	AU 50.00 30
	\$	17 50.00 ×
	\$	one 960.00 2755 360
, , , ,	\$	Acc 80.00 30
Tour tangers Transport	\$	1,245.00
Lahour Charges		
	\$	80.00 20
	\$	150.00 60
	\$	300.00 €0
	\$	120.00 6 0
	\$	180.00 / 2
	\$	~ ~ 150.00 ×
	\$	200.0050
	\$	1,800.00 800
		1,600.00
10 16-Spray painting on the arrested areas	\$	4,580.00
Grand Total:	\$	17,547.88
	Rear windscreen sealant Rear tailgate "70KM/H" sticker Rear bumper clip (1 Set) Rear number plate Rear reverse sensor (4 Pcs) Rear tailgate Malaysia sticker Labour Charges To remove, replaced damaged lamps and check up rear wiring To remove and refit inner garnishes , seat etcs To remove and refit rear reverse sensor and recalibrate To transfer rear tailgate mechanism and wiring assembly To remove and refit rear windscreen glass To remove, refit and replace exhaust silencer and mountings To apply undercoating Panel beating To re-spray painting on the affected areas	Rear windscreen sealant Rear tailgate "70KM/H" sticker Rear bumper clip (1 Set) Rear number plate Rear reverse sensor (4 Pcs) Rear tailgate Malaysia sticker Labour Charges To remove, replaced damaged lamps and check up rear wiring To remove and refit inner garnishes , seat etc. To remove and refit rear reverse sensor and recalibrate To transfer rear tailgate mechanism and wiring assembly To remove, refit and replace exhaust silencer and mountings To apply undercoating Panel beating To re-spray painting on the affected areas

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

F-5881-10 202 4410.83 470 1990 6870.83