



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNH 8363S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT BUMPER-RH	BUCKLED	\$810.00	\$810.00
10	FRT BUMPER CLIPS	NECESSARY	\$55.00	\$55.00
1	RHF BUMPER RETAINER	SERVICEABLE	\$75.00	\$0.00
1	RHF FOG LAMP GARNISH	CUT	\$155.00	\$155.00
	LESS 25.00% DISCOUNT		(\$273.75)	(\$255.00)
			\$821.25	\$765.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT DAMAGE PARTS		\$500.00	\$200.00
	TO PUTTY,RESPRAY ON FRT BUMPER,RHF FENDER AFFECTED AREA		\$500.00	\$220.00
			\$1,000.00	\$420.00

GRAND TOTAL			\$1,821.25	\$1,185.00
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			\$1,185.00
--	---	--	--	-------------------

Report Ref No: CS/SPF24080146/Knh3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,100-\$1,400

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.