

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|---|-----------------|-----------------------|--|
| MS | AUTOMOTIVE ENC | GRG. & MGT. DIVISION (TP) | Ref: | CS/SPF24080146/Knh3m4 | |
| | ACCIDENT CLAIMS (SPORE POLICE F | | Date: | 26/09/2024 | |
| | POLICE LOGISTIC | S BASE (PLB) O SINGAPORE 438675 | Code: | SPF | |
| 1. | I. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | QX 1807E | Veh. Inspected | SNH 8363S | |
| | Policy No. | - | Coverage | 0 | |
| | Claim No. | ACS/105/009/2024/037 (LK) | Excess | \$0.00 | |
| | Assign From | LAI PENGCHONG | Assign Date | 08/08/2024 | |
| 2. | 2. Vehicle Details | | | | |
| | Make & Model | TOYOTA NOAH (A) | c.c | 1797 | |
| | Engine No. | 2ZR2S84863 | Year of Reg. | 30/11/2022 | |
| | Chassis No. | ZWR900033731 | Colour | METALLIC BLACK | |
| | Odometer | 124664 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | GOOD | |
| | Modification(s) | RIMS: STANDARD ALLOY RIM | | | |
| 3. | | Condition | s of Tyres | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 205/60R16 | DAVANTI | 9 | |
| | L/H Front Tyre | 205/60R16 | DAVANTI | 9 | |
| | R/H Rear Tyre | 205/60R16 | DAVANTI | 9 | |
| | L/H Rear Tyre | 205/60R16 | DAVANTI | 9 | |
| 4. | | Description | of Damages | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. | | General Information | | | |
| | Accident Date | 05/08/2024 | Inspection Date | 08/08/2024 | |
| | Survey held at | COMFORTDELGRO ENGINEERING 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701. | PTE LTD | | |
| 5a. | | Rem | arks | | |
| | A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | | |
| | | | | | |

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days