

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMG 3574A

	ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMG 35/4A							
	REPLACEMENT OF PARTS							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)				
1	REAR BUMPER	TORN	\$1,578.00	\$887.00				
1	REAR BUMPER END SEAL COVER RH	TORN	\$156.00	\$156.00				
1	REAR BUMPER RH REFLECTOR	CRACKED	\$63.40	\$63.40				
1	REAR BUMPER RH SPONGE	CRACKED	\$84.20	\$84.20				
2	REAR BUMPER SIDE CORNER RETAINER L/R @\$42.90	O/S CRACKED	\$85.80	\$42.90				
2	REAR BUMPER SIDE RETAINER L/R @\$61.20	NOT NECESSARY	\$122.40	\$0.00				
1	REAR RH FENDER	TO REPAIR SEE LABOUR	\$896.00	\$0.00				
	LESS 25.00% DISCOUNT		(\$746.45)	(\$308.38)				
			\$2,239.35	\$925.12				
Special Nett								

Special Nett							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$80.00	\$30.00			
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	\$280.00	\$0.00			
			\$360.00	\$30.00			

TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR  TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)  TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT  TO PROVIDE LABOIR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR RH FENDER	Condition  NOT NECESSARY	\$80.00 \$80.00	<b>Our Adjusted (\$)</b> \$80.00 \$0.00
LIGHTING, AND REWIRE FOR PARKING SENSOR  TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)  TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT  TO PROVIDE LABOIR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF	NOT NECESSARY	\$80.00	·
SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)  TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT  TO PROVIDE LABOIR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF	NOT NECESSARY	,,,,,	\$0.00
PORTION, AND WHERE CONSISTENT TO THE ACCIDENT  TO PROVIDE LABOIR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF			
DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF		\$1,000.00	\$500.00
		\$1,000.00	\$250.00
TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	NOT NECESSARY	\$100.00	\$0.00
		\$830.00	

GRAND TOTAL	\$4,859.35	\$1,785.12		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,400.00		
Report Ref No: CS/AGI24080147/Aqh3e2				



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## **LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.