

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24080150/UNH3E2
Date: 04/10/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001419176
Claimant Vehicle No :	YP4102H	Insured Vehicle No :	SKT7376J
Date of Loss:	03/08/2024	Nature of Claim:	TP
		Claim No:	369189

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP4102H	Engine No:	N04CUS28887
Make & Model:	HINO XZU710R-HKFMS3, 4.0 D (M)	Chassis No:	JHHUCS3H20K018166
Reg. Date:	09/09/2016 (Man. Year: 2016)	Odometer:	124767 km
Colour:	White		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00-16	Rear Tyre Size:	7.00-16 (D)
Front Left Side:	Super Traveller 6 mm	Rear Left Side:	Super Traveller 6/6 mm
Front Right Side:	Super Traveller 6 mm	Rear Right Side:	Super Traveller 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,079.00	8,375.50	11,703.50	58.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	1,920.00	1,880.00	49.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,879.00	10,295.50	13,583.50	56.88
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	23,879.00	8,200.00	15,679.00	65.66
+ GST 9.00/9.00% (S\$)	2,149.11	738.00	1,411.11	65.66
Nett Amount (S\$)	26,028.11	8,938.00	17,090.11	65.66

INSPECTION

Date of Assignment:	12/08/2024	
Date Inspected:	08/08/2024	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Oct 2024)	
Parts:	N/A	HINO XZU710R-HKFMS3 4.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP4102H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,615.00 FL	*1,100.00 FL
2	1		*FRONT BUMPER BRACKET N/S	Bent	520.00 FL	*366.50 FL
3	1		*FRONT BUMPER FOG LAMP N/S	Broken	485.00 FL	*399.20 FL
4	1		*FRONT BUMPER FOG LAMP COVER N/S	Distorted	118.00 FL	*118.00 FL
5	1		*HEADLAMP N/S	Cracked	1,650.00 FL	*1,288.50 FL
6	1		*FRONT CORNER PANEL GARNISH N/S	Not Necessary	745.00 FL	*- FL
7	1		*FRONT GRILLE	Not Necessary	990.00 FL	*- FL
8	1		*FRONT MIRROR BRACKET N/S	Not Necessary	295.00 FL	*- FL
9	1		*FRONT PANEL	Repair	2,450.00 FL	*- FL
10	1		*FRONT DOOR N/S	Badly Dented	3,205.00 FL	*2,100.00 FL
11	1		*FRONT DOOR OUTER PILLAR N/S	Repair	2,115.00 FL	*- FL
12	1		*FRONT DOOR INNER PILLAR N/S	Repair	1,051.00 FL	*- FL
13	1		*FRONT DOOR INNER LOCK N/S	Not Necessary	450.00 FL	*- FL
14	1		*FRONT DOOR INNER TRIM BOARD N/S	Deformed / Torn	585.00 FL	*422.80 FL
15	1		*FRONT DOOR INNER RUBBER N/S	Torn	188.00 FL	*188.00 FL
16	1		*FRONT DOOR HINGE N/S	Serviceable	105.00 FL	*- FL
17	1		*FRONT STEP GARNISH N/S	Cracked	650.00 FL	*335.50 FL
18	1		*AIR CON CONDENSER	Distorted	1,550.00 FL	*1,488.20 FL
19	1		*AIR CON FAN ASSY MOTOR	Cracked / Jammed	850.00 FL	*666.00 FL
20	1		*AIR CON CONDENSER BRACKET	Repair	320.00 FL	*- FL
21	1		*AIR CON PIPE	Serviceable	258.00 FL	*- FL
22	1		*FRONT WHEEL ARCH PANEL N/S	Bent / Twisted	565.00 FL	*522.30 FL
23	1		*SET FRONT DOOR CORPORATE STICKER N/S	Necessary	700.00 FS	*250.00 FS
24	1		*SET FRONT VIEW CAM (DAMAGED)	Not Consistent With The Impact	650.00 FS	*- FS
25	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FN	*30.00 F

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	22,160.00	9,275.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,076.00	899.50
- Nett Item Discount on N Items 10.00/0.00% (\$\$)	5.00	0.00
Total Parts (\$\$)	20,079.00	8,375.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	120.00	50.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	TO DISMANTLE & REFIX FRONT DASHBOARD	New	300.00	0.00
5	TO TRANSFER FRONT DOOR MECHANISM	New	100.00	50.00
6	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,250.00	800.00
8	TO PUTTY & SPRAY PAINTING	New	1,680.00	900.00
Gross Labour Cost (S\$)			3,800.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >