

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080153/UPA3Q2**Date:** 11/10/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220041650
Claimant Vehicle No :	GBL8020C	Insured Vehicle No :	SLD122T
Date of Loss:	05/08/2024	Nature of Claim:	TP
		Claim No:	1534486181SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL8020C		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR MT (M)	Engine No:	1KDB108773
Reg. Date:	13/04/2022 (Man. Year: 2021)	Chassis No:	JTFHT02P400252152
Colour:	White	Odometer:	109085 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,270.40	3,227.37	3,043.03	48.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,530.00	450.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,250.40	4,757.37	3,493.03	42.34
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	8,250.40	3,800.00	4,450.40	53.94
+ GST 9.00/9.00% (S\$)	742.54	342.00	400.54	53.94
Nett Amount (S\$)	8,992.94	4,142.00	4,850.94	53.94
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,624.18		

INSPECTION

Date of Assignment:	12/08/2024	
Date Inspected:	12/08/2024	Inspected At: Liu's Brother Auto Workshop (HQ) 1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Tailgate	Body Dented	2,159.30 F	*2,159.30 FL
2	1		*Tailgate Lock	Damaged	399.20 F	*399.20 FL
3	1		*Tailgate Weatherstrip	Serviceable	426.70 F	*- FL
4	1		*Tailgate Outer Garnish	Not Necessary	397.00 F	*- FL
5	1		*Tailgate Toyota Motif	Necessary	70.50 F	*70.50 FL
6	1		*Tailgate 70 KM/H Sticker	Necessary	15.00 FS	*10.00 FS
7	1		*Tailgate 8 PAX Sticker	Necessary	15.00 FS	*10.00 FS
8	1		*End Panel Outer	Dented/ Bent	566.10 F	*566.10 FL
9	1		*End Panel Inner	Repair	936.20 F	*- FL
10	1		*End Panel Sealant	Necessary	50.00 FS	*30.00 FS
11	1		*Rear Bumper	Dented	681.40 F	*681.40 FL
12	1		*Rear Bumper Clips 1 Set	Necessary	65.00 FS	*30.00 FS
13	1		*Rear Bumper Reverse Sensor 1 Set	Malfunction	220.00 FS	*200.00 FS
14	1		*Tailgate Windscreen Glass Moulding	No Such Part	219.00 F	*- FL
15	1		*Tailgate Windscreen Glass Sealant	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,270.40	4,196.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	969.13
Total Parts (\$\$)	6,270.40	3,227.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Transfer Tailgate Mechanism	New	80.00	50.00
2	Remove and refix rear bumper reverse sensor	New	100.00	30.00
3	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc's	New	800.00	680.00
4	To putty & spray painting & including touch up paint on accident affected areas	New	800.00	600.00
5	To apply Rust Proofing , reseal tuff-coating treatment on accident area	New	80.00	50.00
6	Remove & reinstall Tailgate Glass to facilitate repairs	New	120.00	120.00
Gross Labour Cost (S\$)			1,980.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >