



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO EK 333Y

Cost Plus				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER (WCP)	DENTED/CUT	\$420.00	\$420.00
1	FRONT BUMPER LH SIDE RETAINER (WCP)	NECESSARY	\$70.00	\$70.00
10	FRONT BUMPER CLIPS (WCP)	NECESSARY	\$20.00	\$20.00
1	FRONT LH FENDER (WCP)	BENT	\$650.00	\$650.00
1	FRONT LH FENDER GLASS WITH MOULDING (WCP)	SCRATCHED	\$250.00	\$250.00
1	FRONT LH FENDER INNER SHIELD (WCP)	SERVICEABLE	\$150.00	\$0.00
10	FRONT LH FENDER INNER SHIELD CLIPS (WCP)	NECESSARY	\$20.00	\$20.00
1	FRONT LH FENDER LOWER PROTECTOR (WCP)	DENTED/CUT	\$150.00	\$150.00
1	FRONT LH SPORT RIM (WCP)	DENTED	\$1,500.00	\$1,500.00
1	FRONT LH SHOCK ABSORBER (WCP)	BENT	\$280.00	\$280.00
1	FRONT LH KNUCKLE ARM (WCP)	BENT	\$310.00	\$310.00
1	FRONT LH WHEEL BEARING (WCP)	NECESSARY	\$290.00	\$290.00
1	FRONT LH LOWER ARM (WCP)	DISTORTED	\$220.00	\$220.00
1	FRONT LH STABILIZER LINK (WCP)	SERVICEABLE	\$110.00	\$0.00
1	LH SIDE MIRROR HOUSING (WCP)	CRACKED	\$850.00	\$850.00
1	LH SIDE MIRROR COVER (WCP)	SERVICEABLE	\$70.00	\$0.00
1	FRONT LH DOOR (WCP)	BENT	\$1,100.00	\$1,100.00
	<b>COST PLUS 10.00%</b>		\$646.00	\$613.00
			\$7,106.00	\$6,743.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FENDER GLASS GUM (SN)	NECESSARY	\$60.00	\$40.00
1	FRONT LH TYRE (SN)	SERVICEABLE	\$280.00	\$0.00
			\$340.00	\$40.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX LH FENDER GLASS		\$120.00	\$60.00
	TO CHECK WHEEL ALIGNMENT		\$150.00	\$60.00
	TO REMOVE AND REFIX FRONT UNDERCARRIAGE		\$280.00	\$200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REPAIR DAMAGES		\$780.00	\$600.00
	TO SPRAY PAINTING		\$880.00	\$800.00
			\$2,210.00	\$1,720.00
GRAND TOTAL			\$9,656.00	\$8,503.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$6,800.00
	LESS EXCESS			(\$750.00)
	NETT LIABILITY			\$6,050.00
Report Ref No: CS/UOI24080155/Knp3m4				

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.