

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080159/AMA3Q2
Date: 07/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0004973_01
Claimant Vehicle No : SLV9473B Insured Vehicle No : SMK1431X
Date of Loss: 09/08/2024 Nature of Claim: TP Claim No: MFL2024D0009206

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV9473B
Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT (A) Engine No: HRA2553997A
Reg. Date: 23/01/2018 (Man. Year: 2017) Chassis No: SJNFEAJ11U2161902
Colour: Red Odometer: 105068 km
Engine Capacity: 1197 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Giti 6 mm Rear Left Side: Giti 6 mm
Front Right Side: Giti 6 mm Rear Right Side: Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,586.44	6,687.15	9,899.29	59.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,338.00	1,750.00	5,588.00	76.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,924.44	8,437.15	15,487.29	64.73
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	23,924.44	6,750.00	17,174.44	71.79
+ GST 9.00/9.00% (S\$)	2,153.20	607.50	1,545.70	71.79
Nett Amount (S\$)	26,077.64	7,357.50	18,720.14	71.79
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		7,984.75		
Global Sum Settlement (S\$)		7,900.00		

INSPECTION

Date of Assignment: 12/08/2024
Date Inspected: 12/08/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Dec 2024)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV9473B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	646.00 FL	*646.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	64.20 FL	*- FL
3	1		*FRONT BUMPER FOGLAMP COVER RH	Not Necessary	75.10 FL	*- FL
4	2		*HEADLAMP (HID)	Not Necessary	1,224.40 FL	*- FL
5	1		*BONNET	Repair	1,061.30 FL	*- FL
6	2		*BONNET HINGE	Not Necessary	112.20 FL	*- FL
7	1		*FRONT FENDER RH	Distorted	677.10 FL	*677.10 FL
8	1		*FRONT FENDER INNER GARNISH RH	Not Necessary	138.40 FL	*- FL
9	1		*FRONT FENDER ARCH SEAL RH	Deformed	148.90 FL	*148.90 FL
10	1		*FRONT FENDER COWLING RH	Deformed	119.80 FL	*119.80 FL
11	1		*FRONT FENDER MUDFLAP RH	Deformed	86.20 FL	*86.20 FL
12	1		*FRONT ABS SENSOR RH	Not Necessary	217.60 FL	*- FL
13	1		*FRONT KNUCKLE RH	Damaged	389.70 FL	*389.70 FL
14	1		*FRONT SHOCK ABSORBER RH	Not Necessary	268.70 FL	*- FL
15	1		*FRONT WHEEL RIM RH	Cut	1,679.40 FS	*680.00 FS
16	1		*FRONT WHEEL HUP RH	Damaged	398.60 FL	*398.60 FL
17	1		*FRONT WHEEL HUP BEARING RH	Damaged	197.40 FL	*197.40 FL
18	1		*FRONT STEERING RANK AND PINION	Bent	1,524.80 FL	*1,524.80 FL
19	1		*FRONT LINKAGE RH	Not Necessary	127.60 FL	*- FL
20	1		*FRONT LOWER ARM RH	Bent	546.80 FL	*546.80 FL
21	1		*FRONT DRIVESHAFT RH	Not Necessary	1,249.80 FL	*- FL
22	1		*FRONT DOOR PILLAR RH	Repair	1,869.20 FL	*- FL
23	1		*FRONT WINDSCREEN MOULDING	Not Necessary	286.40 FL	*- FL
24	1		*FRONT DOOR RH	Dented	1,542.40 FL	*1,542.40 FL
25	1		*FRONT DOOR BLACK S STICKER RH	Necessary	86.40 FL	*86.40 FL
26	1		*FRONT DOOR FRAME STEP GARNISH RH	Not Necessary	96.50 FL	*- FL
27	2		*FRONT DOOR HINGE RH	Not Necessary	87.20 FL	*- FL
28	1		*FRONT DOOR LOCK CHECKER RH	Not Necessary	79.60 FL	*- FL
29	1		*FRONT DOOR LOCK CATCHER RH	Not Necessary	25.30 FL	*- FL
30	1		*FRONT DOOR OUTER STRIP RH	Not Necessary	98.30 FL	*- FL
31	1		*FRONT DOOR INNER LOCK RH	Not Necessary	298.70 FL	*- FL
32	1		*FRONT DOOR INNER TRIM RH	Not Necessary	746.70 FL	*- FL
33	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	147.80 FL	*- FL
34	1		*FRONT DOOR PROTECTOR RH	Cracked	199.40 FL	*199.40 FL
35	1		*FRONT DOOR INNER LOWER RUBBER RH	Not Necessary	98.00 FL	*- FL
36	1		*FRONT DOOR SPEAKER RH	Not Necessary	349.10 FL	*- FL
37	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
38	1		*SET FRONT FENDER COWLING CLIP RH	Necessary	30.00 FS	*30.00 FS
39	1		*SET FRONT FENDER WHEEL ARCH CLIP RH	Necessary	50.00 FS	*20.00 FS
40	1		*SET FRONT DOOR INNER TRIM CLIP RH	Not Necessary	50.00 FS	*- FS
41	1		*SET FRONT DOOR PROTECTOR CLIP RH	Necessary	50.00 FS	*20.00 FS
42	1		*FRONT DOOR PILLAR SEALANT RH	Not Necessary	120.00 FS	*- FS
43	1		*FRONT WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
44	1		*FRONT WINDSCREEN INNER SHIELD	Not Necessary	120.00 FS	*- FS
45	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*WHEEL TYRE RH	Not Necessary	450.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)	18,115.00	7,343.50
				- List Item Discount on L Items 10.00/10.00% (\$\$)	1,528.56	656.35
				Total Parts (\$\$)	16,586.44	6,687.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	600.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	250.00	30.00
5	REFOCUS HEADLAMP BEAM	New	80.00	0.00
6	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
7	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	0.00
8	REMOVE AND REFIX DASHBOARD	New	650.00	0.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	648.00	220.00
10	REMOVE AND REFIX STEERING RACK AIR PINION	New	180.00	120.00
11	TO PRESS FRONT WHEEL BEARING	New	80.00	0.00
12	TRANFER FRONT DOOR MECHANISM	New	80.00	40.00
13	REMOVE & REINSTALL FRONT WINDOW GLASS	New	80.00	30.00
14	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
15	RESET ABS LIGHT	New	350.00	0.00
16	FOUR WHEEL ALIGNMENT	New	120.00	80.00
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			7,338.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >