

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24080163/ENP3E2

Date: 28/08/2024

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SHA7512T	Insured Vehicle No :	SLP9527L
Date of Loss:	08/08/2024	Nature of Claim:	TP
		Claim No:	DMPC2401043H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7512T		
Make & Model:	HYUNDAI SX2 KONA, 1.6 GDI HEV (A)	Engine No:	G4LLRU429662
Reg. Date:	28/06/2024 (Man. Year: 2024)	Chassis No:	KMHHB811VRU071428
Colour:	Blue	Odometer:	11663 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Kumho 7 mm	Rear Left Side:	Kumho 7 mm
Front Right Side:	Kumho 7 mm	Rear Right Side:	Kumho 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,176.06	5,765.31	1,410.75	19.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,510.00	860.00	36.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,546.06	7,275.31	2,270.75	23.79
+ GST 9.00/9.00% (\$\$)	859.15	654.78	204.37	23.79
Nett Amount (\$\$)	10,405.21	7,930.09	2,475.12	23.79

INSPECTION

Date of Assignment:	12/08/2024		
Date Inspected:	12/08/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Aug 2024)
Parts:	192	HYUNDAI SX2 KONA 1.6 GDI HEV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7512T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY UPPER	Broken	1,020.00 FL	*1,015.00 FL
2	1		*REAR BUMPER ASSY LOWER	Broken	668.82 FL	*510.39 FL
3	1		*REAR BUMPER BEAM	Broken	582.00 FL	*582.00 FL
4	2		*REAR BUMPER STAY LH/RH	Not Necessary	110.00 FL	*- FL
5	1		*PANEL ASSY-TAIL GATE	Dented	2,164.00 FL	*2,164.00 FL
6	1		*EMBLEM-HYBRID	Necessary	47.00 FL	*47.00 FL
7	1		*EMBLEM-KONA	Necessary	97.00 FL	*97.00 FL
8	1		*EMBLEM-SYMBOL MARK	Necessary	72.00 FL	*72.00 FL
9	1		*LATCH ASSY-TAIL GATE	Broken	278.00 FL	*278.00 FL
10	1		*HANDLE ASSY-TAIL GATE	Not Necessary	125.00 FL	*- FL
11	1		*REAR BUMPER COVER SIDE LH	Repair	245.00 FL	*- FL
12	1		*GARNISH-TAIL GATE	Broken	325.00 FL	*325.00 FL
13	1		*REAR WINDSCREEN GLASS	Not Necessary	609.00 FL	*- FL
14	1		*REAR END PANEL	Dented	729.00 FL	*729.00 FL
15	2		*REAR NUMBER PLATE LAMP LH/RH	Broken	142.00 FL	*71.00 FL
16	1		*TAILLAMP ASSY LH	Cut	953.00 FL	*953.00 FL
17	1		*REAR BUMPER SIDE BRACKET LH	Not Necessary	32.00 FL	*- FL
18	1		*REAR BUMPER COVER LH	Not Necessary	245.00 FL	*- FL
19	1		*REAR FOG LAMP	Not Necessary	163.00 FL	*- FL
20	1		*BOOTLID COMFORT LOG	Necessary	30.00 FS	*30.00 FS
21	1		*BOOTLID COMFORT TEL NOS LOGO	Necessary	30.00 FS	*30.00 FS
22	1		*BOOTLID APPS LOGO	Necessary	40.00 FS	*40.00 FS
23	1		*WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
24	1		*REAR NUMBER PLATE	Broken	55.00 FS	*55.00 FS
25	1		*ANTENNA ASSY-SMARTKEY	Broken	112.00 FL	*112.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					8,919.82	7,156.39
- List Item Discount on L Items 20.00/20.00% (\$\$)					1,743.76	1,391.08
Total Parts (\$\$)					7,176.06	5,765.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	760.00
2	SPRAY PAINT	New	900.00	560.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	20.00
4	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
5	CHECK WIRING	New	50.00	30.00
6	TUFF COAT	New	50.00	20.00
Gross Labour Cost (\$\$)			2,370.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >