5/5/25, 10:02 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080167/TUA3Q2(N)

Date: 05/05/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0007521_03

Claimant Vehicle SLZ5887X Insured Vehicle No: SMG6811X

No:

Date of Loss: 03/08/2024 Nature of Claim: TP Claim No: MPC2024D0008978

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLZ5887X Reg No:

Make & Model: BMW 116I, 1.5 LED HL FL MSPT (A) Engine No: 34186939B38A15A Reg. Date: WBA7K120607L71101 10/10/2023 (Man. Year: 2022) Chassis No:

Colour: White Odometer: 13078 km

Engine Capacity: 1499 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes **Engine Modification:** Nο

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,282.80	40.00	1,242.80	96.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,844.00	1,912.00	932.00	32.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,126.80	1,952.00	2,174.80	52.70
+ GST 9.00/9.00% (S\$)	371.41	175.68	195.73	52.70
Nett Amount (S\$)	4,498.21	2,127.68	2,370.53	52.70
+ Loss of Use (3.0 x	S\$60.00/day) (S\$)	180.00		
+ Do	c/Search Fee (S\$)	2.18		
•	Other Costs (S\$)	420.00		
	Nett Liability (S\$)	2,729.86		

INSPECTION

Date of Assignment: 16/08/2024

Date Inspected: 16/08/2024 Inspected At: 303 Alexandra Road, Singapore

Performance Motors Limited (HQ)

Singapore 159941

Estimated Period of Repair: 3.0 days

MOHD TAUFIKH BIN HAMID Adjuster: NA MENG YAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2025)

Parts: 144 BMW 116I 1.5 LED HL FL MSPT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ5887X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*REAR RH DOOR	Repair	1,242.80 FS	*- FS
2 1	*SUNDRIES	Necessary	40.00 FS	*40.00 FS
F=Franchise part. S=SpcNe	ett.	Total Parts (S\$)	1,282.80	40.00
	Report was	unsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	To replace rear right passenger door	New	1,275.00	850.00
2	To replace rear right passenger door	New	1,038.00	885.00
3	To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (1 door).	New	531.00	177.00
	Gross Labour Cost (S\$)		2,844.00	1,912.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >