

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24080168/UPA3Q2**Date:** 09/12/2025REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7230090952   |
| <b>Claimant Vehicle No :</b> | SLP7296R                             | <b>Insured Vehicle No :</b> | SMF7850G     |
| Date of Loss:                | 08/08/2024                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 8503185136SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLP7296R</b>                   |             |                   |
| Make & Model:               | VOLVO S60, 1.5 T2 (A)             | Engine No:  | B4154T52051150    |
| Reg. Date:                  | 26/05/2017 (Man. Year: 2017)      | Chassis No: | YV1FS28C0H2441110 |
| Colour:                     | Silver                            | Odometer:   | 111527 km         |
| Engine Capacity:            | 1498 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/45Z R18   | Rear Tyre Size:  | 225/45Z R18   |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 17,302.14         | 4,787.62          | 12,514.52         | 72.33         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 2,490.00          | 1,250.00          | 1,240.00          | 49.80         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>19,792.14</b>  | <b>6,037.62</b>   | <b>13,754.52</b>  | <b>69.49</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>4,200.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 19,792.14         | 4,200.00          | 15,592.14         | 78.78         |
| <b>+ GST 9.00/9.00% (S\$)</b>                   | 1,781.29          | 378.00            | 1,403.29          | 78.78         |
| <b>Nett Amount (S\$)</b>                        | <b>21,573.43</b>  | <b>4,578.00</b>   | <b>16,995.43</b>  | <b>78.78</b>  |
| <b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b> |                   | 500.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.18              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>5,080.18</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>5,080.00</b>   |                   |               |

INSPECTION

|                             |                          |                                                        |
|-----------------------------|--------------------------|--------------------------------------------------------|
| Date of Assignment:         | 22/08/2024               | Hock Wah Motor Workshop Pte Ltd (Bedok)                |
| Date Inspected:             | 22/08/2024 Inspected At: | Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012 |
| Estimated Period of Repair: | 4.0 days                 | Singapore 489977                                       |

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition     | Repairer's | Amount       |
|-----|-----|----------|--------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *FRONT FENDER LH               | Badly Dented  | 1,865.84 F | *1,650.00 FL |
| 2   | 1   |          | *FRONT FENDER INNER SHIELD LH  | Twisted       | 423.13 F   | *423.13 FL   |
| 3   | 1   |          | *BONNET HINGE LH               | Not Necessary | 285.00 F   | *- FL        |
| 4   | 1   |          | *BONNET HINGE RH               | Not Necessary | 285.00 F   | *- FL        |
| 5   | 1   |          | *FRONT BUMPER SIDE RETAINER LH | Not Necessary | 133.83 F   | *- FL        |
| 6   | 1   |          | *FRONT BUMPER REINFORCEMENT    | Not Necessary | 1,690.82 F | *- FL        |
| 7   | 1   |          | *HEADLAMP LH                   | Not Necessary | 1,705.20 F | *- FL        |
| 8   | 1   |          | *HEADLAMP BRACKET LH           | Not Necessary | 133.87 F   | *- FL        |
| 9   | 1   |          | *FRONT WHEEL RIM LH            | Warped        | 1,166.47 F | *1,166.47 FL |
| 10  | 1   |          | *FRONT KNUCKLE ARM LH          | Not Necessary | 2,018.39 F | *- FL        |
| 11  | 1   |          | *FRONT SHOCK ABSORBER LH       | Not Necessary | 2,319.54 F | *- FL        |
| 12  | 1   |          | *FRONT LOWER ARM LH            | Not Necessary | 1,181.49 F | *- FL        |
| 13  | 1   |          | *FRONT WHEEL BEARING LH        | Not Necessary | 886.66 F   | *- FL        |
| 14  | 1   |          | *FRONT ABS SENSOR LH           | Not Necessary | 430.50 F   | *- FL        |
| 15  | 1   |          | *FRONT BALL JOINT LH           | Not Necessary | 496.40 F   | *- FL        |
| 16  | 1   |          | *FRONT BUMPER                  | Cut / Torn    | 1,800.00 F | *1,800.00 FL |
| 17  | 1   |          | *FRONT TYRE LH                 | Serviceable   | 480.00 FS  | *- FS        |
| 18  | 1   |          | *BONNET (NPA)                  | Repair        | 0.00 F     | *- FL        |
| 19  | 1   |          | *FRONT DOOR LH (NPA)           | Repair        | 0.00 F     | *- FL        |
| 20  | 1   |          | *FRONT WHEEL HOUSING LH (NPA)  | Not Necessary | 0.00 F     | *- FL        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                        |                  |                 |
|--------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                  | <b>17,302.14</b> | <b>5,039.60</b> |
| <b>- List Item Discount on L Items 0.00/5.00% (\$)</b> | 0.00             | 251.98          |
| <b>Total Parts (\$)</b>                                | <b>17,302.14</b> | <b>4,787.62</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                              | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                          |          |                 |                 |
| 1                               | LABOUR TO REMOVE & REFIT NECESSARY PARTS | New      | 800.00          | 400.00          |
| 2                               | SPRAY PAINT ON THE AFFECTED AREAS        | New      | 1,200.00        | 800.00          |
| 3                               | TO REMOVE & REFIT UNDERCARRIAGE          | New      | 350.00          | 0.00            |
| 4                               | WIRING                                   | New      | 40.00           | 20.00           |
| 5                               | ANTI RUST COATING                        | New      | 100.00          | 30.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                          |          | <b>2,490.00</b> | <b>1,250.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >