

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24080169/ENP3M4**Date:** 29/08/2024REFERENCE

Handling Insurer: ECICS Limited

Policy No:

**Claimant Vehicle No :** SHD3971L**Insured Vehicle No :** GBH2047L

Date of Loss: 09/08/2024

Nature of Claim:

TP

Claim No: DMCV2400157H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD3971L**

Make &amp; Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2G17957

Reg. Date: 20/12/2019 (Man. Year: 2019)

Chassis No: JTDKB3FU903090505

Colour: Blue

Odometer: 395399 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size:

195/65R15

Front Left Side: West Lake 4 mm

Rear Left Side:

West Lake 4 mm

Front Right Side: West Lake 4 mm

Rear Right Side:

West Lake 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,750.51	2,580.23	2,170.28	45.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	2,050.00	250.00	10.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,050.51</b>	<b>4,630.23</b>	<b>2,420.28</b>	<b>34.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,700.00</b>		
<b>(S\$)</b>	7,050.51	3,700.00	3,350.51	47.52
<b>+ GST 9.00/9.00% (S\$)</b>	634.55	333.00	301.55	47.52
<b>Nett Amount (S\$)</b>	<b>7,685.06</b>	<b>4,033.00</b>	<b>3,652.06</b>	<b>47.52</b>

INSPECTION

Date of Assignment: 12/08/2024

Date Inspected:

12/08/2024 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2024)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3971L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	551.89 FL	*551.89 FL
2	1		*REAR BUMPER LOWER COVER	Broken	654.96 FL	*654.96 FL
3	1		*REAR BUMPER SIDE SEAL LH	Not Necessary	148.40 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	378.32 FL	*378.32 FL
5	1		*REAR BUMPER TOW HOOK COVER	Broken	82.70 FL	*82.70 FL
6	1		*REAR TRUNK LOGO PRIUS	Necessary	52.90 FL	*52.90 FL
7	1		*REAR TRUNK LOGO HYBRID	Necessary	52.40 FL	*52.40 FL
8	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	225.40 FL	*- FL
9	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
10	1		*REAR END PANEL	Dented	738.96 FL	*738.96 FL
11	1		*REAR BUMPER REFLECTOR LH	Not Necessary	55.00 FL	*- FL
12	1		*REAR TYRE PANEL	Repair	667.70 FL	*- FL
13	1		*REAR LOWER CENTRE COVER	Missing	425.25 FL	*425.25 FL
14	1		*FRONT DOOR PANEL RH	Repair	1,797.20 FL	*- FL
15	1		*FRONT DOOR COMFORT STICKER	Necessary	75.00 FS	*75.00 FS
16	2		*BOOTLID COMFORT /TELNO. STICKER	Necessary	60.00 FS	*60.00 FS
17	1		*BOOTLID COMFORT APP STICKER	Necessary	40.00 FS	*40.00 FS
18	1		*REAR BUMPER REVERSE SENSOR	Broken	135.70 FS	*135.70 FS
19	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,213.78	3,320.08
- List Item Discount on L Items 25.00/25.00% (S\$)	1,463.27	739.85
Total Parts (S\$)	4,750.51	2,580.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	1,140.00
2	SPRAY PAINTING CHARGE	New	900.00	840.00
3	CHECK WIRING AND LIGHTING	New	60.00	30.00
4	TUFF COATING	New	80.00	20.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	20.00
Gross Labour Cost (\$\$)			2,300.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >