

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24080170/KNP3M4**Date:** 26/08/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002958595
Claimant Vehicle No :	SNH1972E	Insured Vehicle No :	GBB1031U
Date of Loss:	05/08/2024	Nature of Claim:	TP
		Claim No:	369669

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH1972E	Engine No:	LEB7608398
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP72206883
Reg. Date:	03/10/2022 (Man. Year: 2021)	Odometer:	148530 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	KAPSEN 3 mm	Rear Left Side:	KAPSEN 4 mm
Front Right Side:	KAPSEN 3 mm	Rear Right Side:	KAPSEN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,050.20	1,270.72	3,779.48	74.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	980.00	1,570.00	61.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,600.20	2,250.72	5,349.48	70.39
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	7,600.20	1,800.00	5,800.20	76.32
+ GST 9.00/9.00% (S\$)	684.02	162.00	522.02	76.32
Nett Amount (S\$)	8,284.22	1,962.00	6,322.22	76.32

INSPECTION

Date of Assignment:	13/08/2024		
Date Inspected:	13/08/2024	Inspected At:	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Aug 2024)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH1972E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR N/S	Bent	1,357.00 FL	*898.60 FL
2	1		*FRONT DOOR TOP HINGE N/S	Repair	187.00 FL	*- FL
3	1		*FRONT DOOR LOWER HINGE N/S	Distorted	176.00 FL	*65.30 FL
4	1		*FRONT DOOR INNER TRIM BOARD N/S	Serviceable	583.00 FL	*- FL
5	1		*FRONT DOOR OUTER HANDLE N/S	Serviceable	296.00 FL	*- FL
6	1		*FRONT DOOR OUTER HANDLE LOCK SENSOR N/S	Serviceable	195.00 FL	*- FL
7	1		*FRONT DOOR LOCK N/S	Repair	285.00 FL	*- FL
8	1		*FRONT DOOR WEATHERSTRIP N/S	Serviceable	183.00 FL	*- FL
9	1		*FRONT DOOR WINDOW REGULATOR N/S	Serviceable	336.00 FL	*- FL
10	1		*FRONT DOOR WINDOW MOTOR N/S	Serviceable	281.00 FL	*- FL
11	1		*FRONT DOOR WINDOW OUTER CHANNEL N/S	Serviceable	153.00 FL	*- FL
12	1		*FRONT FENDER N/S	Bent	884.00 FL	*425.90 FL
13	1		*FRONT FENDER COWLING N/S	Distorted	197.00 FL	*142.60 FL
14	1		*FRONT FENDER HYBRID EMBLEM N/S	Necessary	56.00 FL	*56.00 FL
15	10		*FRONT DOOR INNER TRIM BOARD CLIPS N/S	Not Necessary	55.00 FS	*- FS
16	1		*FRONT STEEL WHEEL N/S	Serviceable	350.00 FS	*- FS
17	1		*FRONT HUB COVER N/S	Serviceable	180.00 FS	*- FS
18	1		*FRONT TYRE N/S	Serviceable	280.00 FS	*- FS
19	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,084.00	1,588.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,033.80	317.68
Total Parts (\$\$)	5,050.20	1,270.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,200.00	400.00
2	TO DISCONNECT N/S FRONT DOOR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS OF POWER WINDOWS	New	50.00	20.00
3	TO REMOVE AND REFIT N/S FRONT DOOR COMPONENTS TO REPLACE N/S FRONT DOOR, CHECK ALIGNMENT	New	200.00	60.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	1,000.00	440.00
5	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	60.00
Gross Labour Cost (\$\$)			2,550.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >