

- On the day of accident, many Lorries are queuing up at left side road (red color arrows) including the **XB7335T** (the opponent lorry) waiting for soil disposal and tried to enter LTA site gate at RIGHT side at the time of incident
- Our lorry **XB5471X** (Kuber Global) going all the way in the road at right side
- The opponent lorry **XB7335T**, after waiting, suddenly tried to turn right to enter the site gate entrance at the time. At the time our lorry **XB5471X** going on the way (right side road) to the next soil disposal site.
- The lorry **XB7335T** DID NOT signal and suddenly turned right side without watching the behind the our lorry from the right side road.
- When our lorry **XB5471X** going towards to next site, the opponent lorry HIT our lorry's **left side BACK Tire barrier** (refer **Figure-2**)
- Refer the **Figure-1**, the opponent lorry hit with our lorry at right side back tire barrier.

Figure-1





Figure-2 The opponent lorry hit into our lorry at back tire barrier when suddenly turned right from the left side after waiting (as indicated below)



**Figure-3** : The opponent lorry **XB7335T** trying to turn right and enter into the site at the time of accident





**Figure-4** : The opponent lorry damaged after hit into our lorry behind while turning right into LTA site after waiting in road side



Our Lorry Driver's IC copy (this is recent renewal license copy)

