

CHUNNI MOTOR WORK PTE LTD

To Survey by Ute (Ma)

REPAIR ESTIMATE*

VEHICLE NO : SHA 4406L

DATE : 12.12.2014

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI SONATA

FAX : 6542 6039

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet Bnc			\$ 1,151.80
	Bonnet Rubber (LH) NH			\$ 18.00
	Bonnet Hinge (LH/RH) o/s st n/s repen	\$	87.50	\$ 175.00
	Bonnet Lock st			\$ 48.80
	Bonnet Cable snc			\$ 45.50
	Radiator Grille crack			\$ 282.10
	Radiator Grille U Moulding crack			\$ 108.90
	Front Bumper Cover torn			\$ 538.80
	Front Bumper Sponge torn			\$ 136.30
	Front Bumper Reinforcement st			\$ 504.10
	Front Bumper Grille (RH) broken			\$ 17.60
	Front Bumper Centre Grille broken			\$ 131.10
	Front Bumper Lip torn			\$ 59.90
	Front Bumper Bracket Top (RH) broken			\$ 22.40
	Front Bumper Protector (RH) broken			\$ 29.20
	Front Bumper Bracket (RH) broken			\$ 20.10
	Front Bumper Side Bracket broken			\$ 14.30
	Front Bumper Retainer Mounting broken			\$ 9.20
	Headlamp Support Panel Assy crack			\$ 1,023.00
	Headlamp (LH/RH) o/s smashed n/s NH	\$	797.90	\$ 1,595.80
	Headlamp Halogen Bulb (LH/RH) o/s smashed n/s NH	\$	13.80	\$ 27.60
	Radiator Punctured			\$ 814.80
	Radiator Fan Blade, Cowling, Motor Assy ?			\$ 651.30
	Radiator Bracket repen	\$	6.20	\$ 12.40
	Radiator Hose Upper damaged			\$ 45.40
	Radiator Hose Lower NH			\$ 45.40
	Radiator Expansion Tank crack			\$ 46.00
	Front Fender (RH) snc			\$ 593.00
	Front Fender Apron Panel (RH) snc			\$ 732.50
	Front Fender Shield (RH) torn			\$ 86.00
	Front Fender Mudflap (RH) n/f			\$ 15.50
	Front Fender Signal Lamp (RH) NH			\$ 45.40
	Front Fender Retainer H/c			\$ 9.20
	Aircon Condenser st			\$ 1,089.90
	Aircon Suction & Liquid Hose st ?			\$ 631.40
	Aircon Discharge Hose ?			\$ 223.50
	Aircon Compressor ?			\$ 2,738.50
	Front Windscreen Glass cracked			\$ 1,015.00
	Front Windscreen Moulding H/c			\$ 27.20
	Wiper Container torn			\$ 59.00
	Wiper Container Motor Dam			\$ 63.00
	Front Wheel Rim (RH) st			\$ 284.70
	Front Wheel Hub Cap (RH) dislodged			\$ 145.00
	Front Wheel Bearing ?			\$ 124.50
	Front Wheel Hub Assy ?			\$ 176.60

Page 2 of 3

SHA 4406L

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Windscreen Sealant <i>NEC</i>			\$ 46.00	Nett ✓
	Front Tyre (RH) <i>punctured 50% dpt</i>		<i>150/-</i>	\$ 207.00	Nett <i>75/-</i>
				\$ 253.00	
	Labour Charge				<i>1200/-</i>
	Panel Beating			\$ 1,500.00	<i>1000/-</i>
	Spray Painting Charge			\$ 950.00	<i>750/-</i>
	Wiring Charge			\$ 100.00	<i>30/-</i>
	Tuff Kote			\$ 150.00	<i>40/-</i>
	Towing Charge <i>receipt</i>			\$ 50.00	<i>?</i>
	Front Chassis Alignment Charge			\$ 400.00	<i>150/-</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	<i>80/-</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00	<i>80/-</i>
	Remove/Refix Undercarriage (FRT)			\$ 400.00	<i>250/-</i>
	FRT Wheel Alignment			\$ 120.00	<i>60/-</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00	<i>80/-</i>
	Remove/Refix Gearbox			\$ 500.00	<i>NW</i>
	Remove/Refix Dashboard			\$ 350.00	<i>NW</i>
	Remove/Refix Power Steering Pump			\$ 150.00	<i>80/-</i>
	TOTAL LABOUR			\$ 5,090.00	
	ESTIMATE TOTAL			\$ 51,994.57	
	<i>15/12/2014 @ 1030hrs</i>				
	<i>Not Authorized.</i>				
	<i>2/5mm 10 dgs.</i>				
	<i>Bryan</i>				
	<i>2 Kk Auto</i>				
	<i>* check MV</i>				
	<i>* wheel alignment.</i>				
	<i>* PMA after repair.</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					