

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3708L

DATE 16/4/2015 13:04

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>deform</i>			\$ 603.60 ✓
	Rear Bumper Reinforcement <i>svc</i>			\$ 504.36 +
	Rear Bumper Reinforcement Bracket (LH/RH) <i>svc</i>		\$ 180.00	\$ 360.00 +
	Rear Bumper Side Bracket <i>cra</i>			\$ 49.00 ✓
	Rear Bumper Sponge <i>svc</i>			\$ 143.40 +
	Rear Bumper Under Cover <i>svc</i>			\$ 225.00 X
	Tail Lamp (RH) <i>crushed</i>			\$ 545.90 ✓
	Tail Lamp Quarter Panel RH <i>repair</i>			\$ 97.92 +
	Rear Fender (RH) <i>repair</i>			\$ 2,020.08 X
	Rear Fender Inner Lining (RH) <i>svc</i>			\$ 164.40 +
	Rear Windscreen Moulding <i>an</i>			\$ 62.16 +
	SUB TOTAL			\$ 4,775.82
	LESS 20%			\$ 955.16
	DISCOUNTED TOTAL			\$ 3,820.66
	Rear Bumper Reverse Sensor <i>m</i>			\$ 135.70 Nett X
	Rear Bumper Rubber Mat <i>nec</i>			\$ 50.00 Nett ✓
	Rear Windscreen Sealant <i>m</i>			\$ 46.00 Nett X
				\$ 231.70
	Labour Charge			
	Panel Beating		300	\$ 850.00
	Spray Painting Charge		360	\$ 400.00
	Wiring Charge		30	\$ 50.00
	Tuff Kote		30	\$ 50.00
	Remove/Refix Cushion & Upholstery Rear		60	\$ 150.00
	Remove/Refix Rear Windscreen Glass		X	\$ 120.00
	TOTAL LABOUR			\$ 1,620.00
	ESTIMATE TOTAL			\$ 5,672.36
3day PIP B4 paint photo LKK Henry 97884060 16/4/15 1400hrs				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				