



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5653Y

| Qty | Description of Parts               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b> |                      |                           |                   |
| 1   | BUMPER COVER FRT                   | BUCKLED              | 968.79                    | 968.79            |
| 1   | BUMPER SPOILER FRT                 | DISTORTED            | 139.81                    | 139.81            |
| 1   | BUMPER ABSORBER FRT                | SERVICEABLE          | 303.60                    | -                 |
| 1   | BUMPER BRACKET FRT LH              | TO REPAIR SEE LABOUR | 116.47                    | -                 |
| 1   | BUMPER SUPPORT FRT LH              | TO REPAIR SEE LABOUR | 18.37                     | -                 |
| 1   | BUMPER BRACKET FRT RH              | TO REPAIR SEE LABOUR | 115.98                    | -                 |
| 1   | BUMPER SUPPORT FRT RH              | TO REPAIR SEE LABOUR | 18.37                     | -                 |
| 1   | BUMPER UNDERTRAY FRT               | SERVICEABLE          | 363.71                    | -                 |
| 1   | BUMPER GRILLE LOWER FRT            | DISTORTED / DENTED   | 205.23                    | 205.23            |
| 1   | BUMPER FOG LAMP GRILLE LH          | SERVICEABLE          | 159.39                    | -                 |
| 1   | BUMPER FOG LAMP GRILLE RH          | SERVICEABLE          | 159.39                    | -                 |
| 1   | BUMPER BEAM FRT                    | SERVICEABLE          | 703.14                    | -                 |
| 1   | RADIATOR GRILLE                    | CRACKED              | 1,313.68                  | 1,313.68          |
| 1   | RADIATOR GRILLE BADGE 'RENAULT'    | NECESSARY            | 173.36                    | 173.36            |
| 1   | RADIATOR GRILLE FRAME              | CRACKED              | 1,041.35                  | 1,041.35          |
| 1   | FRAME FULL SUPPORT PANEL           | SERVICEABLE          | 473.77                    | -                 |
| 1   | FRAME FULL SUPPORT BRACKET         | SERVICEABLE          | 69.07                     | -                 |
| 1   | FRONT BRACE PANEL                  | TO REPAIR SEE LABOUR | 136.32                    | -                 |
| 1   | SUBFRAME OUTER FRT                 | SERVICEABLE          | 2,040.34                  | -                 |
| 1   | HEADLAMP LH                        | DENTED               | 911.10                    | 911.10            |
| 1   | HEADLAMP PANEL FRT LH              | TO REPAIR SEE LABOUR | 134.59                    | -                 |
| 1   | HEADLAMP RH                        | SERVICEABLE          | 911.10                    | -                 |
| 1   | HEADLAMP PANEL FRT RH              | TO REPAIR SEE LABOUR | 134.59                    | -                 |
| 1   | HORN L70Y LH                       | SERVICEABLE          | 241.67                    | -                 |
| 1   | HORN L70Y RH                       | SERVICEABLE          | 241.67                    | -                 |

Report Ref No. CC3/TP15011379/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

| Qty | Description of Parts        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------|----------------------|---------------------------|-------------------|
| 1   | HORN BRACKET                | TO REPAIR SEE LABOUR | 31.12                     | -                 |
| 1   | BONNET                      | TO REPAIR SEE LABOUR | 1,493.56                  | -                 |
| 1   | BONNET INSULATOR            | SERVICEABLE          | 312.10                    | -                 |
| 1   | BONNET STRUT LH             | SERVICEABLE          | 166.29                    | -                 |
| 1   | BONNET STRUT RH             | SERVICEABLE          | 166.29                    | -                 |
| 1   | BONNET HINGE LH             | TO REPAIR SEE LABOUR | 267.93                    | -                 |
| 1   | BONNET HINGE RH             | TO REPAIR SEE LABOUR | 267.93                    | -                 |
| 1   | BONNET LOCK                 | TO REPAIR SEE LABOUR | 234.99                    | -                 |
| 1   | BONNET CABLE                | SERVICEABLE          | 91.69                     | -                 |
| 1   | FENDER PANEL FRT LH         | TO REPAIR SEE LABOUR | 602.95                    | -                 |
| 1   | FENDER PANEL FRT RH         | TO REPAIR SEE LABOUR | 602.95                    | -                 |
| 1   | WHEELARCH FRT LH            | SERVICEABLE          | 107.32                    | -                 |
| 1   | WHEELARCH FRT RH            | SERVICEABLE          | 214.49                    | -                 |
| 1   | RADIATOR                    | SERVICEABLE          | 924.77                    | -                 |
| 1   | ENGINE UNDERTRAY            | SERVICEABLE          | 434.60                    | -                 |
| 1   | A/C CONDENSER               | PUNCTURE             | 1,554.13                  | 1,554.13          |
| 1   | TRANSMISSION COOLER         | SERVICEABLE          | 852.66                    | -                 |
| 1   | DOOR PANEL REAR LH          | TO REPAIR SEE LABOUR | 2,188.20                  | -                 |
| 1   | DOOR SEAL REAR LH           | SERVICEABLE          | 68.02                     | -                 |
| 1   | DOOR PANEL REAR RH          | TO REPAIR SEE LABOUR | 2,188.20                  | -                 |
| 1   | DOOR SEAL REAR RH           | SERVICEABLE          | 68.02                     | -                 |
| 1   | BUMPER COVER REAR           | BENT                 | 852.66                    | 852.66            |
| 1   | BUMPER BRACKET CTR REAR     | CRACKED              | 87.29                     | 87.29             |
| 1   | BUMPER BRACKET SIDE LH REAR | DISTORTED            | 34.61                     | 34.61             |
| 1   | BUMPER RETAINER LH REAR     | NO SUCH PARTS        | 104.59                    | -                 |
| 1   | BUMPER BRACKET SIDE RH REAR | DISTORTED            | 34.61                     | 34.61             |
| 1   | BUMPER RETAINER RH REAR     | NO SUCH PARTS        | 104.59                    | -                 |
| 1   | BUMPER LOWER REAR           | BENT                 | 591.41                    | 591.41            |

Report Ref No. CC3/TP15011379/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

| Qty | Description of Parts        | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------|----------------------|---------------------------|-------------------|
| 1   | BUMPER BEAM REAR            | BENT                 | 598.08                    | 598.08            |
| 1   | BUMPER BEAM BRACKET LH REAR | BENT                 | 173.81                    | 173.81            |
| 1   | BUMPER BEAM BRACKET RH REAR | BENT                 | 173.81                    | 173.81            |
| 1   | BUMPER REFLECTOR LH         | SERVICEABLE          | 33.55                     | -                 |
| 1   | BUMPER REFLECTOR RH         | BROKEN               | 33.55                     | 33.55             |
| 1   | BOOT REAR                   | BENT                 | 2,209.75                  | 2,209.75          |
| 1   | BOOT FINISHER               | SERVICEABLE          | 361.58                    | -                 |
| 1   | BOOT LOCK                   | DENTED               | 155.90                    | 155.90            |
| 1   | BOOT LOCK CATCH             | DISTORTED            | 57.23                     | 57.23             |
| 1   | BOOT WEATHERSTRIP           | DISTORTED / CUT      | 248.50                    | 248.50            |
| 1   | BOOT REFLECTOR LAMP LH      | SERVICEABLE          | 379.50                    | -                 |
| 1   | BOOT REFLECTOR LAMP RH      | CRACKED              | 379.50                    | 379.50            |
| 1   | BOOT BADGE 'RENAULT'        | NECESSARY            | 173.35                    | 173.35            |
| 1   | BOOT BADGE                  | NECESSARY            | 173.35                    | 173.35            |
| 1   | BOOT STRUT LH               | SERVICEABLE          | 212.36                    | -                 |
| 1   | BOOT STRUT RH               | SERVICEABLE          | 212.36                    | -                 |
| 1   | BOOT HINGE RH               | TO REPAIR SEE LABOUR | 282.96                    | -                 |
| 1   | BOOT HINGE LH               | TO REPAIR SEE LABOUR | 282.96                    | -                 |
| 2   | LICENCE PLATE LAMP          | SERVICEABLE          | 84.00                     | -                 |
| 2   | BOOT RUBBER PLUG            | SERVICEABLE          | 170.63                    | -                 |
| 1   | WINDSCREEN REAR             | SERVICEABLE          | 1,125.60                  | -                 |
| 1   | TAILLAMP LH                 | SERVICEABLE          | 425.04                    | -                 |
| 1   | TAILLAMP PANEL LH           | TO REPAIR SEE LABOUR | 759.00                    | -                 |
| 1   | TAILLAMP RH                 | BROKEN               | 425.04                    | 425.04            |
| 1   | TAILLAMP PANEL RH           | BENT                 | 759.00                    | 759.00            |
| 1   | FENDER PANEL REAR LH        | TO REPAIR SEE LABOUR | 2,537.80                  | -                 |
| 1   | FENDER PANEL REAR RH        | BUCKLED              | 2,537.80                  | 2,537.80          |
| 1   | FENDER WHEELARCH REAR LH    | TO REPAIR SEE LABOUR | 418.06                    | -                 |
| 1   | FENDER WHEELARCH REAR RH    | TO REPAIR SEE LABOUR | 418.06                    | -                 |

Report Ref No. CC3/TP15011379/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

| Qty | Description of Parts                         | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| 1   | AIR VENT RH                                  | SERVICEABLE          | 74.83                     | -                 |
| 1   | FENDER PANEL INNER TRIM REAR RH              | DEFORMED             | 516.50                    | 516.50            |
| 1   | FENDER PANEL INNER TRIM REAR LH              | SERVICEABLE          | 516.50                    | -                 |
| 1   | FENDER WHEEL HOUSE PANEL REAR LH             | TO REPAIR SEE LABOUR | 2,337.72                  | -                 |
| 1   | FENDER WHEEL HOUSE PANEL REAR RH             | TO REPAIR SEE LABOUR | 2,337.72                  | -                 |
| 1   | SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)      | BENT / BUCKLED       | 1,684.52                  | 1,684.52          |
| 1   | SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL) | DEFORMED             | 470.93                    | 470.93            |
| 1   | OUTER PANEL REAR (END PANEL)                 | BENT                 | 1,132.13                  | 1,132.13          |
| 1   | OUTER PANEL REAR (END PANEL)TRIM             | DENTED               | 308.48                    | 308.48            |
| 1   | EXHAUST REAR                                 | BENT                 | 5,760.00                  | 5,760.00          |
| 1   | EXHAUST CAP REAR                             | BENT                 | 177.30                    | 177.30            |
| 1   | WINDSCREEN REAR                              | REPEATED             | 1,125.60                  | -                 |
|     | LESS 10% DISCOUNT                            |                      | -5,798.72                 | -2,605.66         |
|     |  |                      | 52,188.47                 | 23,450.90         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>             |                      |                           |                   |
| 1   | SET RADIATOR GRILLE FRAME CLIP (SN)          | NECESSARY            | 52.00                     | 52.00             |
| 1   | SET BUMPER CLIP FRT (SN)                     | NECESSARY            | 66.00                     | 66.00             |
| 1   | TOW COVER FRT (SN)                           | SERVICEABLE          | 14.50                     | -                 |
| 1   | SET RADIATOR GRILLE SCREW (SN)               | NECESSARY            | 16.00                     | 16.00             |
| 1   | SET BUMPER GRILLE LOWER CLIP (SN)            | NECESSARY            | 69.00                     | 69.00             |
| 1   | SET FRAME FULL SUPPORT PANEL CLIP (SN)       | NECESSARY            | 70.00                     | 70.00             |
| 2   | FRAME FULL SUPPORT PANEL NUT (SN)            | SERVICEABLE          | 20.00                     | -                 |
| 2   | FRAME FULL SUPPORT PANEL STUD (SN)           | SERVICEABLE          | 30.00                     | -                 |
| 2   | BONNET CABLE CLIP (SN)                       | NOT NECESSARY        | 6.40                      | -                 |
| 1   | SET WHEELARCH CLIP LH (SN)                   | NOT NECESSARY        | 30.50                     | -                 |
| 1   | SET WHEELARCH CLIP RH (SN)                   | NOT NECESSARY        | 29.40                     | -                 |
| 1   | SET DOOR CASING CLIP (SN)                    | NOT NECESSARY        | 6.40                      | -                 |
| 1   | SET DOOR SEAL CLIP FRT RH (SN)               | NOT NECESSARY        | 18.50                     | -                 |
| 1   | DOOR STICKER 'TRANS-CAB' LH (SN)             | NOT NECESSARY        | 80.00                     | -                 |
| 1   | DOOR STICKER 'CLASSIC' LH (SN)               | NOT NECESSARY        | 30.00                     | -                 |
| 1   | DOOR STICKER 'TRANS-CAB' RH (SN)             | NOT NECESSARY        | 80.00                     | -                 |

Report Ref No. CC3/TP15011379/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

| Qty | Description of Parts                     | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| 1   | DOOR STICKER 'CLASSIC' RH (SN)           | NOT NECESSARY        | 30.00                     | -                 |
| 1   | RIM RH RR (SN)                           | SERVICEABLE          | 385.00                    | -                 |
| 1   | TYRE RH RR (SN)                          | SERVICEABLE          | 330.00                    | -                 |
| 1   | SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)   | SERVICEABLE          | 385.00                    | -                 |
| 1   | SPARE TYRE (SN)                          | SERVICEABLE          | 330.00                    | -                 |
| 1   | SET WHEELARCH CLIP LH RR (SN)            | NOT NECESSARY        | 32.34                     | -                 |
| 1   | SET WHEELARCH CLIP RH RR (SN)            | NOT NECESSARY        | 32.34                     | -                 |
| 1   | SET PARKING AID (SN)                     | TORN                 | 600.00                    | 600.00            |
| 1   | SET BUMPER RR RIVET (SN)                 | NECESSARY            | 28.60                     | 28.60             |
| 1   | SET BUMPER RR CLIP (SN)                  | NECESSARY            | 66.00                     | 66.00             |
| 1   | SET REFLECTOR SCREW (NECESSARY) (SN)     | NOT NECESSARY        | 25.00                     | -                 |
| 1   | SET BUMPER BEAM BOLT (NECESSARY) (SN)    | SERVICEABLE          | 22.22                     | -                 |
| 2   | DOOR STICKER '6555-3333' LH/RH (SN)      | NOT NECESSARY        | 160.00                    | -                 |
| 1   | SET BOOT FINISHER CLIP (SN)              | NOT NECESSARY        | 25.10                     | -                 |
| 1   | REAR BOOT STICKER 'TRANS-CAB' (SN)       | NECESSARY            | 30.00                     | 30.00             |
| 1   | REAR BOOT STICKER '6555-3333' (SN)       | NECESSARY            | 30.00                     | 30.00             |
| 2   | REAR WINDSCREEN SEALANT (SN)             | NECESSARY            | 80.00                     | 40.00             |
| 1   | WINDSCREEN MOULDING (SN)                 | NECESSARY            | 100.00                    | 30.00             |
| 1   | REAR WINDSCREEN INNER SPONGE SEAL (SN)   | NOT NECESSARY        | 100.00                    | -                 |
| 1   | EXHAUST MOUNTING REAR (SN)               | TORN                 | 65.50                     | 65.50             |
| 1   | EXHAUST BRACKET REAR (SN)                | TO REPAIR SEE LABOUR | 22.22                     | -                 |
| 1   | SET FRONT LICENCE PLATE WITH HOLDER (SN) | BENT                 | 80.00                     | 45.00             |
| 1   | SET REAR LICENCE PLATE WITH HOLDER (SN)  | DENTED               | 80.00                     | 45.00             |
|     |  |                      | 3,658.02                  | 1,253.10          |

Report Ref No. CC3/TP15011379/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

| Qty | Description of Parts   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
|     | <b><u>LABOUR</u></b>   |               |                           |                   |
|     | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BRACKET FRT LH,BUMPER SUPPORT FRT LH,BUMPER BRACKET FRT RH,BUMPER SUPPORT FRT RH,FRONT BRACE PANEL,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,HORN BRACKET,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,FENDER PANEL FRT LH,FENDER PANEL FRT RH,DOOR PANEL REAR LH,DOOR PANEL REAR RH, } |               | 16,800.00                 | 2,400.00          |
|     | BOOT HINGE LH,BOOT HINGE RH,TAILLAMP PANEL LH,FENDER PANEL REAR LH,FENDER WHEELARCH REAR LH,FENDER WHEELARCH REAR RH,FENDER WHEEL HOUSE PANEL REAR LH,FENDER WHEEL HOUSE PANEL REAR RH AND EXHAUST BRACKET REAR. }   |               | -                         | -                 |
|     | TOWING FEES.   |               | 120.00                    | 50.00             |
|     | TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT .  | NOT NECESSARY | 380.00                    | -                 |
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .   |               | 18,000.00                 | 1,760.00          |
|     | TO RUST-PROOFING OF THE AFFECTED AREAS .   |               | 170.00                    | 150.00            |
|     | TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR-CONDENSER .   |               | 380.00                    | 100.00            |
|     | TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INTERCOOLER.  |               | 170.00                    | 50.00             |
|     | TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR .  |               | 170.00                    | 50.00             |
|     | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.   |               | 380.00                    | 120.00            |
|     | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.   |               | 220.00                    | 60.00             |
|     | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.   | NOT NECESSARY | 170.00                    | -                 |
|     | TO CHECK ABS BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING.   | NOT NECESSARY | 380.00                    | -                 |
|     | TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.}   |               | 380.00                    | 250.00            |

Report Ref No. CC3/TP15011379/Kpa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

| Qty                | Description of Parts   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|--|---------------|---------------------------|-------------------|
|                    | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR .}                        |               | 380.00                    | -                 |
|                    | TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                                | NOT NECESSARY | 170.00                    | -                 |
|                    | TO CHECK ELECTRICAL LIGHTING CONCERNED.  |               | 170.00                    | 40.00             |
|                    | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                      | NOT NECESSARY | 170.00                    | -                 |
|                    | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.            | NOT NECESSARY | 170.00                    | -                 |
|                    | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.   |               | 380.00                    | 80.00             |
|                    | TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                             |               | 170.00                    | 60.00             |
|                    | TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                         | NOT NECESSARY | 380.00                    | -                 |
|                    | TO TRANSFER OF REAR WINDSCREEN FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                     |               | 380.00                    | 120.00            |
|                    | TO REINSTALL REAR BUMPER PARKING SENSOR .  |               | 170.00                    | 60.00             |
|                    | TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.}                    |               | 280.00                    | 80.00             |
|                    | TO REPAIR AND REALIGN REAR EXHAUST PIPE.}  |               | 170.00                    | -                 |
|                    | TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING .                            |               | 380.00                    | 240.00            |
|                    | TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY ,REMOVE AND RENEWAL OF PARTS ,FINAL CHECKING AND TESTING . | NOT NECESSARY | 380.00                    | -                 |
|                    |  |               | 41,470.00                 | 5,670.00          |
| <b>GRAND TOTAL</b> |  |               | <b>97,316.49</b>          | <b>30,374.00</b>  |

|   |  |  |                  |
|---|--|--|------------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>27,300.00</b> |
|---|--|--|------------------|

Report Ref No. CC3/TP15011379/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.