



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 01.11.2018

Survey Details:

Date of loss	11.12.2015
Date of appointment	16.12.2015
Date of survey	16.12.2016
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHB 9913B
Make and Model	Renault Latitude (1995cc)
Date of registration	16.09.2013
Excess	NIL
Market Value/ Book Value	\$ 83,170.00 (est)
Parf/COE Rebate	\$ 51,164.00 (est)
Nett Loss	\$ 32,006.00 (est)

Repair details:

Initial Estimate	\$ 130,561.77
------------------	---------------

Proposed/Revised repair cost:

Parts	\$ 36,126.71
Check items (estimate)	NIL
Labour	\$ 6,290.00
Supplementary	
Total	\$ 42,416.71
Lump Sum(if applicable)	\$ 32,000.00

Number of days for repair	<u>26</u>
---------------------------	-----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date:

Remarks:

*Recommended 26 repair days + 4 Sunday + 2 PH + 1 Inspection =
33 days*

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 34,240.00	
Loss of use	NIL	
Loss of rental	\$ 4,237.20	(33days x \$128.40)
Loss of income	\$ 1,650.00	(33days x \$50.00)
LTA/GIA search fees	\$ 5.35	
Others	NIL	
Proposed Total	\$ 40,132.55	

Print Received Message

This mail is associated with :

***SHB9913B (C0364364)**

[YM6544T]

TP

TRANS-CAB SERVICES PTE LTD

Dec 11 2015 12:00AM

[KUAN AIK HONG CONSTRUCTION PTE LTD]

Trans-cab Auto Services Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 20/11/2018 22:09 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$36000.00) - SHB9913B - Claim Handler: Khor Saw Theng

Approved:36000.00:btw, what is your breakdown of claim. how you derived with \$40,132.55?

Print Sent Message

This mail is associated with :

***SHB9913B (C0364364)**

[YM6544T]

TP

TRANS-CAB SERVICES PTE LTD

Dec 11 2015 12:00AM

[KUAN AIK HONG CONSTRUCTION PTE LTD]

Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 23/11/2018 08:16 AM.
To sawtheng.khor@axa.com.sg
CC AXA_SG; chewht@lkkauto.com
Subject RE: Alert - Adj Mandate Approved (S\$36000.00) - SHB9913B - Claim Handler: Khor Saw Theng

Hi Saw Theng,

We will proceed to offer third party as per mandate amount of \$36K(all-in).

Kindly refer to IA (with mandate) dd 011118 uploaded in Merimen. The breakdown is as follows: -

Liability(TP) 100%

Proposed repair cost (w/GST): \$ 34,240.00

Loss of rental: \$ 4,237.20 (33days x \$128.40)

Loss of income: \$ 1,650.00 (33days x \$50.00)

LTA/GIA search fees: \$ 5.35

Proposed Total: **\$ 40,132.55**

We will update if there is any issue.

Thank you.

Hsiao Tong

<-- Original Message -->

From: AXA_SG

To: LKK_HQ

Sent On: 20/11/2018 10:09 PM

Subject: Alert - Adj Mandate Approved (S\$36000.00) - SHB9913B - Claim Handler: Khor Saw Theng

Approved:36000.00:btw, what is your breakdown of claim. how you derived with \$40,132.55?

Hsiao Tong (LKKAUTO)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Thursday, 13 December 2018 11:43 AM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'; 'Zhe Wei'; claims@transcab.com.sg
Subject: RE: Your ref: AAD1512 -145 (SHB 9913B) *Our Ref: CC3/AXA15021629/Kpa3
[ACCIDENT INVOLVING YM 6544T(AXA) /SHB 9913B/ OTHERS ON 11/12/2015]

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Saturday, 24 November 2018 8:24 AM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; 'Zhe Wei' (zhewei.kek@transcab.com.sg) <zhewei.kek@transcab.com.sg>; claims@transcab.com.sg
Subject: Your ref: AAD1512 -145 (SHB 9913B) *Our Ref: CC3/AXA15021629/Kpa3 [ACCIDENT INVOLVING YM 6544T(AXA) /SHB 9913B/ OTHERS ON 11/12/2015]

Your ref: **AAD1512 -145 (SHB 9913B)**
Our Ref: CC3/AXA15021629/Kpa3

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING YM 6544T(AXA) /SHB 9913B/ OTHERS ON 11/12/2015

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$36,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

81 File incurred >\$40k

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Dec 2015		18 Dec 2015 10:43 Edit Adj Rpt	\$32,000.00 Edit Estimates	\$32,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KUAN AIK HONG CONSTRUCTION PTE LTD , Co. Reg. No.: 199901484R		
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHB9913B	Date of Loss:	11/12/2015 00:00 - :59 [26 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0364364	Policy/Cover Note No.:	P1621969 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	YM6544T	Policy No. (Claimant):	APX/P1680520
		Excess:	\$0.00
Repairer:	Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1, 729346 Sungei Kadut - Tel: 62876666		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Khor Saw Theng - 6880 4754]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/12/2015]		
Driver/Custodian (Insured):	NAGARAJ JAYAMURUGAN (32 / Male), NRIC: G8315954K		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (20/11/2018): **Alert - Adj Mandate Approved (\$36000.00) - SHB9913B - Claim Handler: Khor Saw T...**
- AXA_SG (11/09/2018): **Re: Pls submit Final Report**
- AXA_SG (23/05/2017): **C0364364 / YM6544T / SHB9913B**
- AXA_SG (16/02/2017): **Re: Fw: Re: Direct Settlement - Accident Involving YM6544T (OI : AXA - C0364364)...**
- AXA_SG (15/02/2017): **Re: Direct Settlement - Accident Involving YM6544T (OI : AXA - C0364364) and SHB...**
- AXA_SG (18/12/2015): **New TP Assignment - C0364364/P1621969**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB9913B (C0364364)**
[YM6544T]

TP

TRANS-CAB SERVICES PTE LTD

Dec 11 2015 12:00AM

[KUAN AIK HONG CONSTRUCTION PTE LTD]

Trans-cab Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/12/15 15:36	Adjuster Immediate Advice	1	Load HTM	

Documentation

1 per page

No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	18/12/15 09:27	EMAIL_ABS	1	Load PDF	
2	18/12/15 09:27	ESTIMATE_ABS	1	Load PDF	
3	18/12/15 09:27	GIA SHC6769R_ABS	1	Load PDF	
4	18/12/15 09:27	GIA SKK7331K_ABS	1	Load PDF	
5	18/12/15 09:28	GIA SKW1063K_ABS	1	Load PDF	
6	18/12/15 09:28	GIA YM6544T (INSD)_ABS	1	Load PDF	
7	18/12/15 09:58	TP POLICE REPORT_ABS	1	Load PDF	
8	18/12/15 09:58	SHB9913B TP GIA REPORT_ABS	1	Load PDF	
9	18/12/15 10:43	Certificate of Insurance	1	Load PDF	
10	18/12/15 10:43	Certificate Schedule NO TP EXCESS	1	Load PDF	
11	09/03/16 11:19	Driver's Driving License - Foreign DL_front	1	Load PDF	
12	09/03/16 11:19	Driver's Driving License - Foreign DL_back	1	Load PDF	

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/12/15 17:39	Letter to OI	1	Load PDF	
2	01/11/18 10:10	LKK Survey Photos	1	Load PDF	
3	01/11/18 10:10	LKK Resurvey Photos 1	1	Load PDF	
4	01/11/18 10:10	LKK Resurvey Photos 2	1	Load PDF	
5	01/11/18 10:20	PARF_COE REBATE	1	Load PDF	
6	01/11/18 10:30	RENTAL & LOG BOOK	1	Load PDF	
7	01/11/18 10:30	LTA	1	Load PDF	
8	01/11/18 10:40	IA (with mandate) dd 011118	1	Load PDF	
9	14/01/19 08:43	AUTHORISATION TO ACT	1	Load PDF	
10	14/01/19 08:43	DISCHARGE VOUCHER	1	Load PDF	
11	14/01/19 08:43	LOD	1	Load PDF	
12	14/01/19 08:43	WORKSHOP INVOICE	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YM6544T (Insd veh)	Model:	RENAULT LATITUDE 2.0 L DCI
	SHB9913B (TP veh)		AUTO D/AB 4DR (A)
Date of Accident:	11/12/2015		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	139,701.14
Final Repair Cost	:	\$	34,240.00
Loss of Token Sum	:	\$	1,500.00
Rental (if any)	:	\$	3,852.00
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	36,000.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)
** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks: PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	:	\$ 36,000.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

14 Jan
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA15021629/KPA3S2

Date: 14/01/2019

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1621969
Claimant Vehicle No :	SHB9913B	Insured Vehicle No :	YM6544T
Date of Loss:	11/12/2015	Nature of Claim:	TP
		Claim No:	C0364364

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9913B		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C000242
Reg. Date:	16/09/2013 (Man. Year: 2013)	Chassis No:	VF1ABL15AUC273095
Colour:	Metallic White/Red	Odometer:	280073 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Rovelo 9 mm	Rear Left Side:	Rovelo 8 mm
Front Right Side:	Rovelo 9 mm	Rear Right Side:	Rovelo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	89,601.81	36,126.62	53,475.19	59.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	40,960.00	6,290.00	34,670.00	84.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	130,561.81	42,416.62	88,145.19	67.51
Approved Total (Overridden) (S\$)		32,000.00		
(S\$)	130,561.81	32,000.00	98,561.81	75.49
+ GST 7.00/7.00% (S\$)	9,139.33	2,240.00	6,899.33	75.49
Nett Amount (S\$)	139,701.14	34,240.00	105,461.14	75.49
+ Loss of Use (30.0 x S\$50.00/day) (S\$)		1,500.00		
+ Car Rental (30.0 x S\$128.40/day) (S\$)		3,852.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		39,597.35		
Global Sum Settlement (S\$)		36,000.00		

INSPECTION

Date of Assignment: 18/12/2015

Date Inspected:

16/12/2015

Inspected At:

Trans-cab Auto Services Pte Ltd (HQ)
No. 42 Sungei Kadut St 1
Singapore 729346

Estimated Period of Repair: 26.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 11 Jan 2019)

Parts: 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB9913B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (CONSISTENT)	Buckled / Cracked	968.79 FL	*968.79 FL
2	1		*BUMPER SPOILER FRT (CONSISTENT)	Distorted	139.81 FL	*139.81 FL
3	1		*BUMPER ABSORBER FRT (CONSISTENT)	Cracked	303.60 FL	*303.60 FL
4	1		*BUMPER RETAINER FRT LH (CONSISTENT)	Distorted	116.47 FL	*116.47 FL
5	1		*BUMPER SUPPORT FRT (HEADLAMP LOWER) (CONSISTENT)	Distorted	18.37 FL	*18.37 FL
6	1		*BUMPER RETAINER FRT RH (CONSISTENT)	Distorted	115.98 FL	*115.98 FL
7	1		*BUMPER SUPPORT FRT RH (HEADLAMP LOWER) (CONSISTENT)	Distorted	18.37 FL	*18.37 FL
8	1		*BUMPER UNDERTRAY FRT (CONSISTENT)	Serviceable	363.71 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT (CONSISTENT)	Distorted	205.23 FL	*205.23 FL
10	1		*BUMPER FOG LAMP GRILLE LH (CONSISTENT)	Serviceable	159.39 FL	*- FL
11	1		*BUMPER FOG LAMP GRILLE RH (CONSISTENT)	Serviceable	159.39 FL	*- FL
12	1		*BUMPER BEAM FRT (CONSISTENT)	Bent	703.14 FL	*703.14 FL
13	1		*RADIATOR GRILLE (CONSISTENT)	Cracked	1,313.68 FL	*1,313.68 FL
14	1		*RADIATOR GRILLE BADGE RENAULT (CONSISTENT)	Necessary	173.36 FL	*173.36 FL
15	1		*RADIATOR GRILLE FRAME (CONSISTENT)	Broken	1,041.35 FL	*1,041.35 FL
16	1		*FRAME FULL SUPPORT PANEL (CONSISTENT)	Cracked	473.77 FL	*473.77 FL
17	1		*FRAME FULL SUPPORT BRACKET (CONSISTENT)	Bent	69.07 FL	*69.07 FL
18	1		*FRONT BRACE PANEL (CONSISTENT)	Bent	136.32 FL	*136.32 FL
19	1		*SUBFRAME OUTER FRT (CONSISTENT)	Serviceable	2,040.34 FL	*- FL
20	1		*HORN LH (CONSISTENT)	Cracked	241.67 FL	*241.67 FL
21	1		*HORN RH (CONSISTENT)	Cracked	241.67 FL	*241.67 FL
22	1		*HORN BRACKET (CONSISTENT)	Repair	31.12 FL	*- FL
23	1		*HEADLAMP LH (CONSISTENT)	Cracked	911.10 FL	*911.10 FL
24	1		*HEADLAMP HARNESS LH (CONSISTENT)	Serviceable	714.07 FL	*- FL
25	1		*HEADLAMP PANEL FRT LH (CONSISTENT)	Repair	134.59 FL	*- FL
26	1		*HEADLAMP RH (CONSISTENT)	Mtg Cracked	911.10 FL	*911.10 FL
27	1		*HEADLAMP HARNESS RH (CONSISTENT)	Serviceable	714.07 FL	*- FL
28	1		*HEADLAMP PANEL FRT RH (CONSISTENT)	Repair	134.59 FL	*- FL
29	1		*BONNET (CONSISTENT)	Bent	1,493.56 FL	*1,493.56 FL
30	1		*BONNET INSULATOR (CONSISTENT)	Serviceable	312.10 FL	*- FL
31	1		*BONNET STRUT LH (CONSISTENT)	Serviceable	166.29 FL	*- FL
32	1		*BONNET STRUT RH (CONSISTENT)	Serviceable	166.29 FL	*- FL
33	1		*BONNET HINGE LH (CONSISTENT)	Repair	267.93 FL	*- FL
34	1		*BONNET HINGE RH (CONSISTENT)	Repair	267.93 FL	*- FL
35	2		*BAL HOOD (CONSISTENT)	Serviceable	75.60 FL	*- FL
36	1		*BONNET LOCK (CONSISTENT)	Distorted	234.99 FL	*234.99 FL
37	1		*BONNET CABLE (CONSISTENT)	Serviceable	91.69 FL	*- FL
38	1		*BONNET CABLE COVER (CONSISTENT)	Serviceable	123.87 FL	*- FL
39	1		*BONNET SEAL OUTER (CONSISTENT)	Serviceable	71.04 FL	*- FL
40	1		*FENDER PANEL FRT LH (CONSISTENT)	Repair	602.95 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FENDER INSULATOR LH (CONSISTENT)	Serviceable	100.64 FL	*- FL
42	1		*FENDER PANEL BRACKET FRT LH (CONSISTENT)	Repair	161.52 FL	*- FL
43	1		*WHEEL HOUSING PANEL FRT LH (CONSISTENT)	Repair	3,601.61 FL	*- FL
44	1		*FENDER PANEL FRT RH (CONSISTENT)	Bent	602.95 FL	*602.95 FL
45	1		*FENDER INSULATOR RH (CONSISTENT)	Serviceable	100.64 FL	*- FL
46	1		*FENDER PANEL BRACKET FRT RH (CONSISTENT)	Repair	161.52 FL	*- FL
47	1		*WHEEL HOUSING PANEL FRT RH (CONSISTENT)	Repair	3,601.61 FL	*- FL
48	1		*FENDER WHEELARCH FRT LH (LINNER) (CONSISTENT)	Serviceable	107.32 FL	*- FL
49	1		*FENDER WHEELARCH FRT RH (LINNER) (CONSISTENT)	Serviceable	214.49 FL	*- FL
50	1		*WINDSCREEN FRT (CONSISTENT)	Cracked	1,327.34 FL	*1,327.34 FL
51	1		*WIPER RESERVOIR (CONSISTENT)	Serviceable	190.96 FL	*- FL
52	1		*WIPER RESERVOIR NECK (CONSISTENT)	Serviceable	27.78 FL	*- FL
53	1		*WIPER RESERVOIR MOTOR (CONSISTENT)	Serviceable	100.95 FL	*- FL
54	1		*RADIATOR (CONSISTENT)	Serviceable	924.77 FL	*- FL
55	1		*RADIATOR MTG LOWER (CONSISTENT)	Serviceable	42.96 FL	*- FL
56	1		*RADIATOR FAN COWLING (CONSISTENT)	Serviceable	631.18 FL	*- FL
57	1		*RADIATOR FAN MOTOR LH (CONSISTENT)	Serviceable	744.12 FL	*- FL
58	1		*RADIATOR FAN MOTOR RH (CONSISTENT)	Serviceable	1,138.04 FL	*- FL
59	1		*RADIATOR TANK (CONSISTENT)	Serviceable	249.71 FL	*- FL
60	1		*RADIATOR TANK CAP (CONSISTENT)	Serviceable	37.95 FL	*- FL
61	1		*AIR CLEANER HOSE (CONSISTENT)	Serviceable	58.57 FL	*- FL
62	1		*AIR CLEANER LOWER (CONSISTENT)	Serviceable	311.95 FL	*- FL
63	1		*ENGINE UNDERTRAY (CONSISTENT)	Serviceable	434.60 FL	*- FL
64	1		*A/C CONDENSER (CONSISTENT)	Punctured	1,554.13 FL	*1,554.13 FL
65	1		*TRANSMISSION COOLER (CONSISTENT)	Serviceable	852.66 FL	*- FL
66	1		*ENGINE UNDERTRAY (CONSISTENT)	Serviceable	434.60 FL	*- FL
67	1		*INJECTION COMPUTER M9R839 (CONSISTENT)	Serviceable	2,819.53 FL	*- FL
68	1		*STEERING PUMP ELECTRIC (CONSISTENT)	Serviceable	1,543.08 FL	*- FL
69	1		*DASHBOARD (CONSISTENT)	Serviceable	3,769.65 FL	*- FL
70	1		*DOOR PANEL FRT LH (CONSISTENT)	Repair	2,188.20 FL	*- FL
71	1		*DOOR MIRROR LH (CONSISTENT)	Serviceable	1,141.08 FL	*- FL
72	1		*DOOR SEAL FRT LH (CONSISTENT)	Serviceable	50.92 FL	*- FL
73	1		*DOOR PANEL FRT RH (CONSISTENT)	Repair	2,188.20 FL	*- FL
74	1		*DOOR MIRROR RH (CONSISTENT)	Serviceable	1,141.08 FL	*- FL
75	1		*DOOR SEAL FRT RH (CONSISTENT)	Serviceable	50.92 FL	*- FL
76	1		*BUMPER COVER REAR (CONSISTENT)	Bent	852.66 FL	*852.66 FL
77	1		*BUMPER BRACKET CTR REAR (CONSISTENT)	Cracked	87.29 FL	*87.29 FL
78	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER) (CONSISTENT)	Serviceable	34.61 FL	*- FL
79	1		*BUMPER RETAINER LH REAR (CONSISTENT)	Serviceable	104.59 FL	*- FL
80	1		*BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER) (CONSISTENT)	Cracked	34.61 FL	*34.61 FL
81	1		*BUMPER RETAINER RH REAR (CONSISTENT)	Cracked	104.59 FL	*104.59 FL
82	1		*BUMPER LOWER REAR (CONSISTENT)	Bent	591.41 FL	*591.41 FL
83	1		*BUMPER BEAM REAR (CONSISTENT)	Bent	598.08 FL	*598.08 FL
84	1		*BUMPER BEAM BRACKET LH REAR (CONSISTENT)	Bent	173.81 FL	*173.81 FL
85	1		*BUMPER BEAM BRACKET RH REAR (CONSISTENT)	Bent	173.81 FL	*173.81 FL
86	1		*BUMPER REFLECTOR LH (CONSISTENT)	Serviceable	33.55 FL	*- FL
87	1		*BUMPER REFLECTOR RH (CONSISTENT)	Broken	33.55 FL	*33.55 FL
88	1		*BOOT REAR (CONSISTENT)	Bent	2,209.75 FL	*2,209.75 FL
89	1		*BOOT FINISHER (MOULDING) (CONSISTENT)	Cracked	361.58 FL	*361.58 FL
90	1		*BOOT LOCK (CONSISTENT)	Bent	155.90 FL	*155.90 FL
91	1		*BOOT LOCK CATCH (CONSISTENT)	Repair	57.23 FL	*- FL
92	1		*BOOT WEATHERSTRIP (CONSISTENT)	Distorted / Cut	248.50 FL	*248.50 FL
93	1		*BOOT REFLECTOR LAMP LH (CONSISTENT)	Cracked	379.50 FL	*379.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
94	1		*BOOT REFLECTOR LAMP RH (CONSISTENT)	Cracked	379.50 FL	*379.50 FL
95	1		*BOOT BADGE RENAULT (CONSISTENT)	Necessary	173.35 FL	*173.35 FL
96	1		*BOOT BADGE (CONSISTENT)	Necessary	173.35 FL	*173.35 FL
97	1		*BOOT STRUT LH (CONSISTENT)	Serviceable	212.36 FL	*- FL
98	1		*BOOT STRUT RH (CONSISTENT)	Serviceable	212.36 FL	*- FL
99	1		*BOOT HINGE LH (CONSISTENT)	Bent	282.96 FL	*282.96 FL
100	1		*BOOT HINGE RH (CONSISTENT)	Bent	282.96 FL	*282.96 FL
101	2		*LICENCE PLATE LAMP (CONSISTENT)	Cracked	84.00 FL	*84.00 FL
102	2		*BOOT RUBBER PLUG (CONSISTENT)	Serviceable	170.63 FL	*- FL
103	1		*WINDSCREEN REAR (CONSISTENT)	Shattered	1,125.60 FL	*1,125.60 FL
104	1		*TAILLAMP LH (CONSISTENT)	Mtg Cracked	425.04 FL	*425.04 FL
105	1		*TAILLAMP PANEL LH (CONSISTENT)	Repair	759.00 FL	*- FL
106	1		*TAILLAMP RH (CONSISTENT)	Broken	425.04 FL	*425.04 FL
107	1		*TAILLAMP PANEL RH (CONSISTENT)	Bent	759.00 FL	*759.00 FL
108	1		*FENDER PANEL REAR LH (CONSISTENT)	Buckled	2,537.80 FL	*2,537.80 FL
109	1		*FENDER PANEL REAR RH (CONSISTENT)	Buckled / Bent	2,537.80 FL	*2,537.80 FL
110	1		*FENDER WHEELARCH REAR LH (LINER) (CONSISTENT)	Serviceable	418.06 FL	*- FL
111	1		*FENDER WHEELARCH REAR RH (LINER) (CONSISTENT)	Serviceable	418.06 FL	*- FL
112	1		*AIR VENT RH (CONSISTENT)	Serviceable	74.83 FL	*- FL
113	1		*FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	Cracked	516.50 FL	*516.50 FL
114	1		*FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	Cracked	516.50 FL	*516.50 FL
115	1		*FENDER WHEEL HOUSE PANEL REAR LH (CONSISTENT)	Repair	2,337.72 FL	*- FL
116	1		*FENDER WHEEL HOUSE PANEL REAR RH (CONSISTENT)	Repair	2,337.72 FL	*- FL
117	1		*REAR AXLE (CONSISTENT)	Serviceable	3,205.41 FL	*- FL
118	1		*AXLE ARM ROD (CONSISTENT)	Serviceable	90.17 FL	*- FL
119	1		*AXLE ARM RH (CONSISTENT)	Serviceable	90.17 FL	*- FL
120	1		*AXLE ARM LH (CONSISTENT)	Serviceable	90.17 FL	*- FL
121	1		*KNUCKLE ARM REAR RH (CONSISTENT)	Serviceable	566.67 FL	*- FL
122	1		*KNUCKLE ARM REAR LH (CONSISTENT)	Serviceable	566.67 FL	*- FL
123	1		*AXLE SPRING ARM RH (CONSISTENT)	Serviceable	289.94 FL	*- FL
124	1		*ALXE SPRING ARM LH (CONSISTENT)	Serviceable	289.94 FL	*- FL
125	1		*LOWER ARM REAR RH (CONSISTENT)	Serviceable	696.91 FL	*- FL
126	1		*LOWER ARM REAR LH (CONSISTENT)	Serviceable	696.91 FL	*- FL
127	1		*LOWER ARM BALANCER REAR RH (CONSISTENT)	Serviceable	26.26 FL	*- FL
128	1		*LOWER ARM BALANCER REAR LH (CONSISTENT)	Serviceable	26.26 FL	*- FL
129	1		*ABSORBER REAR LH (CONSISTENT)	Serviceable	299.81 FL	*- FL
130	1		*ABSORBER REAR RH (CONSISTENT)	Serviceable	299.81 FL	*- FL
131	1		*STABILIZER BAR REAR (CONSISTENT)	Serviceable	465.12 FL	*- FL
132	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	Bent / Buckled	1,684.52 FL	*1,684.52 FL
133	1		*SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL) (CONSISTENT)	Serviceable	470.93 FL	*- FL
134	1		*OUTER PANEL REAR (END PANEL) (CONSISTENT)	Bent	1,132.13 FL	*1,132.13 FL
135	1		*OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	Cracked	308.48 FL	*308.48 FL
136	1		*EXHAUST REAR (CONSISTENT)	Bent	5,760.00 FL	*5,760.00 FL
137	1		*EXHAUST CAP REAR (CONSISTENT)	Dented	177.30 FL	*177.30 FL
138	1		*DOOR PANEL REAR LH (CONSISTENT)	Repair	2,188.20 FL	*- FL
139	1		*DOOR SEAL REAR LH (CONSISTENT)	Serviceable	68.02 FL	*- FL
140	1		*DOOR PANEL REAR RH (CONSISTENT)	Repair	2,188.20 FL	*- FL
141	1		*DOOR SEAL REAR RH (CONSISTENT)	Serviceable	68.02 FL	*- FL
142	1		*DOOR HINGE UPPER RH (CONSISTENT)	Repair	242.88 FL	*- FL
143	1		*DOOR HINGE LOWER RH (CONSISTENT)	Repair	231.19 FL	*- FL
144	1		*DOOR LOCK REAR RH (CONSISTENT)	Repair	699.04 FL	*- FL
145	1		*SET RADIATOR GRILLE FRAME CLIP (CONSISTENT)	Necessary	52.00 FS	*52.00 FS
146	1		*SET BUMPER CLIP FRT (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
147	1		*BUMPER BRACKET CLIP FRT LH (CONSISTENT)	Not Necessary	12.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
148	1		*BUMPER SUPPORT CLIP FRT LH (CONSISTENT)	Not Necessary	10.50 FS	*- FS
149	1		*BUMPER BRACKET CLIP FRT RH (CONSISTENT)	Not Necessary	12.00 FS	*- FS
150	1		*BUMPER SUPPORT CLIP FRT RH (CONSISTENT)	Not Necessary	10.50 FS	*- FS
151	1		*TOW COVER FRT (CONSISTENT)	Serviceable	14.50 FS	*- FS
152	1		*SET RADIATOR GRILLE SCREW (CONSISTENT)	Not Necessary	16.00 FS	*- FS
153	1		*SET BUMPER GRILLE LOWER CLIP (CONSISTENT)	Necessary	69.00 FS	*69.00 FS
154	1		*SET FRAME FULL SUPPORT PANEL CLIP (CONSISTENT)	Necessary	70.00 FS	*70.00 FS
155	2		*FRAME FULL SUPPORT PANEL NUT (CONSISTENT)	Not Necessary	20.00 FS	*- FS
156	2		*FRAME FULL SUPPORT PANEL STUD (CONSISTENT)	Serviceable	30.00 FS	*- FS
157	1		*SET WHEELARCH CLIP FRT LH (CONSISTENT)	Not Necessary	30.50 FS	*- FS
158	1		*SET WHEELARCH CLIP FRT RH (CONSISTENT)	Not Necessary	29.40 FS	*- FS
159	2		*BONNET CABLE CLIP (CONSISTENT)	Not Necessary	6.40 FS	*- FS
160	1		*SET BUMPER RR RIVET (CONSISTENT)	Necessary	28.60 FS	*28.60 FS
161	1		*SET BUMPER RR CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
162	1		*SET BUMPER BEAM BOLT (CONSISTENT)	Serviceable	22.22 FS	*- FS
163	1		*SET REFLECTOR SCREW LH (CONSISTENT)	Not Necessary	25.00 FS	*- FS
164	1		*SET PARKING AID (CONSISTENT)	Torn	600.00 FS	*600.00 FS
165	1		*BUMPER BRACKET CLIP CTR REAR (CONSISTENT)	Not Necessary	15.00 FS	*- FS
166	1		*BUMPER BRACKET SIDE CLIP LH REAR (CONSISTENT)	Not Necessary	12.00 FS	*- FS
167	1		*BUMPER RETAINER CLIP LH REAR (CONSISTENT)	Not Necessary	10.40 FS	*- FS
168	1		*BUMPER BRACKET SIDE CLIP RH REAR (CONSISTENT)	Not Necessary	12.00 FS	*- FS
169	1		*BUMPER RETAINER CLIP RH REAR (CONSISTENT)	Not Necessary	10.40 FS	*- FS
170	1		*SET WHEELARCH CLIP LH RR (CONSISTENT)	Not Necessary	32.34 FS	*- FS
171	1		*SET WHEELARCH CLIP RH RR (CONSISTENT)	Not Necessary	32.34 FS	*- FS
172	1		*CAP HUB LH RR (CONSISTENT)	Serviceable	35.00 FS	*- FS
173	1		*RIM LH RR (CONSISTENT)	Serviceable	385.00 FS	*- FS
174	1		*TYRE LH RR (CONSISTENT)	Serviceable	330.00 FS	*- FS
175	1		*SPARE TYRE RIM (ROUE 7J 16H 2547) (CONSISTENT)	Serviceable	385.00 FS	*- FS
176	1		*SPARE TYRE (CONSISTENT)	Serviceable	330.00 FS	*- FS
177	1		*SET BOOT FINISHER CLIP (CONSISTENT)	Necessary	25.10 FS	*25.10 FS
178	1		*REAR BOOTS STICKER TRANS-CAB (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
179	1		*REAR BOOTS STICKER 6555-3333 (CONSISTENT)	Necessary	30.00 FS	*30.00 FS
180	1		*FENDER PANEL INNER TRIM CLIP REAR RH (CONSISTENT)	Necessary	22.00 FS	*22.00 FS
181	1		*FENDER PANEL INNER TRIM CLIP REAR LH (CONSISTENT)	Not Necessary	22.00 FS	*- FS
182	2		*REAR WINDSCREEN SEALANT (CONSISTENT)	Necessary	80.00 FS	*40.00 FS
183	1		*WINDSCREEN MOULDING (CONSISTENT)	Necessary	100.00 FS	*100.00 FS
184	1		*REAR WINDSCREEN INNER SPONGE SEAL (CONSISTENT)	Necessary	100.00 FS	*30.00 FS
185	1		*EXHAUST MOUNTING REAR (CONSISTENT)	Torn	65.50 FS	*65.50 FS
186	1		*EXHAUST BRACKET REAR (CONSISTENT)	Repair	22.22 FS	*- FS
187	1		*SET FRONT LICENCE PLATE WITH HOLDER (CONSISTENT)	Dented	80.00 FS	*45.00 FS
188	1		*SET REAR LICENCE PLATE WITH HOLDER (CONSISTENT)	Dented	80.00 FS	*45.00 FS
189	1		*DOOR STICKER TRANS-CAB LH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
190	1		*DOOR STICKER CLASSIC LH (CONSISTENT)	Not Necessary	15.00 FS	*- FS
191	1		*DOOR STICKER 6555-3333 LH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
192	1		*DOOR STICKER TRANS-CAB RH (CONSISTENT)	Not Necessary	80.00 FS	*- FS
193	1		*DOOR STICKER CLASSIC RH (CONSISTENT)	Not Necessary	15.00 FS	*- FS
194	1		*DOOR STICKER 6555-3333 RH (CONSISTENT)	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	99,136.80	39,986.89
- List Item Discount on L Items 10.00/10.00% (\$\$)	9,534.99	3,860.27
Total Parts (\$\$)	89,601.81	36,126.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	16,800.00	3,000.00
2	TOWING FEES.	New	120.00	50.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	18,000.00	2,200.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	170.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	120.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	60.00
8	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
9	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	New	380.00	0.00
10	TO REMOVE AND REFIT ABS PUMP RELAY TO ENABLE REPAIR.	New	380.00	0.00
11	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	New	380.00	250.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	40.00
14	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
15	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
16	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	New	380.00	80.00
17	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
18	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
19	TO TRANSFER OF REAR WINDSCREEN FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	120.00
20	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
21	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }	New	280.00	80.00
22	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }	New	170.00	0.00
23	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
24	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	New	380.00	0.00
Gross Labour Cost (\$\$)			40,960.00	6,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >