

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG16002798/AHA3S2**Date:** 15/07/2019REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100409399
Claimant Vehicle No :	SJL2763L	Insured Vehicle No :	SDV5785Y
Date of Loss:	09/02/2016	Nature of Claim:	TP
		Claim No:	9932620602SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL2763L	Engine No:	4G18JT2913
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A8U010850
Reg. Date:	21/11/2008 (Man. Year: 2008)	Odometer:	134340 km
Colour:	Silver		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/02/2016	SK Automobile Pte Ltd (HQ)
Date Inspected:	15/02/2016 Inspected At:	23 KAKI BUKIT AVE 4 # 03-01 VICOM
		INSPECTION CENTRE
		Singapore 415933
Estimated Period of Repair:	15.0 days	

Adjuster: ADRIAN LING**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Repair	0.00 F	*- F
2	1		*FRT LH DOOR CHROME MOULDING	Necessary	0.00 F	*- F
3	1		*ROCKER PANEL LH	Dented	0.00 F	*- F
4	1		*REAR LH DOOR	Distorted	0.00 F	*- F
5	1		*REAR LH DOOR CHROME MOULDING	Necessary	0.00 F	*- F
6	1		*REAR LH DOOR RUBBER	Cut	0.00 F	*- F
7	1		*REAR LH DOOR OUTER HANDLE	Damaged	0.00 F	*- F
8	1		*REAR LH DOOR LOCK	Jammed	0.00 F	*- F
9	1		*REAR BUMPER	Deformed	0.00 F	*- F
10	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
11	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
12	1		*REAR LH FENDER	Distorted	0.00 F	*- F
13	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
14	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
15	1		*REAR WHEEL RIM LH	Cut	0.00 F	*- F
16	1		*REAR TYRE LH	Punctured	0.00 F	*- F
17	1		*REAR LOWER ARM LH	Bent	0.00 F	*- F
18	1		*REAR KNUCKLE ARM LH	Bent	0.00 F	*- F
19	1		*REAR SHOCK ABSORBER LH	Bent	0.00 F	*- F
20	1		*REAR TRAILING ARM LH	Bent	0.00 F	*- F
21	1		*REAR WHEEL HUB C/W BEARING	Damaged	0.00 F	*- F
22	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
23	1		*FRT NUMBER PLATE BASE	Deformed	0.00 F	*- F
24	1		*FRT NUMBER PLATE GARNISH	Deformed	0.00 F	*- F
25	1		*FRT BUMPER	Distorted	0.00 F	*- F
26	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
27	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
28	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
29	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
30	1		*FRT GRILLE	Cracked	0.00 F	*- F
31	2		*FRT GRILLE GARNISH	Cracked	0.00 F	*- F
32	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
33	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
34	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
35	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
36	1		*BONNET	Distorted	0.00 F	*- F
37	1		*BONNET LOCK	Jammed	0.00 F	*- F
38	2		*BONNET HINGE	Bent	0.00 F	*- F
39	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
40	1		*AIR CON FAN ASSY	Damaged	0.00 F	*- F
41	1		*RADIATOR	Bent	0.00 F	*- F
42	1		*RADIATOR FAN ASSY	Damaged	0.00 F	*- F
43	1		*AIR DUCT	Deformed	0.00 F	*- F
44	1		*AIR CLEANER ASSY	Cracked	0.00 F	*- F
45	1		*FRT LH FENDER	Buckled	0.00 F	*- F
46	1		*FRT LH FENDER CHROME MOULDING	Necessary	0.00 F	*- F
47	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >