

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AXA16005162/KPA3Q2**Date:** 27/03/2019REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA011218
Claimant Vehicle No :	SKD1690A	Insured Vehicle No :	SKP9574L
Date of Loss:	18/03/2016	Nature of Claim:	TP
		Claim No:	C0376143

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD1690A	Engine No:	HIDDEN
Make & Model:	HONDA CIVIC, 2.0 (A)	Chassis No:	JHMFD26407S200796
Reg. Date:	01/04/2007 (Man. Year: 2007)	Odometer:	144425 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,398.00	2,367.04	7,030.96	74.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,400.00	1,680.00	54.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,478.00	3,767.04	8,710.96	69.81
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	12,478.00	3,000.00	9,478.00	75.96
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	18/03/2016	
Date Inspected:	21/03/2016 Inspected At:	Meng Whee Bros Motor Service (HQ) 10 Ang Mo Kio Industrial Park 2A, #05-25, AMK Autopoint Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2019)
Parts:	143	HONDA CIVIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD1690A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT BONNET (CONSISTENT)	Buckled	960.00 F	*738.50 FL
2	1		*REAR BOOT LOCK (CONSISTENT)	Repair	295.00 F	*- FL
3	1		*REAR BOOT LOGO (CONSISTENT)	Necessary	120.00 F	*52.40 FL
4	1		*REAR BOOT EMBLEM CIVIC (CONSISTENT)	Necessary	85.00 F	*85.00 FL
5	1		*REAR BOOT EMBLEM 2.0 (CONSISTENT)	Necessary	48.00 F	*40.80 FL
6	1		*REAR BOOT EMBLEM I-VTEC (CONSISTENT)	Necessary	135.00 F	*45.70 FL
7	2		*REAR BOOT LAMP (CONSISTENT)	Scratched / Cut	880.00 F	*320.40 FL
8	10		*INSULATOR CLIPS (CONSISTENT)	Not Necessary	50.00 F	*- FL
9	2		*REAR BOOT HINGES (CONSISTENT)	Repair	360.00 F	*- FL
10	2		*REAR BOOT HINGES GARNISH (CONSISTENT)	Serviceable	320.00 F	*- FL
11	1		*REAR BOOT WHEATHERSTRIPS (50%) (CONSISTENT)	Buckled / Dented	380.00 FS	*87.60 FS
12	1		*REAR BOOT INNER LOCK (CONSISTENT)	Repair	295.00 F	*- FL
13	1		*REAR END PANEL (CONSISTENT)	Buckled	880.00 F	*269.50 FL
14	1		*REAR SPARE TYRE PANEL (CONSISTENT)	Repair	990.00 F	*- FL
15	2		*TAILLAMP RETAINER (CONSISTENT)	Serviceable	160.00 F	*- FL
16	1		*TAIL LAMP (CONSISTENT)	Cut	380.00 F	*240.50 FL
17	1		*REAR END PANEL GARNISH (CONSISTENT)	Cracked	280.00 F	*78.50 FL
18	1		*REAR BUMPER (CONSISTENT)	Bent	840.00 F	*638.00 FL
19	1		*REVERSE SENSOR (CONSISTENT)	Shorted	220.00 F	*220.00 FL
20	1		*SIDE RETAINERS (CONSISTENT)	O/S Distorted	120.00 F	*60.00 FL
21	12		*BUMPER CLIPS (CONSISTENT)	Necessary	60.00 F	*60.00 FL
22	1		*REAR EXHAUST MUFFLE (CONSISTENT)	Not Necessary	1,200.00 F	*- FL
23	1		*REAR EXHAUST CHROME (CONSISTENT)	Not Necessary	280.00 F	*- FL
24	1		*REAR NUMBER PLATE W/CASE (CONSISTENT)	Serviceable	60.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,398.00	2,936.90
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	569.86
Total Parts (\$)	9,398.00	2,367.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHASSIS ALIGNMENT	New	380.00	0.00
2	TO REMOVE AND REFIT REAR BOOT BONNET ,BUMPER ,REAR END PANEL,LAMP ,CUT AND WELD SPARE TANK ETC AND STRAIGHTEN REAR CHASSIS	New	1,200.00	600.00
3	TO CHECK REAR WIRING SYSTEM	New	120.00	20.00
4	TO RESPRAY ANTIRUST ON AFFECTED AREA	New	180.00	60.00
5	TO APPLY PUTTY,PRIMER AND RESPRAY PAINT ON DAMAGED SECTION	New	1,200.00	720.00
Gross Labour Cost (\$\$)			3,080.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >