

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AXA16006755/KPA3Q2
Date: 16/07/2020REFERENCE

Handling Insurer: AXA Insurance Pte Ltd	Policy No:	GA091285
Claimant		
Vehicle No : SHD274K	Insured Vehicle No :	SJR7186M
Date of Loss: 09/04/2016	Nature of Claim:	TP
	Claim No:	C0379481

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD274K		
Make & Model:	RENAULT LATITUDE, 2.0 CVT ABS (A)	Engine No:	M9R8839C003076
Reg. Date:	04/02/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC282629
Colour:	Metallic White/Red	Odometer:	21756 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	75,006.28	30,733.03	44,273.25	59.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,440.00	2,790.00	19,650.00	87.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	97,446.28	33,523.03	63,923.25	65.60
+ GST 7.00/7.00% (S\$)	6,821.24	2,346.61	4,474.63	65.60
Nett Amount (S\$)	104,267.52	35,869.64	68,397.88	65.60
+ Car Rental (9.0 x S\$133.75/day) (S\$)		1,203.75		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		37,078.74		
Global Sum Settlement (S\$)		37,000.00		

INSPECTION

Date of Assignment:	14/04/2016	
Date Inspected:	11/04/2016 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2019)
Parts: 143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD274K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (CONSISTENT)	Torn	968.79 FL	*968.79 FL
2	1		*BUMPER SPOILER FRT (CONSISTENT)	Missing	139.81 FL	*139.81 FL
3	1		*BUMPER ABSORBER FRT (CONSISTENT)	Broken	303.60 FL	*303.60 FL
4	1		*BUMPER BRACKET FRT LH (CONSISTENT)	Bent	116.47 FL	*116.47 FL
5	1		*BUMPER RETAINER FRT LH (CONSISTENT)	Cracked	18.37 FL	*18.37 FL
6	1		*BUMPER BRACKET FRT RH (CONSISTENT)	Serviceable	115.98 FL	*- FL
7	1		*BUMPER RETAINER FRT RH (CONSISTENT)	Serviceable	18.37 FL	*- FL
8	1		*BUMPER UNDERTRAY FRT (CONSISTENT)	Cracked	363.71 FL	*363.71 FL
9	1		*BUMPER GRILLE LOWER FRT (CONSISTENT)	Cracked	205.23 FL	*205.23 FL
10	1		*BUMPER FOG LAMP GRILLE LH (CONSISTENT)	Missing	159.39 FL	*159.39 FL
11	1		*BUMPER FOG LAMP GRILLE RH (CONSISTENT)	Serviceable	159.39 FL	*- FL
12	1		*BUMPER BEAM FRT (CONSISTENT)	Bent	703.14 FL	*703.14 FL
13	1		*RADIATOR GRILLE (CONSISTENT)	Cracked	1,313.68 FL	*1,313.68 FL
14	1		*RADIATOR GRILLE BADGE RENAULT (CONSISTENT)	Necessary	173.36 FL	*173.36 FL
15	1		*RADIATOR GRILLE FRAME (CONSISTENT)	Broken	1,041.35 FL	*1,041.35 FL
16	1		*FRAME FULL SUPPORT PANEL (CONSISTENT)	Cracked	473.77 FL	*473.77 FL
17	1		*FRAME FULL SUPPORT BRACKET (CONSISTENT)	Bent	69.07 FL	*69.07 FL
18	1		*FRONT BRACE PANEL (CONSISTENT)	Bent	136.32 FL	*136.32 FL
19	1		*SUBFRAME OUTER FRT (CONSISTENT)	Serviceable	2,040.34 FL	*- FL
20	1		*SUBFRAME INNER FRT (CROSSMEMBER) (CONSISTENT)	Serviceable	1,757.54 FL	*- FL
21	1		*SUBFRAME SUPPORT INNER (CONSISTENT)	Repair	71.04 FL	*- FL
22	1		*SUBFRAME BRACKET OUTER LH (CONSISTENT)	Repair	71.04 FL	*- FL
23	1		*SUBFRAME BRACKET OUTER RH (CONSISTENT)	Repair	71.04 FL	*- FL
24	1		*SUBFRAME BRACKET INNER LH (CONSISTENT)	Repair	138.44 FL	*- FL
25	1		*SUBFRAME BRACKET INNER RH (CONSISTENT)	Repair	138.44 FL	*- FL
26	1		*LOWER ARM RH (CONSISTENT)	Serviceable	527.51 FL	*- FL
27	1		*BRAKE DISC FRT (CONSISTENT)	Serviceable	211.91 FL	*- FL
28	1		*KNUCKLE ARM RH (CONSISTENT)	Serviceable	651.53 FL	*- FL
29	1		*KNUCKLE HUB+BEARING RH (CONSISTENT)	Not Necessary	382.84 FL	*- FL
30	1		*KNUCKLE ARM SHIELD RH (CONSISTENT)	Serviceable	101.10 FL	*- FL
31	1		*KNUCKLE ARM PLATE RH (CONSISTENT)	Serviceable	133.89 FL	*- FL
32	1		*BRAKE DISC FRT (CONSISTENT)	Serviceable	211.91 FL	*- FL
33	1		*ABSORBER FRT RH (CONSISTENT)	Serviceable	277.34 FL	*- FL
34	1		*ABSORBER MOUNTING KIT RH (CONSISTENT)	Serviceable	338.97 FL	*- FL
35	1		*ABSORBER DUST COVER (CONSISTENT)	Serviceable	175.94 FL	*- FL
36	1		*STABILIZER BAR FRT (CONSISTENT)	Serviceable	465.12 FL	*- FL
37	1		*STABILIZER LINK FRT (CONSISTENT)	Serviceable	90.17 FL	*- FL
38	1		*BRAKE CALIPER FRT RH (CONSISTENT)	Serviceable	505.34 FL	*- FL
39	1		*BRAKE CALIPER BRACKET FRT RH (CONSISTENT)	Serviceable	427.01 FL	*- FL
40	1		*ABS SENSOR FRT RH (CONSISTENT)	Serviceable	196.73 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*BRAKE HOSE FRT RH (CONSISTENT)	Serviceable	96.70 FL	*- FL
42	1		*DRIVESHAFT RH (CONSISTENT)	Repair	1,344.19 FL	*- FL
43	1		*LOWER ARM LH (CONSISTENT)	Serviceable	527.51 FL	*- FL
44	1		*BRAKE DISC FRT (CONSISTENT)	Serviceable	211.91 FL	*- FL
45	1		*KNUCKLE ARM LH (CONSISTENT)	Serviceable	651.53 FL	*- FL
46	1		*KNUCKLE HUB+BEARING LH (CONSISTENT)	Not Necessary	382.84 FL	*- FL
47	1		*KNUCKLE ARM SHIELD LH (CONSISTENT)	Serviceable	101.10 FL	*- FL
48	1		*KNUCKLE ARM PLATE LH (CONSISTENT)	Serviceable	133.89 FL	*- FL
49	1		*BRAKE DISC FRT (CONSISTENT)	Serviceable	211.91 FL	*- FL
50	1		*ABSORBER FRT LH (CONSISTENT)	Serviceable	277.34 FL	*- FL
51	1		*ABSORBER MOUNTING KIT LH (CONSISTENT)	Serviceable	338.97 FL	*- FL
52	1		*ABSORBER DUST COVER (CONSISTENT)	Serviceable	175.94 FL	*- FL
53	1		*STABILIZER BAR FRT (CONSISTENT)	Repeated	465.12 FL	*- FL
54	1		*STABILIZER LINK FRT (CONSISTENT)	Serviceable	90.17 FL	*- FL
55	1		*BRAKE CALIPER FRT LH (CONSISTENT)	Serviceable	505.34 FL	*- FL
56	1		*BRAKE CALIPER BRACKET FRT LH (CONSISTENT)	Serviceable	427.01 FL	*- FL
57	1		*ABS SENSOR FRT LH (CONSISTENT)	Serviceable	196.73 FL	*- FL
58	1		*BRAKE HOSE FRT LH (CONSISTENT)	Serviceable	96.70 FL	*- FL
59	1		*DRIVESHAFT LH (CONSISTENT)	Repair	1,344.19 FL	*- FL
60	1		*SEATBELT BUCKLE RH (CONSISTENT)	Serviceable	730.61 FL	*- FL
61	1		*SEATBELT RH (CONSISTENT)	Jammed	2,250.28 FL	*2,250.28 FL
62	1		*SEATBELT BUCKLE LH (CONSISTENT)	Serviceable	730.61 FL	*- FL
63	1		*SEATBELT LH (CONSISTENT)	Jammed	2,250.28 FL	*2,250.28 FL
64	1		*PASSENGER AIRBAG (CONSISTENT)	Burst	2,624.93 FL	*2,624.93 FL
65	1		*PASSENGER AIRBAG COMPUTER (CONSISTENT)	Necessary	969.09 FL	*969.09 FL
66	1		*PASSENGER AIRBAG SENSOR (CONSISTENT)	Necessary	557.41 FL	*557.41 FL
67	1		*STEERING AIRBAG (CONSISTENT)	Burst	1,942.89 FL	*1,942.89 FL
68	1		*STEERING AIRBAG SENSOR (CONSISTENT)	Necessary	222.54 FL	*222.54 FL
69	1		*STEERING AIRBAG COMPUTER (CONSISTENT)	Repeated	969.09 FL	*- FL
70	1		*ROTARY SWITCH (CONSISTENT)	Necessary	963.93 FL	*963.93 FL
71	1		*DASHBOARD (CONSISTENT)	Torn	3,769.65 FL	*3,769.65 FL
72	1		*GLOVE BOX (CONSISTENT)	Serviceable	799.83 FL	*- FL
73	1		*GLOVE BOX FLAP (CONSISTENT)	Serviceable	983.82 FL	*- FL
74	1		*HEADLAMP LH (CONSISTENT)	Broken	911.10 FL	*911.10 FL
75	1		*HEADLAMP RH (CONSISTENT)	Mtg Cracked	911.10 FL	*911.10 FL
76	1		*HEADLAMP HARNESS RH (CONSISTENT)	Serviceable	714.07 FL	*- FL
77	1		*HEADLAMP HARNESS LH (CONSISTENT)	Serviceable	714.07 FL	*- FL
78	1		*HEADLAMP PANEL FRT RH (CONSISTENT)	Repair	134.59 FL	*- FL
79	1		*HEADLAMP PANEL FRT LH (CONSISTENT)	Bent	134.59 FL	*134.59 FL
80	1		*BONNET (CONSISTENT)	Buckled	1,493.56 FL	*1,493.56 FL
81	1		*BONNET INSULATOR (CONSISTENT)	Deformed	312.10 FL	*312.10 FL
82	1		*BONNET STRUT LH (CONSISTENT)	Serviceable	166.29 FL	*- FL
83	1		*BONNET STRUT RH (CONSISTENT)	Serviceable	166.29 FL	*- FL
84	1		*BONNET HINGE LH (CONSISTENT)	Distorted	267.93 FL	*267.93 FL
85	1		*BONNET HINGE RH (CONSISTENT)	Repair	267.93 FL	*- FL
86	2		*BAL HOOD (CONSISTENT)	Serviceable	75.60 FL	*- FL
87	1		*BONNET LOCK (CONSISTENT)	Distorted	234.99 FL	*234.99 FL
88	1		*BONNET CABLE (CONSISTENT)	Serviceable	91.69 FL	*- FL
89	1		*BONNET CABLE COVER (CONSISTENT)	Serviceable	123.87 FL	*- FL
90	1		*BONNET SEAL OUTER (CONSISTENT)	Serviceable	71.04 FL	*- FL
91	1		*FENDER PANEL FRT LH (CONSISTENT)	Bent	602.95 FL	*602.95 FL
92	1		*FENDER PANEL FRT RH (CONSISTENT)	Repair	602.95 FL	*- FL
93	1		*FENDER WHEELARCH FRT LH (LINNER) (CONSISTENT)	Cracked	107.32 FL	*107.32 FL
94	1		*FENDER WHEELARCH FRT RH (LINNER) (CONSISTENT)	Serviceable	214.49 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
95	1		*FENDER INSULATOR RH (CONSISTENT)	Serviceable	100.64 FL	*- FL
96	1		*FENDER INSULATOR LH (CONSISTENT)	Serviceable	100.64 FL	*- FL
97	1		*FENDER PANEL BRACKET FRT RH (CONSISTENT)	Repair	161.52 FL	*- FL
98	1		*FENDER PANEL BRACKET FRT LH (CONSISTENT)	Bent	161.52 FL	*161.52 FL
99	1		*WHEEL HOUSING PANEL FRT RH (CONSISTENT)	Repair	3,601.61 FL	*- FL
100	1		*WHEEL HOUSING PANEL FRT LH (CONSISTENT)	Repair	3,601.61 FL	*- FL
101	1		*FENDERCHASSIS REINFORCEMENT FRT LH (CONSISTENT)	Repair	765.90 FL	*- FL
102	1		*FENDERCHASSIS REINFORCEMENT FRT RH (CONSISTENT)	Repair	765.90 FL	*- FL
103	1		*RADIATOR (CONSISTENT)	Punctured	924.77 FL	*924.77 FL
104	1		*RADIATOR FAN COWLING (CONSISTENT)	Cracked	573.80 FL	*573.80 FL
105	1		*RADIATOR FAN MOTOR LH (CONSISTENT)	Jammed	676.48 FL	*676.48 FL
106	1		*RADIATOR FAN MOTOR RH (CONSISTENT)	Jammed	676.48 FL	*676.48 FL
107	1		*RADIATOR HOSE UPPER (CONSISTENT)	Serviceable	168.22 FL	*- FL
108	1		*RADIATOR HOSE LOWER (CONSISTENT)	Serviceable	343.48 FL	*- FL
109	1		*AIR CLEANER HOSE (CONSISTENT)	Serviceable	58.57 FL	*- FL
110	1		*AIR CLEANER LOWER (CONSISTENT)	Serviceable	311.95 FL	*- FL
111	1		*ENGINE UNDERTRAY (CONSISTENT)	Serviceable	434.60 FL	*- FL
112	1		*A/C CONDENSER (CONSISTENT)	Punctured	1,554.13 FL	*1,554.13 FL
113	1		*A/C CONDENSER GARNISH LH UPPER (CONSISTENT)	Cracked	27.74 FL	*27.74 FL
114	1		*A/C CONDENSER GARNISH RH UPPER (CONSISTENT)	Serviceable	27.74 FL	*- FL
115	1		*A/C CONDENSER GARNISH LH (CONSISTENT)	Cracked	41.12 FL	*41.12 FL
116	1		*A/C CONDENSER GARNISH RH (CONSISTENT)	Serviceable	41.68 FL	*- FL
117	1		*A/C PIPE CONDENSER TO COMPRESSOR (CONSISTENT)	Serviceable	145.73 FL	*- FL
118	1		*A/C PIPE CONDENSER TO EXPENSION VALVE (CONSISTENT)	Serviceable	460.64 FL	*- FL
119	1		*A/C PIPE COMPRESSOR (CONSISTENT)	Serviceable	233.77 FL	*- FL
120	1		*A/C PIPE (CONSISTENT)	Serviceable	460.64 FL	*- FL
121	1		*TRANSMISSION COOLER (CONSISTENT)	Bent / Punctured	852.66 FL	*852.66 FL
122	1		*AIR INTERCOOLER HOSE (LONG) (CONSISTENT)	Serviceable	709.18 FL	*- FL
123	1		*AIR INTERCOOLER HOSE (SHORT) (CONSISTENT)	Serviceable	262.34 FL	*- FL
124	1		*STEERING PUMP ELECTRIC (CONSISTENT)	Cracked	1,543.08 FL	*1,543.08 FL
125	1		*STEERING HOSE LOW PRESSURE LONG (CONSISTENT)	Serviceable	442.50 FL	*- FL
126	1		*STEERING HOSE LOW PRESSURE (CONSISTENT)	Serviceable	247.18 FL	*- FL
127	1		*WINDSCREEN FRT (CONSISTENT)	Serviceable	1,005.56 FL	*- FL
128	1		*WIPER RESERVOIR (CONSISTENT)	Serviceable	190.96 FL	*- FL
129	1		*WIPER RESERVOIR NECK (CONSISTENT)	Serviceable	27.78 FL	*- FL
130	1		*WIPER RESERVOIR MOTOR (CONSISTENT)	Serviceable	100.95 FL	*- FL
131	1		*DOOR PANEL FRT LH (CONSISTENT)	Repair	2,188.20 FL	*- FL
132	1		*DOOR MIRROR LH (CONSISTENT)	Serviceable	1,141.08 FL	*- FL
133	1		*DOOR SEAL FRT LH (CONSISTENT)	Serviceable	50.92 FL	*- FL
134	1		*DOOR PANEL FRT RH (CONSISTENT)	Repair	2,188.20 FL	*- FL
135	1		*DOOR MIRROR RH (CONSISTENT)	Serviceable	1,141.08 FL	*- FL
136	1		*DOOR SEAL FRT RH (CONSISTENT)	Serviceable	50.92 FL	*- FL
137	1		*SET RADIATOR GRILLE FRAME CLIP (CONSISTENT)	Necessary	52.00 FS	*52.00 FS
138	1		*SET BUMPER CLIP FRT (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
139	1		*TOW COVER FRT (CONSISTENT)	Dented	14.50 FS	*14.50 FS
140	1		*SET RADIATOR GRILLE SCREW (CONSISTENT)	Necessary	16.00 FS	*16.00 FS
141	1		*SET BUMPER GRILLE LOWER CLIP (CONSISTENT)	Necessary	69.00 FS	*69.00 FS
142	1		*SET FRAME FULL SUPPORT PANEL CLIP (CONSISTENT)	Necessary	70.00 FS	*70.00 FS
143	2		*FRAME FULL SUPPORT PANEL NUT (CONSISTENT)	Not Necessary	20.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
144	2		*FRAME FULL SUPPORT PANEL STUD (CONSISTENT)	Not Necessary	30.00 FS	*- FS
145	2		*BONNET CABLE CLIP (CONSISTENT)	Not Necessary	6.40 FS	*- FS
146	1		*SET WHEELARCH CLIP LH (CONSISTENT)	Necessary	30.50 FS	*30.50 FS
147	1		*SET WHEELARCH CLIP RH (CONSISTENT)	Not Necessary	29.40 FS	*- FS
148	2		*FRONT WINDSCREEN SEALANT (CONSISTENT)	Not Necessary	80.00 FS	*- FS
149	2		*FRONT WINDSCREEN MOULDING (CONSISTENT)	Not Necessary	100.00 FS	*- FS
150	2		*E.R.P STICKER (CONSISTENT)	Not Necessary	65.00 FS	*- FS
151	1		*DOOR STICKER TRANS-CAB (CONSISTENT)	Not Necessary	80.00 FS	*- FS
152	1		*DOOR STICKER CLASSIC (CONSISTENT)	Not Necessary	30.00 FS	*- FS
153	1		*DOOR STICKER 6555-3333 (CONSISTENT)	Not Necessary	80.00 FS	*- FS
154	1		*SET NUMBER PLATE WITH HOLDER (CONSISTENT)	Broken	140.00 FS	*45.00 FS
155	1		*DASHBOARD SCREW (CONSISTENT)	Not Necessary	55.55 FS	*- FS
156	1		*CAP HUB RH FRT (CONSISTENT)	Serviceable	35.00 FS	*- FS
157	1		*RIM RH FRT (CONSISTENT)	Serviceable	385.00 FS	*- FS
158	1		*TYRE RH FRT (CONSISTENT)	Serviceable	330.00 FS	*- FS
159	1		*CAP HUB LH FRT (CONSISTENT)	Serviceable	35.00 FS	*- FS
160	1		*RIM LH FRT (CONSISTENT)	Serviceable	385.00 FS	*- FS
161	1		*TYRE LH FRT (CONSISTENT)	Serviceable	330.00 FS	*- FS
162	1		*CAP HUB LH RR (CONSISTENT)	Serviceable	35.00 FS	*- FS
163	1		*RIM LH RR (CONSISTENT)	Serviceable	385.00 FS	*- FS
164	1		*TYRE LH RR (CONSISTENT)	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	82,975.38	34,107.48
- List Item Discount on L Items 10.00/10.00% (\$)	7,969.10	3,374.45
Total Parts (\$)	75,006.28	30,733.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	8,400.00	900.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	9,000.00	1,100.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
6	TOWING FEES	New	120.00	50.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
9	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING	New	380.00	0.00
10	TO LIFT -UP ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
11	TO DISMANTLE AND REFIT ENGINE CROSS -MEMBER AND ENGINE MOUNTING	New	380.00	0.00
12	TO REMOVE AND RENEW POWER STEERING PUMP ,OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	60.00
13	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET	New	480.00	250.00
14	TO CHECK ABS BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
15	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK }	New	380.00	250.00
16	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR }	New	380.00	0.00
17	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
18	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	30.00
Gross Labour Cost (\$\$)			22,440.00	2,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >