

Print Sent Message

This mail is associated with :

***SKM3350X (C0386155)
[GX6397G]**

TP

KANG CHEU KHIEM

May 31 2016 12:00AM

[BRIGHTNESS SERVICES]

Em-1 Auto Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 05/06/2019 10:23 AM.
To sashe.goms@axa.com.sg
CC AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com
Subject <Seek Mandate> C0386155/ P1633547

Dear Sashe,

Thank you for your email.

This is a head-to-rear collision. Liability is down against OID.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to third party repairer, **EM-1 Auto Pte Ltd** is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 37,429.35	\$ 19,260.00
2. Loss of Rental (10days x \$200.00)(w/GST)	\$ 2,140.00	\$ 1,926.00 (10days x\$180.00)(w/GST)
3. LTA/ GIA Search Fee	\$ 5.35	\$ 5.35
Total	\$ 39,574.70	\$ 21,191.35

Market Value : \$ 45,000.00 (est)
 LTA Rebate : \$ 24,617.13 (est)
 Nett Value : **\$ 20,382.87 (est)**

For your approval in Merimen please.

Hsiao Tong
 LKK Auto Consultants Pte Ltd
 DID: 6742 3197

<-- Original Message -->

From: AXA_SG
To: LKK_HQ; chewht@lkkauto.com; admin-a@lkkauto.com
CC: AXA_SG
Sent On: 30/05/2019 01:54 PM
Subject: Re: C0386155/ P1633547

Dear Hsiao Tong

We have completed our investigation.

Please proceed DS with TP workshop.

Thank you.

Regards
 Sashe

<-- Original Message -->

From: AXA_SG

To: LKK_HQ; chewht@lkkauto.com; admin-a@lkkauto.com

CC: AXA_SG

Sent On: 14/05/2019 03:24 PM

Subject: Re: C0386155/ P1633547



Dear LKK

The investigation is still ongoing. Please hold the claim and we will update you.

Thank you.

Regards

Sashe

<-- Original Message -->

From: LKK_HQ

To: kianchuan.chan@axa.com.sg

CC: AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com

Sent On: 27/04/2019 01:10 PM

Subject: Re: C0386155/ P1633547

Dear Sirs/Mdm,

We refer to your below email.

Kindly advise if investigation had been cleared and let us have your instruction.

Hsiao Tong

<-- Original Message -->

From: LKK_HQ

To: kianchuan.chan@axa.com.sg

CC: AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com

Sent On: 13/04/2019 09:23 AM

Subject: Re: C0386155/ P1633547

Dear Sirs/Mdm,

We refer to your below email.

Kindly advise if investigation had been cleared and let us have your instruction.

Hsiao Tong

<-- Original Message -->

From: LKK_HQ

To: kianchuan.chan@axa.com.sg

CC: AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com

Sent On: 02/03/2019 03:02 PM

Subject: Re: C0386155/ P1633547

Dear Sirs/Mdm,

We refer to your below email.

Kindly advise if investigation had been cleared and let us have your instruction.

Hsiao Tong

<-- Original Message -->

From: AXA_SG

To: LKK_HQ

CC: chewht@lkkauto.com; admin-a@lkkauto.com

Sent On: 17/01/2019 10:39 AM

Subject: Re: C0386155/ P1633547

HI,

WE WILL APPOINT INVESTIGATOR FOR FURTHER ACTION.
PLS HOLD FOR TP CLAIM.

THANK YOU.



AXA INSURANCE PTE LTD
8 Shenton Way, #24-01 AXA Tower
Singapore 068811
Customer Centre #81-01
☎ (SG) 6540 4888
☎ (SG) 6538 2522
🌐 www.axa.com.sg
GST Reg No.: 199605512M
Co. Reg No.: 199605512M

<-- Original Message -->

From: LKK_HQ

To: kianchuan.chan@axa.com.sg

CC: AXA_SG; chewht@lkkauto.com; admin-a@lkkauto.com

Sent On: 15/01/2019 04:35 PM

Subject: C0386155/ P1633547

Dear Sirs/Mdm,

We refer to the above matter.

We noted that our insured driver's work permit employer company is B-H-T Air-Conditioning and Maintenance Services, however our driver was driving GX 6397G which is registered under Brightness Services.

Kindly advise if there is any policy issue and whether we can proceed DS.

Thank you.

HsiaoTong

Print Received Message

This mail is associated with :

***SKM3350X (C0386155)**
[GX6397G]

TP

KANG CHEU KHIEM

May 31 2016 12:00AM

[BRIGHTNESS SERVICES]

Em-1 Auto Pte Ltd

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 06/06/2019 09:36 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20550.00) - SKM3350X - Claim Handler: Richard Ang

Approved:20550.00:Please offer up to \$20,550/- (all-in). Thank you.

Hsiao Tong (LKKAuto)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Thursday, 13 June 2019 12:09 PM
To: Hsiao Tong (LKKAuto)
Cc: Admin A
Subject: Re: LOD - SKM 3350X DOA 31.05.2016 - TP AXA *LKK REF: CC4/AXA16010277/M1pa3

WITHOUT PREJUDICE

Dear Hsiao Tong,

We accept your offer on Global sum S\$ 20,000.00 (all-in).
Kindly proceed to arrange payment/DV to **EM-1 AUTO PTE LTD.**

Thanks & Best Regards,

Karen, on behalf of,
Chia Sin Muk (Mr)
m: (65) 9666 6556 | o: (65) 6452 3298 | f: (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On Wed, 12 Jun 2019 at 17:13, Hsiao Tong (LKKAuto) <chewht@lkkauto.com> wrote:

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of **\$20,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.”

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chia Sin Muk <em1autopteltd@gmail.com>

Sent: Monday, 14 January 2019 1:18 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Fwd: LOD - SKM 3350X DOA 31.05.2016 - TP AXA

WITHOUT PREJUDICE

Dear All,

Kindly update us the status of claim.

Thanks & Best Regards,

Nicole, on behalf of,
Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

----- Forwarded message -----

From: **Chia Sin Muk** <em1autopteltd@gmail.com>
Date: Thu, 28 Sep 2017 at 15:46
Subject: LOD - SKM 3350X DOA 31.05.2016 - TP AXA
To: Team A <admin-a@lkkauto.com>

WITHOUT PREJUDICE

Dear Sir/Madam,

Please find the attached LOD.

COR \$ 19,260.00

LTA \$ 5.35

LOR \$ 2,140.00

Total : \$ 21,405.35

Kindly arrange for settlement.

Thanks & Best Regards,

Nicole, on behalf of,
Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Rd Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C
#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

M/S KANG CHEU KHIEM

17/PI00281/4602TP

Date

: 22-Sep-2017

AXA Insurance Singapore Pte Ltd
Motor Claim Department
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Date of Accident : 31-May-2016
Our Client's Vehicle Number : SKM 3350X
Vehicle Make/ Model : LEXUS GS 300
Your Insurer : GX 6397G

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (Recommended by LKK Mr Ma)	18,000.00	1,260.00	19,260.00 SR
LTA Fee	5.00	0.35	5.35 SR
Loss of Rental (10 days x \$ 200)	2,000.00	140.00	2,140.00 SR

SGD (Twenty-One Thousand Four Hundred Five And Cents
Thirty-Five only)

GRAND TOTAL

21,405.35

Subject to 7% GST

1,400.35



Authorised Signature and Company Stamp

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jun 2016		02 Jun 2016 13:49 Edit Adj Rpt	S\$18,000.00 Edit Estimates	S\$18,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BRIGHTNESS SERVICES , Co. Reg. No.: 53158704E, Tel: +6597928991		
Main Claimant:	KANG CHEU KHIEM , ID: S69454731		
Vehicle Reg. No.:	SKM3350X	Date of Loss:	31/05/2016 00:00 - :59 [122 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0386155	Policy/Cover Note No.:	P1633547 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	GX6397G	Policy No. (Claimant):	DMPCSN3019481602
		Excess:	S\$0.00
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Richard Ang]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 13/06/2016]		
Driver/Custodian (Insured):	KANNAN MANOJ KUMAR (), NRIC: G2187948M Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (06/06/2019): **Alert - Adj Mandate Approved (S\$20550.00) - SKM3350X - Claim Handler: Richard An...**
- AXA_SG (30/05/2019): **Re: <Seek Instruction> C0386155/ P1633547**
- AXA_SG (14/05/2019): **Re: <Seek Instruction> C0386155/ P1633547**
- AXA_SG (17/01/2019): **Re: <Seek Instruction> C0386155/ P1633547**
- AXA_SG (14/11/2018): **Alert - Adj Mandate Approved (S\$0.00) - SKM3350X - Claim Handler: Chan Kian Chua...**
- AXA_SG (10/12/2017): **Alert - Adj Mandate Maintained - SKM3350X - Claim Handler: Vale Oh**
- AXA_SG (25/08/2017): **FILE REVIEW - PLEASE ADVISE STATUS VIA MERIMEN, THANKS-VO**
- AXA_SG (05/11/2016): **PLS ADVISE STATUS OF THE ABOVE MATTER, THANKS - VO-05.11.16**
- AXA_SG (02/06/2016): **New TP Assignment - C0386155/P1633547**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKM3350X (C0386155)**
[GX6397G]
 TP
KANG CHEU KHIEM
May 31 2016 12:00AM
[BRIGHTNESS SERVICES]
Em-1 Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown								Edit	
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	25/10/17 17:30	Adjuster Immediate Advice								Load HTM	
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)							Thumbnail	Print	
1	02/06/16 13:03	EMAIL_ABS								Load PDF	
2	02/06/16 13:03	GX6397G INSD GIA REPORT_ABS								Load PDF	
3	02/06/16 13:03	vehicle not found_abs								Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	03/06/16 17:51	TP ESTIMATE - MARKED								Load PDF	
2	03/06/16 17:51	TP GIA REPORT								Load PDF	
3	09/06/16 10:03	Letter to OI								Load PDF	
4	20/06/16 08:57	OI POLICE REPORT								Load PDF	
5	20/06/16 08:58	OI scene photos								Load PDF	
6	25/10/17 17:29	TP ESTIMATE_WITH PART PRICE								Load PDF	
7	05/12/17 10:02	LKK Survey Photos								Load PDF	
8	05/12/17 10:02	LKK Resurvey Photos								Load PDF	
9	02/11/18 12:12	PARF_COE REBATE								Load PDF	
10	15/01/19 16:07	OID Work Permit & DL								Load PDF	
11	26/06/19 15:24	AUTHORISATION TO ACT								Load PDF	
12	26/06/19 15:24	LTA SEARCH								Load PDF	
13	26/06/19 15:24	RELEASE VOUCHER								Load PDF	
14	26/06/19 15:24	RENTAL MILEAGE								Load PDF	
15	26/06/19 15:24	RENTAL RECEIPT								Load PDF	
16	26/06/19 15:24	WORKSHOP INVOICE								Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.</p>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GX6397G (Insd veh)	Model:	LEXUS GS300 3.0 (A)
	SKM3350X (TP veh)		
Date of Accident:	31/05/2016		

Global Sum Settlement	:	[X] Yes	[] No
Repair Estimate	:	\$	37,429.35
Final Repair Cost	:	\$	19,260.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	1,605.00 10 days
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	
	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	20,000.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	EM-1 Auto Pte Ltd	:	\$ 20,000.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

26 Jun
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA16010277/M1PA3S2
Date: 26/06/2019

REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	P1633547	
Claimant Vehicle No :	SKM3350X	Insured Vehicle No :	GX6397G	
Date of Loss:	31/05/2016	Nature of Claim:	TP	Claim No: C0386155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM3350X	Engine No:	3GR0159840
Make & Model:	LEXUS GS300, 3.0 (A)	Chassis No:	JTHBG96S905035638
Reg. Date:	17/03/2006 (Man. Year: 2006)	Odometer:	219131 km
Colour:	Grey		
Engine Capacity:	2994 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Falken 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	29,850.70	20,664.37	9,186.33	30.77	
Miscellaneous Items	0.00	0.00	0.00		
Labour	5,130.00	3,820.00	1,310.00	25.54	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	34,980.70	24,484.37	10,496.33	30.01	
Approved Total (Overridden) (S\$)		18,000.00			
	(S\$)	34,980.70	18,000.00	16,980.70	48.54
+ GST 7.00/7.00% (S\$)	2,448.65	1,260.00	1,188.65	48.54	
Nett Amount (S\$)	37,429.35	19,260.00	18,169.35	48.54	
+ Car Rental (10.0 x S\$150.00/day + 7.00% GST) (S\$)		1,605.00			
+ Doc/Search Fee (S\$)		5.35			
Nett Liability (S\$)		20,870.35			
Global Sum Settlement (S\$)		20,000.00			

INSPECTION

Date of Assignment:	02/06/2016		Em-1 Auto Pte Ltd (HQ)
Date Inspected:	02/06/2016	Inspected At:	Blk 8 Sin Ming Industrial Estate Sector C, #01-68 Singapore 575643
Estimated Period of Repair:	14.0 days		

Adjuster: MA CHIN FOOK

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2019)
Parts: 143	LEXUS GS300 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKM3350X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID (CONSISTENT)	Dented	992.50 F	*992.50 FL
2	1		*BOOT LID BADGE (CONSISTENT)	Necessary	75.00 F	*75.00 FL
3	1		*BOOT LID EMBLEM LEXUS (CONSISTENT)	Necessary	86.10 F	*86.10 FL
4	1		*BOOT LID EMBLEM GS300 (CONSISTENT)	Necessary	86.10 F	*86.10 FL
5	1		*BOOT LID OUTER GARNISH (CONSISTENT)	Distorted	1,394.00 F	*1,394.00 FL
6	1		*SET BOOT LID OUTER GARNISH CLIPS (CONSISTENT)	Necessary	40.00 F	*40.00 FL
7	2		*BOOT LID NUMBER PLATE LAMP (CONSISTENT)	Cracked	259.40 F	*259.40 FL
8	1		*BOOT LID OPENER SWITCH (CONSISTENT)	Shorted	158.10 F	*158.10 FL
9	1		*BOOT LID KEY LOCK (CONSISTENT)	Serviceable	341.80 F	*- FL
10	2		*BOOT LID LAMPS (CONSISTENT)	Cracked	650.00 F	*650.00 FL
11	2		*BOOT LID LAMPS INNER SEALER (CONSISTENT)	Necessary	72.00 F	*72.00 FL
12	2		*SET BOOT LID LAMPS CLIPS (CONSISTENT)	Necessary	50.00 F	*50.00 FL
13	2		*BOOT LID STOPPER (CONSISTENT)	Serviceable	36.00 F	*- FL
14	1		*BOOT LID INSULATOR (CONSISTENT)	Distorted	452.10 F	*452.10 FL
15	1		*SET BOOT LID INSULATOR CLIPS (CONSISTENT)	Necessary	40.00 F	*40.00 FL
16	1		*BOOT LID POCKET HANDLE (CONSISTENT)	Serviceable	173.00 F	*- FL
17	1		*BOOT LID INNER LOCK (CONSISTENT)	Bent	1,377.90 F	*1,377.90 FL
18	1		*BOOT LID LOCK COVER (CONSISTENT)	Cut	96.40 F	*96.40 FL
19	1		*BOOT LID AUTO LOCK ACTUATOR (CONSISTENT)	Shorted	481.70 F	*481.70 FL
20	1		*BOOT LID LOCK CATCH (CONSISTENT)	Bent	66.20 F	*66.20 FL
21	1		*BOOT LID WEATHERSTRIP (CONSISTENT)	Distorted	205.60 F	*205.60 FL
22	2		*BOOT LID HINGES (CONSISTENT)	Bent	238.60 F	*238.60 FL
23	2		*BOOT LID ABSORBER (CONSISTENT)	Bent	572.20 F	*572.20 FL
24	1		*REAR BUMPER (CONSISTENT)	Deformed	1,099.80 F	*1,099.80 FL
25	2		*REAR BUMPER SIDE RETAINERS (CONSISTENT)	Distorted	217.60 F	*217.60 FL
26	2		*REAR BUMPER ATTACHMENT RETAINERS (CONSISTENT)	Distorted	136.00 F	*136.00 FL
27	1		*SET REAR BUMPER CLIPS (CONSISTENT)	Necessary	50.00 F	*50.00 FL
28	2		*REAR BUMPER SIDE SCREW COVER (CONSISTENT)	Necessary	55.40 F	*55.40 FL
29	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Bent	556.80 F	*556.80 FL
30	2		*REAR BUMPER REINFORCEMENT BRACKET (CONSISTENT)	Bent	322.60 F	*322.60 FL
31	1		*REAR BUMPER SPONGE (CONSISTENT)	Distorted	175.50 F	*175.50 FL
32	2		*REAR BUMPER TOWING COVER (CONSISTENT)	Distorted	72.00 F	*72.00 FL
33	1		*REAR BUMPER BOTTOM COVER (CONSISTENT)	Distorted	156.20 F	*156.20 FL
34	1		*SET REAR BUMPER BOTTOM COVER CLIPS (CONSISTENT)	Necessary	30.00 F	*30.00 FL
35	1		*END PANEL (CONSISTENT)	Bent	771.90 F	*771.90 FL
36	1		*END PANEL TOP TRIM (CONSISTENT)	Distorted	333.00 F	*333.00 FL
37	1		*SET END PANEL TOP TRIM CLIPS (CONSISTENT)	Necessary	30.00 F	*30.00 FL
38	1		*SPARE TYRE PANEL (CONSISTENT)	Repair	938.40 F	*- FL
39	1		*SPARE TYRE PANEL TOP BOARD (CONSISTENT)	Distorted	359.50 F	*359.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SPARE TYRE PANEL TOP SIDE BOARD (CONSISTENT)	O/s Serviceable/N/s Distorted	296.00 F	*148.00 FL
41	1		*SPARE TYRE PANEL TOP TRAY (CONSISTENT)	Distorted	459.60 F	*459.60 FL
42	1		*SPARE TYRE PANEL TOP INNER INSULATOR (CONSISTENT)	Distorted	541.80 F	*541.80 FL
43	1		*SPARE TYRE WHEEL NUT (CONSISTENT)	Bent	65.20 F	*65.20 FL
44	1		*REAR KEY ANTENNA SENSOR (CONSISTENT)	Serviceable	216.00 F	*- FL
45	1		*REAR CHASSIS FRAME MEMBER LH (CONSISTENT)	Repair	756.20 F	*- FL
46	2		*TAILLAMPS (CONSISTENT)	Cracked	1,891.20 F	*1,891.20 FL
47	2		*TAILLAMPS INNER SEALER (CONSISTENT)	Necessary	72.00 F	*72.00 FL
48	2		*SET TAILLAMPS CLIPS (CONSISTENT)	Necessary	50.00 F	*50.00 FL
49	2		*TAILLAMPS SIDE COVER GARNISH (CONSISTENT)	Distorted	150.00 F	*150.00 FL
50	1		*TAILLAMP PANEL LH (CONSISTENT)	Bent	227.80 F	*227.80 FL
51	1		*REAR FENDER LH (CONSISTENT)	Bent	1,876.90 F	*1,876.90 FL
52	1		*REAR FENDER TOP SIDE JOINT PANEL LH (CONSISTENT)	Bent	149.50 F	*149.50 FL
53	1		*REAR FENDER TOP SIDE RAILING GARNISH (CONSISTENT)	N/s Distorted/O/s Serviceable	172.00 F	*86.00 FL
54	1		*SET REAR FENDER TOP SIDE RAILING GARNISH CLIPS (CONSISTENT)	N/s Necessary/O/s NotNecessary	50.00 F	*25.00 FL
55	1		*REAR FENDER INNER TRIM (CONSISTENT)	N/s Distorted/O/s Serviceable	1,075.00 F	*536.00 FL
56	2		*SET REAR FENDER INNER TRIM CLIPS (CONSISTENT)	Necessary	60.00 F	*60.00 FL
57	2		*REAR FENDER INNER SHIELD (CONSISTENT)	Distorted	338.00 F	*338.00 FL
58	2		*SET REAR FENDER INNER SHIELD CLIPS (CONSISTENT)	Necessary	50.00 F	*50.00 FL
59	1		*REAR FENDER BOTTOM ARCH RUBBER LH (CONSISTENT)	Distorted	146.50 F	*146.50 FL
60	2		*REAR AIR VENTS (CONSISTENT)	Cracked	170.00 F	*170.00 FL
61	1		*FUEL LID COVER (CONSISTENT)	Serviceable	110.00 F	*- FL
62	1		*FUEL LID COVER LOCK (CONSISTENT)	Serviceable	65.00 F	*- FL
63	1		*REAR SPAEKER PANEL OUTER RAILING GARNISH (CONSISTENT)	N/s Distorted	438.20 F	*219.10 FL
64	2		*SET REAR SPEAKER PANEL OUTER RAILING GARNISH CLIPS (CONSISTENT)	Serviceable	80.00 F	*- FL
65	1		*REAR SPEAKER PANEL BOTTOM INSULATOR (CONSISTENT)	Serviceable	495.80 F	*- FL
66	1		*SET REAR SPEAKER PANEL BOTTOM INSULATOR CLIPS (CONSISTENT)	Not Necessary	40.00 F	*- FL
67	1		*REAR WINDSCREEN MOULDING (CONSISTENT)	Necessary	197.00 F	*197.00 FL
68	1		*REAR WINDSCREEN INNER SEAL (CONSISTENT)	Necessary	60.00 F	*60.00 FL
69	1		*ROOF TOP MOULDING (CONSISTENT)	O/s Serviceable/N/s Distorted	542.60 F	*271.30 FL
70	2		*SET ROOF TOP MOULDING CLIPS (CONSISTENT)	Necessary	60.00 F	*60.00 FL
71	1		*REAR EXHAUST SILENCER (CONSISTENT)	Bent	1,853.60 F	*1,853.60 FL
72	6		*REAR EXHAUST MOUNTINGS (CONSISTENT)	Not Necessary	228.00 F	*- FL
73	2		*REAR EXHAUST MOUNTINGS BRACKET (CONSISTENT)	Serviceable	224.00 F	*- FL
74	1		*REAR EXHAUST GASKET (CONSISTENT)	Necessary	65.00 F	*65.00 FL
75	2		*REAR EXHAUST HEAT PLATE (CONSISTENT)	Not Necessary	270.00 F	*- FL
76	1		*REAR DOOR LH (CONSISTENT)	Repair	1,062.00 F	*- FL
77	1		*REAR DOOR INNER LOCK LH (CONSISTENT)	Jammed	719.60 F	*719.60 FL
78	1		*REAR DOOR WEATHERSTRIP LH (CONSISTENT)	Not Necessary	266.80 F	*- FL
79	1		*REAR WINDSCREEN SEALANT (CONSISTENT)	Necessary	60.00 FS	*40.00 FS
80	1		*REAR NUMBER PLATE WITH COVER (SPECIAL) (CONSISTENT)	Distorted	150.00 FS	*80.00 FS
81	1		*SET REVERSE SENSOR (CONSISTENT)	Shorted	250.00 FS	*220.00 FS
82	1		*SET BODY PANEL JOINT SEALANT (CONSISTENT)	Necessary	120.00 FS	*80.00 FS
83	1		*SET REAR FLOOR PANEL INSULATOR PAD (CONSISTENT)	Necessary	150.00 FS	*120.00 FS
84	2		*REAR EXHAUST CHROME PIPE (CONSISTENT)	Bent	280.00 FS	*100.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (S\$)	29,850.70	22,889.30
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	2,224.93
					Total Parts (S\$)	29,850.70	20,664.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	2,000.00	1,600.00
2	SPRAY PAINTING.	New	1,800.00	1,400.00
3	CHECK WIRING.	New	50.00	30.00
4	ANTI RUST.	New	180.00	100.00
5	TOWING FEES.	New	70.00	70.00
6	REMOVE AND INSTALL REAR WINDSCREEN.	New	140.00	120.00
7	REMOVE AND INSTALL CARPET AND SEAT.	New	120.00	80.00
8	REMOVE AND INSTALL REVERSE SENSOR.	New	90.00	60.00
9	REMOVE AND INSTALL REAR EXHAUST SILENCER.	New	150.00	80.00
10	REMOVE AND INSTALL PETROL TANK.	New	120.00	0.00
11	REMOVE AND INSTALL REAR DOOR PARTS.	New	90.00	0.00
12	TO JACK AND ALIGNMENT CHASSIS FRAME MEMBER.	New	320.00	280.00
Gross Labour Cost (S\$)			5,130.00	3,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >