



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2004600  
INV Date 26/06/2020  
Reference CC3/LPC16009279/Kda3q2-  
Code LPC2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5980Y  
Insured Veh. GBA 650U  
Claim No. 16/16/16/VC00/018805  
Policy No. Z/16/VC00/097651  
Accident Date 17/05/2016  
Inspection Date 17/05/2016

Description	Total
Third Party Express Settlement	450.00
<b>Subtotal</b>	<b>450.00</b>
<b>GST (7%)</b>	<b>31.50</b>
<b>Grand Total</b>	<b>481.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC16009279/Kwa3q2

100 BEACH ROAD  
#19-00 SHAW TOWERSINGAPORE 189702

Date : 09-06-2016



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBA 650U	<b>Veh. Inspected</b>	SHD 5980Y
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	15/16/16/VC20/018494	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	17/05/2016

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA WISH (A)	<b>c.c</b>	1987
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2011
<b>Chassis No.</b>	JTDGJ20W905003249	<b>Colour</b>	WHITE/RED
<b>Odometer</b>	538658	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	FALKEN	4 mm
<b>L/H Front Tyre</b>	195/65 R15	FALKEN	4 mm
<b>R/H Rear Tyre</b>	195/65 R15	FALKEN	3 mm
<b>L/H Rear Tyre</b>	195/65 R15	FALKEN	3 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	17/05/2016	<b>Inspection Date</b>	17/05/2016
<b>Survey held at</b>	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5980Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	BUCKLED	585.36	585.36
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	130.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	318.11	-
1	FRONT BUMPER RETAINER RH	DISTORTED	74.50	74.50
1	FRONT BUMPER RETAINER LH	SERVICEABLE	74.50	-
1	FRONT BUMPER FOG LAMP RH	SERVICEABLE	208.00	-
1	FRONT FOG LAMP OUTER CHROME RH	SERVICEABLE	190.00	-
1	FRONT BUMPER FOG LAMP GRILLE RH	SERVICEABLE	150.00	-
1	FRONT HEADLAMP RH	CUT	672.00	672.00
1	WINDSCREEN WASHER TANK	SERVICEABLE	166.00	-
1	RADIATOR GRILLE	SERVICEABLE	462.48	-
1	BONNET	TO REPAIR SEE LABOUR	1,019.16	-
1	BONNET CENTRE 'TOYOTA' LOGO BADGE	NOT NECESSARY	115.44	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	81.60	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	81.60	-
1	FRONT FENDER RH	SERVICEABLE	837.60	-
1	FRONT FENDER LINER RH	SERVICEABLE	369.14	-
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	1,222.32	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,554.00	-
	LESS 25% DISCOUNT		-2,077.95	-332.97
			6,233.86	998.89
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	50.00	50.00
1	CNG STICKER (SN)	NECESSARY	30.00	15.00
1	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT PANEL OUTER GARNISH CLIP (SN)	NOT NECESSARY	40.00	-

Report Ref No. CC3/LPC16009279/Kwa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
1	TYRE FRT RH (SN)	SERVICEABLE	180.00	-
1	TYRE RIM FRT RH (SN)	SERVICEABLE	120.00	-
1	FRONT FENDER ADVERTISEMENT STICKER (SN)	NOT NECESSARY	250.00	-
1	FRONT DOOR ADVERTISEMENT STICKER (SN)	NOT NECESSARY	250.00	-
			1,030.00	65.00
	<b>LABOUR</b>			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT,BONNET,BONNET HINGE RH,BONNET HINGE LH,FRONT SUPPORT PANEL ASSY AND FRONT DOOR RH .		1,400.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED.		1,350.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	-
	TO REMOVE AND REPLACE CORPORATE STICKER .	NOT NECESSARY	330.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			3,930.00	850.00
	<b>GRAND TOTAL</b>		<b>11,193.86</b>	<b>1,913.89</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITD PRE-ACCIDENT CONDITION)</b>			<b>1,550.00</b>

Report Ref No. CC3/LPC16009279/Kwa3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5980Y

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

