

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHB 7523G - AXA

Candy

Not Authored
L/Ramp @ 29 Oct

Vehicle No.:	SHB 7523G - Candy
Chassis No.:	KL1LA69RJBB073898
Vehicle Make:	CHEVROLET
Vehicle Model:	CHEVROLET EPICA 2.0
Date of Accident :	23.06.16
Third Party Insurer :	AXA

PART			LIST	
1	1	Front Bumper	\$	<i>CMA</i> 1,202.00 ✓
2	1	Front Bumper Retainer RH	\$	<i>Sm</i> 102.00 X
3	1	Front Bumper Retainer LH	\$	<i>Dis</i> 102.00 ✓
4	1	Front Bumper Reinforcement	\$	<i>R</i> 295.25 X
5	1	Front Bumper Lower Absorber	\$	<i>Sm</i> 180.00 X
6	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Sm</i> 32.40 X
7	1	Headlamp LH	\$	<i>CMA</i> 816.00 ✓
8	1	Front Shock Absorber Assy LH	\$	<i>Sm</i> 216.17 X
9	1	Front Lower Arm LH	\$	<i>Sm</i> 283.00 X
10	1	Front Knuckle Arm LH	\$	<i>Sm</i> 230.00 X
11	1	Front Fender LH	\$	<i>B</i> 837.60 ✓
12	1	Front Fender Liner LH	\$	<i>CMA</i> 47.00 ✓
13	1	Front Stabilizer Bar	\$	<i>Sm</i> 234.00 X
14	1	Front Stabilizer Bar Link LH	\$	<i>Sm</i> 51.79 X
15	1	Front Stabilizer Bar Bracket LH	\$	<i>R</i> 105.75 X
16	1	Front Stabilizer Bar Bush LH	\$	<i>Sm</i> 66.00 X
17	1	Drive Shaft LH	\$	<i>R</i> 900.00 X
18	1	Resonator (B/S Fender LH) AIR BOX	\$	<i>Sm</i> 134.67 X
19	1	Resonator Hose	\$	<i>Sm</i> 37.00 X
20	1	Front Door LH	\$	<i>R</i> 1,133.00 X
21	1	Front Side View Mirror LH	\$	<i>Sm</i> 939.00 X
22	1	Side Rocker Panel Garnish LH	\$	<i>Sm</i> 236.40 X

TOTAL	\$	8,181.03
10%	\$	818.10
	\$	7,362.93

Specical Nett

1	1 Set	Front Bumper Fastener Clip	\$	<i>Sm</i> 30.00 ✓
2	1 Set	Front Fender Liner Clip LH	\$	<i>Sm</i> 30.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7523G - AXA

3	1	Door Sticker "Trans-cab" LH	\$	nn	80.00	X
4	1	Door Sticker " 6555-3333 "LH	\$	nn	80.00	X
5	1set	Side Rocker Panel Garnish Clip LH	\$	nn	60.00	X
6	1	Front Tyre LH	\$	sn	360.00	X
7	1	Front Wheel Rim LH	\$	sn	254.00	X
8	1	Hub Cup Rim Front	\$	nn	35.00	X
9	1Set	Rear Bumper Fastener Clip	\$	nn	35.00	✓
10	2	Rear Windscreen Sealant	\$	nn	80.00	X
11	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	X
12	1	Rear Tyre LH	\$	sn	360.00	X
13	1	Rear Wheel Rim LH	\$	sn	254.00	X

TOTAL	\$	1,758.00
TOTAL PARTS	\$	9,120.93

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 5,400.00 400

To Rust-Proofing Of The Affected Areas.

\$ 220.00 300

Putty and Spray Painting Of The Affected
Portion.

\$ 5,350.00 400

To Check Electrical Lighting Concerned.

\$ 170.00 200

To check steering geometry and computer wheel
alignment

\$ nn 220.00 X

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing.

\$ nn 380.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$ nn 170.00 X

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**Candy**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHB 7523G - AXA

To Transfer Of Fender Fittings, Attachments

And Perform Water Seepage Test.

\$

nn 170.00 X

To transfer of tire, rim and on wheel balancing.

\$

nn 170.00 X**TOTAL**

\$

12,420.00**Over All Total**

\$

21,540.93**REPAIR DAYS****10 DAYS***2 days*