

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AXA16013751/AGA3S2**Date:** 12/07/2019REFERENCE

Handling Insurer:	AXA Insurance Pte Ltd	Policy No:	GA100793
Claimant Vehicle No :	SGM5062L	Insured Vehicle No :	SJD1656L
Date of Loss:	21/07/2016	Nature of Claim:	TP
		Claim No:	C0392892

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM5062L	Engine No:	HIDDEN
Make & Model:	TOYOTA BELTA, 1.3 (A)	Chassis No:	SCP921016762
Reg. Date:	20/10/2006 (Man. Year: 2006)	Odometer:	165072 km
Colour:	Silver		
Engine Capacity:	1296 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	ACELERE 6 mm	Rear Left Side:	ACELERE 6 mm
Front Right Side:	ACELERE 6 mm	Rear Right Side:	ACELERE 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,924.55	4,186.05	7,738.50	64.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	1,980.00	2,710.00	57.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,614.55	6,166.05	10,448.50	62.89
Approved Total (Overridden) (\$\$)		4,900.00		
(\$\$)	16,614.55	4,900.00	11,714.55	70.51
+ GST 7.00/7.00% (\$\$)	1,163.02	343.00	820.02	70.51
Nett Amount (\$\$)	17,777.57	5,243.00	12,534.57	70.51

INSPECTION

Date of Assignment:	25/07/2016	Auto N Cars Services Pte Ltd (HQ)
Date Inspected:	25/07/2016 Inspected At:	Blk 1 Kaki Bukit Ave 6 #01-04, AutoBay @ Kaki Bukit
Estimated Period of Repair:	8.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,750.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2019)
Parts:	143	TOYOTA BELTA 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM5062L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (CONSISTENT)	Deformed	410.00 FL	*410.00 FL
2	1		*REAR BUMPER RH RETAINER (CONSISTENT)	Necessary	65.00 FL	*65.00 FL
3	1		*REAR BUMPER LH RETAINER (CONSISTENT)	Necessary	65.00 FL	*65.00 FL
4	1		*REAR BUMPER CLIPS (CONSISTENT)	Necessary	6.40 FL	*6.40 FL
5	1		*REAR BUMPER REINFORCEMENT (CONSISTENT)	Not Necessary	350.00 FL	*- FL
6	2		*REAR BUMPER PARKING SENSOR (CONSISTENT)	Not Necessary	560.00 FL	*- FL
7	1		*REAR END PANEL (CONSISTENT)	Not Necessary	610.00 FL	*- FL
8	1		*LH REAR FENDER (CONSISTENT)	Dented	790.00 FL	*790.00 FL
9	1		*LH REAR WHEEL HOUSING (CONSISTENT)	Repair	1,100.00 FL	*- FL
10	1		*LH REAR DOOR ASSEMBLY (CONSISTENT)	Dented	980.00 FL	*980.00 FL
11	1		*LH REAR DOOR LOCK MECHANISM (CONSISTENT)	Not Necessary	750.00 FL	*- FL
12	1		*LH REAR DOOR WEATHERSTRIP (CONSISTENT)	Not Necessary	260.00 FL	*- FL
13	1		*LH REAR DOOR POWER WINDOW REGULATOR (CONSISTENT)	Not Necessary	150.00 FL	*- FL
14	1		*LH REAR DOOR POWER WINDOW REGULATOR MOTOR (CONSISTENT)	Not Necessary	360.00 FL	*- FL
15	1		*LH REAR DOOR OUTER HANDLE (CONSISTENT)	Not Necessary	130.00 FL	*- FL
16	1		*LH REAR DOOR GLASS OUTER WEATHERSTRIP (CONSISTENT)	Not Necessary	120.00 FL	*- FL
17	1		*LH REAR DOOR FRAM STICKER (CONSISTENT)	Necessary	75.00 FL	*75.00 FL
18	1		*LH REAR FENDER GLASS SEALANT (CONSISTENT)	Necessary	80.00 FL	*40.00 FL
19	1		*LH REAR TYRE (CONSISTENT)	Cut	690.00 FL	*690.00 FL
20	1		*LH REAR TYRE RIM (CONSISTENT)	Cut	1,100.00 FL	*1,100.00 FL
21	1		*LH REAR KNUCKLE ARM (CONSISTENT)	Not Necessary	890.00 FL	*- FL
22	1		*LH REAR WHEEL BEARING HUB (CONSISTENT)	*Check	788.00 FL	*- FL
23	1		*LH REAR LOWER ARM (CONSISTENT)	Not Necessary	590.00 FL	*- FL
24	1		*LH REAR CONTROL ARM (CONSISTENT)	Not Necessary	650.00 FL	*- FL
25	1		*LH REAR DOOR TOP AND BOTTOM HINGE (CONSISTENT)	Not Necessary	95.00 FL	*- FL
26	1		*REAR WINDSCREEN SEALANT (CONSISTENT)	Necessary	35.00 FL	*35.00 FL
27	1		*REAR WINDSCREEN MOULDING (CONSISTENT)	Necessary	250.00 FL	*120.00 FL
28	1		*REAR WINDSCREEN INNER SEAL (CONSISTENT)	Necessary	25.00 FL	*25.00 FL
29	1		*REAR AXLE ASSEMBLY (CONSISTENT)	*Check	1,900.00 FL	*- FL
30	1		*REAR SHOCK ABSORBER (CONSISTENT)	*Check	280.00 FL	*- FL
31	1		*RH REAR FENDER (CONSISTENT)	Dented	1,100.00 FL	*1,100.00 FL
32	1		*FUEL OUTER COVER (CONSISTENT)	Not Necessary	70.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	3		*BODY SEALANT (CONSISTENT)	Not Necessary	75.00 FL	*- FL
34	1		*RH TAILLAMP CLIP (CONSISTENT)	Necessary	80.00 FL	*80.00 FL
35	1		*LH TAILLAMP ASSEMBLY (CONSISTENT)	Not Necessary	420.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					15,899.40	5,581.40
- List Item Discount on L Items 25.00/25.00% (\$\$)					3,974.85	1,395.35
Total Parts (\$\$)					11,924.55	4,186.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK AND STRAIGHTEN REAR ACCIDENT AREA, CUT AND WELD DAMAGED PANEL AND REALIGN THE SAME.	New	2,300.00	100.00
2	TO PUTTY AND SPRAY RH AND LH REAR FENDER, LH REAR DOOR, REAR BUMPER, RH AND LH SIDE ROOF PANEL AND END PANEL.	New	1,000.00	1,000.00
3	TO REMOVE AND REFIT REAR WINDSCREEN.	New	120.00	100.00
4	TO REMOVE AND REFIT INTERIOR FITTING, TRIMMINGS, GARNISH, SEAT AND OTHER TO ENABLE REPAIR.	New	200.00	80.00
5	TO DROP PETROL TANK, PIPES AND HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	200.00	80.00
6	TO DO WHEEL ALIGNMENT.	New	120.00	80.00
7	TO REMOVE AND REFIT LH REAR DOOR FITTING, FIXTURE AND CONDUCT WATER SEEPAGE AND WIND NOISE TEST.	New	120.00	80.00
8	TO DROP REAR AXLE AND SUSPENSION ASSEMBLY, REMOVE AND RENEW THE NECESSARY PARTS. FINAL CHECKING AND TESTING.	New	450.00	350.00
9	TO CHECK WIRING AND ALL LIGHTING.	New	80.00	30.00
10	TO RUST ROOF THE AFFECTED AREAS.	New	100.00	80.00
Gross Labour Cost (\$\$)			4,690.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >