

Surveyor:

DOI:

Date / Time:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES/NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

25,248.04

(12 days)

Reduction:

23 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lin:

0%

Repair Cost:

SS

24,015.40

Loss of Rental (LOR):

SS

1,669.20

(3 days)

x

28.40

Loss of Use (LOU):

SS

—

(\$

x

days)

Loss of Income (LOI):

SS

—

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

LOR + LOI

GIA/LTA Search

SS

6.00

Medical:

SS

—

Disbursement:

SS

—

Legal Cost

SS

—

Total:

SS

28,684.60

Global Sum SS:

27,500.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

27,500.00

Name 1:

TRANSG-CHD

AUTO

SERVICES

PTE

LTD

Payee 2 (Strike if N.A.):

SS

—

Name 2:

—

Payee 3 (Strike if N.A.):

SS

—

Name 3:

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 450.00

ASS. REC. BY:

REF: 6PC /Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: 1.8-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S/H 53465 Yr Regn: 09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude cc 1995Colour M. White / R A/C: Insured / Std / NI / NASp. Reading 221813 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABCL15AUC 2F9355Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: Renault

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 22/7/16 D.O.I. 26/7/16

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear O/S & 1st O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/7 File pass to CustomerFile #25,248.04CRAP: \$69,416.27 (75%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC3/LPC16013956/Khg3	
100 BEACH ROAD #19-00 SHAW TOWERSINGAPORE 189702		Date : 27-07-2016	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJG 8301Z	Veh. Inspected	SHC 5346J
Policy No.	Z16VP05010945	Coverage (\$)	0.00
Claim No.	16/16/16/VP05/019052	Excess (\$)	0.00
Assign From		Assign Date	27/07/2016
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	22/07/2016	Inspection Date	26/07/2016
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/LPC16013956/Khg3

Date: 27.07.2016

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC53461

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.07.2016 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	94,664.31
Revised Estimate Amount	: S\$	25,248.04
"Check" Items Amount	: S\$	6,844.38
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear & O/S & Front O/S portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 12.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHC5346J

Vehicle to be Exported: Yes

Intended De-registration Date: 25 Jul 2016

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001964

Chassis No.: VF1ABL15AUC279355

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 30 Sep 2014

First Registration Date: 30 Sep 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Sep 2022

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2022

COE Category: A - Car (up to 1600cc & 97kW (130bhp))

COE Period(Years): 8

PQP Paid: \$50,704.00

COE Rebate Amount: \$39,154.00

Total Rebate Amount: \$48,527.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Jul 2016

OK

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5346J - Lonpac*Not Authenticated*
8**ROEL**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5346J - ROEL

VF1ABL15AUC279355

RENAULT

LATITUDE

22.07.16

Lonpac**PART****LIST**

1	1	BUMPER COVER FRT	\$	R ₁	968.79 ✓
2	1	BUMPER SPOILER FRT	\$	S ₁	139.81 X
3	1	BUMPER ABSORBER FRT	\$	CMS	303.60 ✓
4	1	BUMPER RETAINER FRT LH	\$	S ₁	116.47 X
5	1	BUMPER SUPPORT FRT LH(Headlamp lower)	\$	S ₁	18.37 X
6	1	BUMPER RETAINER FRT RH	\$	D ₁	115.98 ✓
7	1	BUMPER SUPPORT FRT RH(Headlamp lower)	\$	CMS	18.37 ✓
8	1	BUMPER UNDERTRAY FRT	\$	S ₁	363.71 X
9	1	BUMPER GRILLE LOWER FRT	\$	S ₁	205.23 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	S ₁	159.39 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	S ₁	159.39 X
12	1	BUMPER BEAM FRT	\$	R ₁	703.14 ✓
13	1	RADIATOR GRILLE	\$	CMS	1,313.68 ✓
14	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R ₁	173.36 ✓
15	1	RADIATOR GRILLE FRAME	\$	CMS	1,041.35 ✓
16	1	FRAME FULL SUPPORT PANEL	\$	CMS	473.77 ✓
17	1	FRAME FULL SUPPORT BRACKET	\$	R	69.07 X
18	1	FRONT BRACE PANEL	\$	R	136.32 X
19	1	HEADLAMP LH	\$	S ₁	911.10 X
20	1	HEADLAMP RH	\$	MS (R ₁)	911.10 ✓
21	1	HEADLAMP PANEL FRT LH	\$	R	134.59 X
22	1	HEADLAMP PANEL FRT RH	\$	R	134.59 X
23	1	BONNET	\$	R R ₁	1,493.56 X
24	1	BONNET INSULATOR	\$	S ₁	312.10 X
25	1	BONNET HINGE LH	\$	R	267.93 X
26	1	BONNET HINGE RH	\$	R	267.93 X
27	1	BONNET LOCK	\$	R	234.99 X
28	1	FENDER PANEL FRT LH	\$	R	602.95 X
29	1	FENDER PANEL FRT RH	\$	R ₁	602.95 ✓
30	1	FENDER WHEELARCH FRT LH (Linner)	\$	S ₁	107.32 X
31	1	FENDER WHEELARCH FRT RH (Linner)	\$	S ₁	214.49 X
32	1	WIPER RESERVOIR	\$	S ₁	190.96 X
33	1	WIPER RESERVOIR NECK	\$	S ₁	27.78 X
34	1	WIPER RESERVOIR MOTOR	\$	S ₁	100.95 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5346J - Lonpac

ROEL

35	1	RADIATOR	\$	Sn	924.77	X
36	1	RADIATOR MTG LOWER	\$	Sn	42.96	X
37	1	RADAIOR FAN COWLING	\$	Sn	631.18	X
38	1	RADIATOR FAN MOTOR LH	\$	Sn	744.12	X
39	1	RADIATOR FAN MOTOR RH	\$	Sn	1,138.04	X
40	1	RADIATOR TANK	\$	Sn	249.71	X
41	1	ENGINE UNDERTRAY	\$	Sn	434.60	✓
42	1	A/C CONDENSER	\$	Per	1,554.13	✓
43	1	TRANSMISSION COOLER	\$	Sn	852.66	X
44	1	BUMPER COVER REAR	\$	Rt	852.66	✓
45	1	BUMPER BRACKET CTR REAR	\$	D/V	87.29	✓
46	1	BUMEPR BRACKET SIDE LH REAR (Taillamp lower)	\$	Sn	34.61	X
47	1	BUMEPR RETAINER LH REAR	\$	Sn	104.59	✓
48	1	BUMEPR BRACKET SIDE RH REAR (Taillamp lower)	\$	D/V	34.61	✓
49	1	BUMEPR RETAINER RH REAR	\$	Sn	104.59	X
50	1	BUMPER LOWER REAR	\$	Rt	591.41	✓
51	1	BUMPER BEAM REAR	\$	Rt	598.08	✓
52	1	BUMPER BEAM BRACKET LH REAR	\$	R	173.81	✓
53	1	BUMPER BEAM BRACKET RH REAR	\$	Rt	173.81	✓
54	1	BUMPER REFLECTOR LH	\$	Sn	33.55	X
55	1	BUMPER REFLECTOR RH	\$	Rt	33.55	✓
56	1	BOOT REAR	\$	Rt	2,209.75	✓
57	1	BOOT FINISHER (Moulding)	\$	Sn	361.58	X
58	1	BOOT LOCK	\$	R	155.90	X
59	1	BOOT LOCK CATCH	\$	R	57.23	✓
60	1	BOOT WHEATERSTRIP	\$	Sn	248.50	X
61	1	BOOT REFLECTOR LAMP LH	\$	Sn	379.50	X
62	1	BOOT REFLECTOR LAMP RH	\$	Sn	379.50	✓
63	1	BOOT BADGE 'RENAULT'	\$	Rt	173.35	✓
64	1	BOOT BADGE	\$	Rt	173.35	✓
65	1	BOOT STRUT LH	\$	Sn	212.36	X
66	1	BOOT STRUT RH	\$	Sn	212.36	X
67	1	BOOT HINGE LH	\$	R	282.96	X
68	1	BOOT HINGE RH	\$	R	282.96	✓
69	2	LICENCE PLATE LAMP	\$	Sn	84.00	X
70	2	BOOT RUBBER PLUG	\$	Sn	170.63	X
71	1	WINDSCREEN REAR	\$	Sn	1,125.60	X
72	1	TAILLAMP LH	\$	CHS	425.04	✓
73	1	TAILLAMP PANEL LH	\$	R	759.00	X
74	1	TAILLAMP RH	\$	mg CHS	425.04	✓
75	1	TAILLAMP PANEL RH	\$	R	759.00	X
76	1	FENDER PANEL REAR LH	\$	R	2,537.80	X

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5346J - Lonpac

77	1	FENDER PANEL REAR RH	\$	1,493.80	2,537.80	✓
78	1	FENDER WHEELARCH REAR LH (Linner)	\$	Sm	418.06	✓
79	1	FENDER WHEELARCH REAR RH (Linner)	\$	Sm	418.06	✓
80	1	AIR VENT RH	\$	Sm	74.83	✓
81	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	516.50	✓
82	1	FENDER PANEL INNER TRIM REAR LH	\$	Sm	516.50	✓
83	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	N	2,337.72	✓
84	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	N	2,337.72	✓
85	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	1,684.52	✓
86	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	Sm	470.93	✓
87	1	OUTER PANEL REAR (End Panel)	\$	N	1,132.13	✓
88	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sm	308.48	✓
89	1	EXHAUST REAR	\$	N	5,760.00	✓
90	1	EXHAUST CAP REAR	\$	N	177.30	✓
91	1	DOOR PANEL REAR LH	\$	N	2,188.20	✓
92	1	DOOR SEAL REAR LH	\$	Sm	68.02	✓
93	1	DOOR PANEL REAR RH	\$	N	2,188.20	✓
94	1	DOOR SEAL REAR RH	\$	Sm	68.02	✓

TOTAL	\$	57,008.21
10%	\$	5,700.82
	\$	51,307.39

Special Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	N	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	N	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	N	12.00	✓
4	1	BUMPER SUPPORT CLIP FRT LH	\$	N	10.50	✓
5	1	BUMPER BRACKET CLIP FRT RH	\$	N	12.00	✓
6	1	BUMPER SUPPORT CLIP FRT RH	\$	N	10.50	✓
7	1	TOW COVER FRT	\$	Sm	14.50	✓
8	1SET	RADAIOR GRILLE SCREW	\$	N	16.00	✓
9	1SET	BUMPER GRILLE LOWER CLIP	\$	N	69.00	✓
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	N	70.00	✓
11	2	FRAME FULL SUPPORT PANEL NUT	\$	Sm	20.00	✓
12	2	FRAME FULL SUPPORT PANEL STUD	\$	Sm	30.00	✓
13	1SET	WHEELARCH CLIP FRT LH	\$	N	30.50	✓
14	1SET	WHEELARCH CLIP FRT RH	\$	N	29.40	✓
15	1SET	BUMPER RR CLIP	\$	N	66.00	✓
16	1SET	BUMPER BEAM BOLT	\$	Sm	22.22	✓
17	1SET	PARKING AID	\$	Shot	600.00	✓ 570
18	1	BUMPER BRACKET CLIP CTR REAR	\$	N	15.00	✓
19	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	N	12.00	✓

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5346J - Lonpac

20	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40	X
21	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00	X
22	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40	X
23	1	CAP HUB LH RR	\$	sn	35.00	X
24	1	RIM LH RR	\$	sn	385.00	X
25	1	TYRE LH RR	\$	sn	330.00	X
26	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	X
27	1	SPARE TYRE	\$	sn	330.00	X
28	1SET	BOOT FINISHER CLIP	\$	nn	25.10	X
29	1	Rear boots sticker "trans-cab"	\$	nn	30.00	—
30	1	Rear boots sticker "6555-3333"	\$	nn	30.00	—
31	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	nn	22.00	X
32	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	nn	22.00	X
33	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X
34	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X
35	2	Rear windscreen sealant	\$	nn	80.00	40sn
36	1	Windscreen moulding	\$	nn	100.00	2
37	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	30sn
38	1	EXHAUST MOUNTING REAR	\$	sn	65.50	X
39	1	EXHAUST BRACKET REAR	\$	sn	22.22	X
40	1SET	Front licence plate with holder	\$	sn	80.00	45sn
41	1SET	Rear licence plate with holder	\$	sn	80.00	X
42	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
43	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X

TOTAL	\$	3,536.92
TOTAL PARTS	\$	54,844.31

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 16,800.00 ^{1,600.00} 4600

Towing Fees.

\$ 120.00 500

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 18,000.00 ^{1,640.00} 17600

To rust-proofing of the affected areas.

\$ 170.00 900

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5346J - Lonpac**ROEL**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100%
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	210 250%
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To Check Electrical Lighting Concerned.	\$	170.00	80%
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60%
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	X 120
To reinstall rear bumper parking sensor.	\$	170.00	60%
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	80%

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5346J - Lonpac

To repair and realign rear exhaust pipe. \$ *HH* 170.00 X

To dismantle and refit rear undercarriage parts, final checking and testing. \$ *HH* 380.00 X

TOTAL	\$	39,820.00
Over All Total	\$	94,664.31

< parts by parts > Repair Days

~~60~~ DAYS*12 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TRANS-CAB AUTO SERVICES PTE LTD
 NO. 2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
 SHC 5346J - Lonpac

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

Not Authored
 8

SHC 5346J - ROEL
 VF1ABL15AUC279355
 RENAULT
 LATITUDE
 22.07.16
 Lonpac

PART

LIST

1	1	BUMPER COVER FRT	\$	R ₁	968.79 ✓
2	1	BUMPER SPOILER FRT	\$	S _{in}	139.81 X
3	1	BUMPER ABSORBER FRT	\$	CRA	303.60 ✓
4	1	BUMPER RETAINER FRT LH	\$	S _{in}	116.47 X
5	1	BUMPER SUPPORT FRT LH(Headlamp lower)	\$	S _{in}	18.37 X
6	1	BUMPER RETAINER FRT RH	\$	D ₁	115.98 ✓
7	1	BUMPER SUPPORT FRT RH(Headlamp lower)	\$	CRA	18.37 ✓
8	1	BUMPER UNDERTRAY FRT	\$	S _{in}	363.71 X
9	1	BUMPER GRILLE LOWER FRT	\$	S _{in}	205.23 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	S _{in}	159.39 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	S _{in}	159.39 X
12	1	BUMPER BEAM FRT	\$	R ₁	703.14 ✓
13	1	RADIATOR GRILLE	\$	CRA	1,313.68 ✓
14	1	RADIATOR GRILLE BADGE RENAULT	\$	R _{in}	173.36 ✓
15	1	RADIATOR GRILLE FRAME	\$	CRA	1,041.35 ✓
16	1	FRAME FULL SUPPORT PANEL	\$	CRA	473.77 ✓
17	1	FRAME FULL SUPPORT BRACKET	\$	R	69.07 X
18	1	FRONT BRACE PANEL	\$	R	136.32 X
19	1	HEADLAMP LH	\$	S _{in}	911.10 X
20	1	HEADLAMP RH	\$	mg CRA	911.10 ✓
21	1	HEADLAMP PANEL FRT LH	\$	R	134.59 X
22	1	HEADLAMP PANEL FRT RH	\$	R	134.59 X
23	1	BONNET	\$	R R ₁	1,493.56 ✓ X
24	1	BONNET INSULATOR	\$	S _{in}	312.10 X
25	1	BONNET HINGE LH	\$	R	267.93 X
26	1	BONNET HINGE RH	\$	R	267.93 X
27	1	BONNET LOCK	\$	R	234.99 X
28	1	FENDER PANEL FRT LH	\$	R	602.95 X
29	1	FENDER PANEL FRT RH	\$	R ₁	602.95 ✓
30	1	FENDER WHEELARCH FRT LH (Linner)	\$	S _{in}	107.32 X
31	1	FENDER WHEELARCH FRT RH (Linner)	\$	S _{in}	214.49 X
32	1	WIPER RESERVOIR	\$	S _{in}	190.96 X
33	1	WIPER RESERVOIR NECK	\$	S _{in}	27.78 X
34	1	WIPER RESERVOIR MOTOR	\$	S _{in}	100.95 X

35	1	RADIATOR	\$	Sm	924.77	X
36	1	RADIATOR MTG LOWER	\$	Sm	42.96	X
37	1	RADAIOR FAN COWLING	\$	Sm	631.18	X
38	1	RADIATOR FAN MOTOR LH	\$	Sm	744.12	X
39	1	RADIATOR FAN MOTOR RH	\$	Sm	1,138.04	X
40	1	RADIATOR TANK	\$	Sm	249.71	X
41	1	ENGINE UNDERTRAY	\$	Sm	434.60	X
42	1	A/C CONDENSER	\$	Pur	1,554.13	✓
43	1	TRANSMISSION COOLER	\$	Sm	852.66	X
44	1	BUMPER COVER REAR	\$	Ry	852.66	✓
45	1	BUMPER BRACKET CTR REAR	\$	D11	87.29	✓
46	1	BUMEPR BRACKET SIDE LH REAR (Taillamp low)	\$	Sm	34.61	X
47	1	BUMEPR RETAINER LH REAR	\$	Sm	104.59	X
48	1	BUMEPR BRACKET SIDE RH REAR (Taillamp low)	\$	D11	34.61	✓
49	1	BUMEPR RETAINER RH REAR	\$	Sm	104.59	X
50	1	BUMPER LOWER REAR	\$	Ry	591.41	✓
51	1	BUMPER BEAM REAR	\$	Ry	598.08	✓
52	1	BUMPER BEAM BRACKET LH REAR	\$	R	173.81	X
53	1	BUMPER BEAM BRACKET RH REAR	\$	Ry	173.81	✓
54	1	BUMPER REFLECTOR LH	\$	Sm	33.55	X
55	1	BUMPER REFLECTOR RH	\$	Ry	33.55	✓
56	1	BOOT REAR	\$	Ry	2,209.75	✓
57	1	BOOT FINISHER (Moulding)	\$	Sm	361.58	X
58	1	BOOT LOCK	\$	R	155.90	X
59	1	BOOT LOCK CATCH	\$	R	57.23	X
60	1	BOOT WHEATERSTRIP	\$	Sm	248.50	X
61	1	BOOT REFLECTOR LAMP LH	\$	Sm	379.50	X
62	1	BOOT REFLECTOR LAMP RH	\$	Sm	379.50	X
63	1	BOOT BADGE 'RENAULT'	\$	Ry	173.35	✓
64	1	BOOT BADGE	\$	Ry	173.35	✓
65	1	BOOT STRUT LH	\$	Sm	212.36	X
66	1	BOOT STRUT RH	\$	Sm	212.36	X
67	1	BOOT HINGE LH	\$	R	282.96	X
68	1	BOOT HINGE RH	\$	R	282.96	X
69	2	LICENCE PLATE LAMP	\$	Sm	84.00	X
70	2	BOOT RUBBER PLUG	\$	Sm	170.63	X
71	1	WINDSCREEN REAR	\$	Sm	1,125.60	X
72	1	TAILLAMP LH	\$	CMS	425.04	✓
73	1	TAILLAMP PANEL LH	\$	R	759.00	X
74	1	TAILLAMP RH	\$	Mj CMS	425.04	✓
75	1	TAILLAMP PANEL RH	\$	R	759.00	X
76	1	FENDER PANEL REAR LH	\$	R	2,537.80	X

77	1	FENDER PANEL REAR RH	\$	2,537.80 ✓
78	1	FENDER WHEELARCH REAR LH (Linner)	\$	Sn 418.06 X
79	1	FENDER WHEELARCH REAR RH (Linner)	\$	Sn 418.06 A
80	1	AIR VENT RH	\$	Sn 74.83 X
81	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn 516.50 X
82	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn 516.50 A
83	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	M 2,337.72 X
84	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	M 2,337.72 A
85	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	M 1,684.52 X
86	1	SPARE WHEEL PANEL TRIM (Luggage Floor Pan	\$	Sn 470.93 X
87	1	OUTER PANEL REAR (End Panel)	\$	M 1,132.13 ✓
88	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn 308.48 X
89	1	EXHAUST REAR	\$	M 5,760.00 ✓
90	1	EXHAUST CAP REAR	\$	M 177.30 ✓
91	1	DOOR PANEL REAR LH	\$	M 2,188.20 X
92	1	DOOR SEAL REAR LH	\$	Sn 68.02 X
93	1	DOOR PANEL REAR RH	\$	M 2,188.20 X
94	1	DOOR SEAL REAR RH	\$	Sn 68.02 X

TOTAL	\$	57,008.21
10%	\$	5,700.82
	\$	51,307.39

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	M 52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	M 66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	M 12.00 X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	M 10.50 X
5	1	BUMPER BRACKET CLIP FRT RH	\$	M 12.00 X
6	1	BUMPER SUPPORT CLIP FRT RH	\$	M 10.50 X
7	1	TOW COVER FRT	\$	Sn 14.50 A
8	1SET	RADAIOR GRILLE SCREW	\$	M 16.00 X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	M 69.00 X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	M 70.00 X
11	2	FRAME FULL SUPPORT PANEL NUT	\$	Sn 20.00 X
12	2	FRAME FULL SUPPORT PANEL STUD	\$	Sn 30.00 A
13	1SET	WHEELARCH CLIP FRT LH	\$	M 30.50 X
14	1SET	WHEELARCH CLIP FRT RH	\$	M 29.40 A
15	1SET	BUMPER RR CLIP	\$	M 66.00 ✓
16	1SET	BUMPER BEAM BOLT	\$	Sn 22.22 X
17	1SET	PARKING AID	\$	Sheet 600.00 ✓
18	1	BUMPER BRACKET CLIP CTR REAR	\$	M 15.00 X
19	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	M 12.00 X

20	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40	X
21	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00	X
22	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40	X
23	1	CAP HUB LH RR	\$	sn	35.00	X
24	1	RIM LH RR	\$	sn	385.00	X
25	1	TYRE LH RR	\$	sn	330.00	X
26	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	X
27	1	SPARE TYRE	\$	sn	330.00	X
28	1SET	BOOT FINISHER CLIP	\$	nn	25.10	X
29	1	Rear boots sticker "trans-cab"	\$	nn	30.00	—
30	1	Rear boots sticker "6555-3333"	\$	nn	30.00	—
31	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	nn	22.00	X
32	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	nn	22.00	X
33	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X
34	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X
35	2	Rear windscreen sealant	\$	nn	80.00	401W
36	1	Windscreen moulding	\$	nn	100.00	2
37	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	301W
38	1	EXHAUST MOUNTING REAR	\$	sn	65.50	X
39	1	EXHAUST BRACKET REAR	\$	sn	22.22	X
40	1SET	Front licence plate with holder	\$	sn	80.00	455W
41	1SET	Rear licence plate with holder	\$	sn	80.00	X
42	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
43	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X

TOTAL	\$	3,536.92
TOTAL PARTS	\$	54,844.31

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	16,800.00	1600
Towing Fees.	\$	120.00	500
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Putty and spray painting of the affected portion.	\$	18,000.00	1760
To rust-proofing of the affected areas.	\$	170.00	900

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 2501
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To Check Electrical Lighting Concerned.	\$	170.00	401
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	1201
To reinstall rear bumper parking sensor.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	801

CAB AUTO SERVICES PTE LTD
NO 10 KIO ST 63 SINGAPORE 569111
TEL NO. 6257 6666 FAX NO. 6257 1330
REG NO. 201019626G
SHC 5346J - Lonpac

ROEL

To repair and realign rear exhaust pipe. \$ 170.00 X

To dismantle and refit rear undercarriage parts, final
checking and testing. \$ ~ 380.00 X

TOTAL	\$	39,820.00
Over All Total	\$	94,664.31

< parts by parts > Repair Days

~~60~~ DAYS

12 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC3/LPC16013956/Khb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 01-08-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 8301Z	Veh. Inspected	SHC 5346J	
Policy No.	Z16VP05010945	Coverage (\$)	0.00	
Claim No.	16/16/16/VP05/019052	Excess (\$)	0.00	
Assign From		Assign Date	26/07/2016	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC279355	Colour	METALLIC WHITE / RED	
Odometer	221813	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	LING LONG	9 mm	
L/H Front Tyre	215/60 R16	LING LONG	9 mm	
R/H Rear Tyre	215/60 R16	ROVELO	9 mm	
L/H Rear Tyre	215/60 R16	ROVELO	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/07/2016	Inspection Date	26/07/2016	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5346J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BENT	968.79	968.79
1	BUMPER SPOILER FRT	SERVICEABLE	139.81	-
1	BUMPER ABSORBER FRT	CRACKED	303.60	303.60
1	BUMPER RETAINER FRT LH	SERVICEABLE	116.47	-
1	BUMPER SUPPORT FRT LH (HEADLAMP LOWER)	SERVICEABLE	18.37	-
1	BUMPER RETAINER FRT RH	DISTORTED	115.98	115.98
1	BUMPER SUPPORT FRT RH (HEADLAMP LOWER)	CRACKED	18.37	18.37
1	BUMPER UNDERTRAY FRT	SERVICEABLE	363.71	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	205.23	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	159.39	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	159.39	-
1	BUMPER BEAM FRT	BENT	703.14	703.14
1	RADIATOR GRILLE	CRACKED	1,313.68	1,313.68
1	RADIATOR GRILLE BADGE "RENAULT"	NECESSARY	173.36	173.36
1	RADIATOR GRILLE FRAME	CRACKED	1,041.35	1,041.35
1	FRAME FULL SUPPORT PANEL	CRACKED	473.77	473.77
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	69.07	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	136.32	-
1	HEADLAMP LH	SERVICEABLE	911.10	-
1	HEADLAMP RH	MTG CRACKED	911.10	911.10
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	134.59	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	134.59	-
1	BONNET	TO REPAIR SEE LABOUR	1,493.56	-
1	BONNET INSULATOR	SERVICEABLE	312.10	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	267.93	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	267.93	-

Report Ref No. CC3/LPC16013956/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET LOCK	TO REPAIR SEE LABOUR	234.99	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	602.95	-
1	FENDER PANEL FRT RH	BENT	602.95	602.95
1	FENDER WHEELARCH FET LH (LINNER)	SERVICEABLE	107.32	-
1	FENDER WHEELARCH FET RH (LINNER)	SERVICEABLE	214.49	-
1	WIPER RESERVOIR	SERVICEABLE	190.96	-
1	WIPER RESERVOIR NECK	SERVICEABLE	27.78	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	100.95	-
1	RADIATOR	SERVICEABLE	924.77	-
1	RADIATOR MTG LOWER	SERVICEABLE	42.96	-
1	RADIATOR FAN COWLING	SERVICEABLE	631.18	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	744.12	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,138.04	-
1	RADIATOR TANK	SERVICEABLE	249.71	-
1	ENGINE UNDERTRAY	SERVICEABLE	434.60	-
1	A/C CONDENSER	PUNCTURE	1,554.13	1,554.13
1	TRANSMISSION COOLER	SERVICEABLE	852.66	-
1	BUMPER COVER REAR	BENT	852.66	852.66
1	BUMPER BRACKET CTR REAR	DISTORTED	87.29	87.29
1	BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER)	SERVICEABLE	34.61	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	104.59	-
1	BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER)	DISTORTED	34.61	34.61
1	BUMPER RETAINER RH REAR	SERVICEABLE	104.59	-
1	BUMPER LOWER REAR	BENT	591.41	591.41
1	BUMPER BEAM REAR	BENT	598.08	598.08
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	173.81	-
1	BUMPER BEAM BRACKET RH REAR	BENT	173.81	173.81
1	BUMPER REFLECTOR LH	SERVICEABLE	33.55	-
1	BUMPER REFLECTOR RH	BROKEN	33.55	33.55
1	BOOT REAR	BENT	2,209.75	2,209.75
1	BOOT FINISHER (MOULDING)	SERVICEABLE	361.58	-

Report Ref No. CC3/LPC16013956/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK	TO REPAIR SEE LABOUR	155.90	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	57.23	-
1	BOOT WEATHERSTRIP	SERVICEABLE	248.50	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	379.50	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	379.50	-
1	BOOT BADGE "RENAULT"	NECESSARY	173.35	173.35
1	BOOT BADGE	NECESSARY	173.35	173.35
1	BOOT STRUT LH	SERVICEABLE	212.36	-
1	BOOT STRUT RH	SERVICEABLE	212.36	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	282.96	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	282.96	-
2	LICENCE PLATE LAMP	SERVICEABLE	84.00	-
2	BOOT RUBBER PLUG	SERVICEABLE	170.63	-
1	WINDSCREEN REAR	SERVICEABLE	1,125.60	-
1	TAILLAMP LH	CRACKED	425.04	425.04
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	759.00	-
1	TAILLAMP RH	MTG CRACKED	425.04	425.04
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	759.00	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	2,537.80	-
1	FENDER PANEL REAR RH	BUCKLED	2,537.80	1,493.56
1	FENDER WHEELARCH REAR LH (LINER)	SERVICEABLE	418.06	-
1	FENDER WHEELARCH REAR RH (LINER)	SERVICEABLE	418.06	-
1	AIR VENT RH	SERVICEABLE	74.83	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	516.50	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	516.50	-
1	FENDER WHEEL HOUSE PANEL REAR LH		2,337.72	-
1	FENDER WHEEL HOUSE PANEL REAR RH	TO REPAIR SEE LABOUR	2,337.72	-

Report Ref No. CC3/LPC16013956/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	1,684.52	-
1	SPARE WHEEL PANEL TRIM (LUGGAGE FLOOR PANEL)	SERVICEABLE	470.93	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,132.13	1,132.13
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	308.48	-
1	EXHAUST REAR	BENT	5,760.00	5,760.00
1	EXHAUST CAP REAR	DENTED	177.30	177.30
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,188.20	-
1	DOOR SEAL REAR LH	SERVICEABLE	68.02	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,188.20	-
1	DOOR SEAL REAR RH	SERVICEABLE	68.02	-
	LESS 10% DISCOUNT		-5,700.83	-2,252.11
			51,307.39	20,269.04
<u>SPECIAL NETT ITEMS</u>				
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	SERVICEABLE	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	SERVICEABLE	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	29.40	-
1	SET BUMPER RR CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BEAM BOLT (SN)	SERVICEABLE	22.22	-
1	SET PARKING AID (SN)	SHORTED	600.00	570.00
1	BUMPER BRACKET CLIP CTR REAR (SN)	NOT NECESSARY	15.00	-

Report Ref No. CC3/LPC16013956/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BRACKET SIDE CLIP LH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP LH REAR (SN)	NOT NECESSARY	10.40	-
1	BUMPER BRACKET SIDE CLIP RH REAR (SN)	NOT NECESSARY	12.00	-
1	BUMPER RETAINER CLIP RH REAR (SN)	NOT NECESSARY	10.40	-
1	CLIP HUB LH RR (SN)	SERVICEABLE	35.00	-
1	RIM LH RR (SN)	SERVICEABLE	385.00	-
1	TYRE LH RR (SN)	SERVICEABLE	330.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TRYE (SN)	SERVICEABLE	330.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	25.10	-
1	REAR BOOTS STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	REAR BOOTS STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	FENDER PANEL INNER TRIM CLIP REAR RH (SN)	NOT NECESSARY	22.00	-
1	FENDER PANEL INNER TRIM CLIP REAR LH (SN)	NOT NECESSARY	22.00	-
1	SET WHEELARCH CLIP LH RR (SN)	NOT NECESSARY	32.34	-
1	SET WHEELARCH CLIP RH RR (SN)	NOT NECESSARY	32.34	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	65.50	-
1	EXHAUST BRACKET REAR (SN)	SERVICEABLE	22.22	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	80.00	45.00
1	SET REAR LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	DOOR STICKER "6555-3333" LH (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "6555-3333" RH (SN)	NOT NECESSARY	80.00	-
			3,536.92	1,029.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.)		16,800.00	1,500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	INCLUSIVE OF THE REPAIR OF FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,FENDER PANEL FRT LH,BOOT LOCK,BOOT LOCK CATCH,BOOT HINGE LH,BOOT HINGE RH,TAILLAMP PANEL LH,TAILLAMP PANEL RH,FENDER PANEL REAR LH,FENDER WHEEL HOUSE PANEL REAR LH,FENDER WHEEL HOUSE PANEL REAR RH,SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),DOOR PANEL REAR LH AND DOOR PANEL REAR RH. }		-	-
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		18,000.00	1,640.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. }		380.00	210.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR. }		380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00

Report Ref No. CC3/LPC16013956/Khb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	REPEATED	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		380.00	120.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.		280.00	80.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			39,820.00	3,950.00
GRAND TOTAL			94,664.31	25,248.04
RECOMMENDED COST OF REPAIRS				25,248.04

Report Ref No. CC3/LPC16013956/Khb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.