



德興摩哆私人有限公司 DE XING MOTOR PTE. LTD.

Blk 3006 Ubi Road 1 #01-356 Singapore 408700.

Tel: 67468582 (4 Lines) Fax: 67439525

GST Reg. No.: M2-0061652-9

Co. Reg. No.: 198303312R



Accredited to the ISO 9000 Standard for Accreditation



Registration No. 2001-5-1999
2011 Reg-Gen No. 501294

☒ Third-Party

☐ Own Damage

☐ List Price

☐ Cost Price

Bike N FBK291U

Date of Ac 25-07-2016

Attn: claims Dept.

Make/ YAMAHA MX135

Chassis N MH250C006EK20206

Year

2014 Requester KOK LEONG

The bike will be here

on Monday to
survey.

Thanks.

S/ NO	Parts Description	Quantity	Unit Price	Total	Remarks
1	REAR FENDER	1	\$95.00	\$95.00	CRA
2	REAR NO PLATE	1	\$18.00	\$18.00	ht
3	REAR SIDE FARING	2	\$85.00	\$170.00	?
4	REAR TAIL LAMP ASSY	1	\$105.00	\$105.00	?
5	REAR SWING ARM	1	\$295.00	\$295.00	?
6	REAR WHEEL SHAFT	1	\$45.00	\$45.00	?
7	REAR SWING ARM	1	\$350.00	\$350.00	X
8	REAR SWING BOLT	2	\$55.00	\$110.00	?
9	LABOUR	1	\$380.00	\$380.00	2.80
10					
11	Rear frame body	1	\$350	\$350	300 R
12					
13					
14					
15					
16					
17					
18					
19					
20					

Rasul
Hp 90010068

3 days

4>

Resurvey after repair

email: rasul@lkkauto.com

02/08/16 @ 1000

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE BE ANY
ADDITIONAL PARTS REQUIRED OR DAMAGED DURING OUR COURSE OF REPAIRS, WE WILL
INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE
SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE.

APPROVING OFFICER'S SIGNATURE & COMPANY'S STAMP



Sub Total \$1,568.00
ADD 7%GST \$109.76
Grand Total \$1,677.76